SSIGNMENT minur D TP/WS/TPRES/OD RES/EVA/INV/MV at Workshop mas 190114753 Claims No. Sum Insured 1000 Make of Veh. (Policy Condition) N/S Remark. The veh had commenced its repair at the time of inspection. Ball or Market Value Consistent? : Yes or No IDAC Accident Rport Consistent? Yes or No GIA / PR Seen Res. Yes or No Est. Repairs: 3 Val.: Yes or No Lum Sum:

CA / REV / REP. / 24 HRS Vehicle IN / OUT Person Contacted

2019 June SMM4748C. Type (Ca) M.Cycle / Bus / Van / Lony / Taxi / Prime Mover / Truck / Trailer or 1984 Insured / Std / NI / NA T/Radio Insured / Std / NI / NA Sp Reading Eng/No: WA4222 FY6K2081704 Gen. Cond God / Fair / Poor / Burnt Steering Ingreat / Jammed / Leaked / Burnt or Ingger / Jammed / Leaked / Burnt or / STD A/Rim or Modi 235/55 R49. Tyre Size 235/558-19. BS / DUN / EXNOVA / GY / FS / LIZA MIT / OHTSU / PIR / SUMI / TOYO / YOKO or Front Rear R/Bal. R/Bal mm L/Bal mm DOL D.O.A Survey held at Des. of Damages Frt / Rear / Q/S / N/S / U/C / Rooftop or Front ols. The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
2/1/2020	Revert via meriman
3/1/2000	Rece approved \$ 33,559 from Victor by merimen
3/1/000	Race approved \$ 33,559 from Victor by merimen Informed Troy cla & \$1000 by email
* 4	
21220	Final fig \$ 30, 476.68 (Red 52, 861.32, 63/0 confirmed by email
8	3

SIMM	4748E -X			
mv	192K			
PV:	68.51c 73,868			
Nett:	123.51			
			- 11	
Cale/Time, File Pass Wil	: Prell. Report	Day	s Of Repair:	
	: Prell. Report		s Of Repair:	Survey Fee:
0	Taxania (Control of Control of Co			Survey Fee:
	Taxania (Control of Control of Co			
Date: Time. File Petium In 1. 8/9/20-Typist	: Final Report	Res	urvey No. of Trip:	Transportation
Date:Time. File Return In 18/9/20-Typist	Taxania (Control of Control of Co	Res	urvey No. of Trip:	Transportation:
Fegora Et James M	: Final Report	Res	urvey No. of Trip:	Transportation + +

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Friday, 3 January 2020 3:40 PM

To:

SUR; claims@premiumauto.com.sg

Cc:

(nora.khai@premiumauto.com.sg); (boojohnny@gmail.com)

Subject:

RE: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN

Dear All,

Kindly take note, Bonnet gas filled strut is Not necessary.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Friday, 3 January 2020 11:18 AM

To: SUR <sur@lkkauto.com>; claims@premiumauto.com.sg

Cc: (nora.khai@premiumauto.com.sg) <nora.khai@premiumauto.com.sg>; (boojohnny@gmail.com)

<boojohnny@gmail.com>

Subject: RE: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN

Dear TRoy,

As instructed by our client, please proceed to repair the insured vehicle SMM 4748C, (Excess \$1000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Please take note from AIG- Why is the Bonnet gas filled strut (Bonnet absorber) necessary to change?

AIG OIC- Azlan, Syazairdina [syazairdina.azlan@aig.com]

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Admin-D (LKKAuto) <a drawn-d@lkkauto.com>

Sent: Thursday, 2 January 2020 10:06 AM

To: SUR <sur@lkkauto.com>

Subject: FW: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN



Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Thursday, 2 January 2020 9:55 AM

To: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>

Cc: assignments@lkkauto.com

Subject: RE: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN

Dear Nivitha,

Herein attached the DL and COI for your next action.

Thanks

Best Regards,

TRoy Goh

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Thursday, 2 January 2020 9:28 AM

To: 'Claims'

Cc: assignments@lkkauto.com

Subject: RE: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN

Dear Sir/Mdm,

Kindly assist to provide us the driving license and Certificate of Insurance.

. 🛦

Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Tuesday, 31 December 2019 1:00 PM

To: 'Admin A' <admin-a@lkkauto.com'>; 'Summer Lee (LKK Auto)' <admin-d@lkkauto.com'>; 'SUR'

<sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN

Dear all,

Kindly register OD claims for this vehicle. Attached is GIA report and estimate repair with marking for your reference. Survey was just carrier up by Adrian this morning.

Kindly advise who is the case handler for the mentioned cases, and expedite the claims for approval. Please do take note that vehicle is in our compound.

Thanks

Best Regards, TRoy Goh Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Friday, 3 January 2020 11:18 AM

To:

SUR; claims@premiumauto.com.sg

Cc:

(nora.khai@premiumauto.com.sg); (boojohnny@gmail.com)

Subject:

RE: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN

Dear TRoy,

As instructed by our client, please proceed to repair the insured vehicle SMM 4748C, (Excess \$1000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Please take note from AIG- Why is the Bonnet gas filled strut (Bonnet absorber) necessary to change?

AIG OIC- Azlan, Syazairdina [syazairdina.azlan@aig.com]

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Thursday, 2 January 2020 10:06 AM

To: SUR <sur@lkkauto.com>

Subject: FW: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN



Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Thursday, 2 January 2020 9:55 AM

To: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>

Cc: assignments@lkkauto.com

Subject: RE: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN

Dear Nivitha,

Herein attached the DL and COI for your next action.

Thanks

Best Regards, TRoy Goh Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Thursday, 2 January 2020 9:28 AM

To: 'Claims'

Cc: assignments@lkkauto.com

Subject: RE: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN

Dear Sir/Mdm,

Kindly assist to provide us the driving license and Certificate of Insurance.



Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phonë: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Tuesday, 31 December 2019 1:00 PM

To: 'Admin A' <admin-a@lkkauto.com'>; 'Summer Lee (LKK Auto)' <admin-d@lkkauto.com'>; 'SUR'

<sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OWN DAMAGE CLAIMS FOR VEHICLE SMM 4748 C, DOA: 28/12/2019 VEH IN

Dear all,

Kindly register OD claims for this vehicle. Attached is GIA report and estimate repair with marking for your reference. Survey was just carrier up by Adrian this morning.

Kindly advise who is the case handler for the mentioned cases, and expedite the claims for approval. Please do take note that vehicle is in our compound.

Thanks

Best Regards, TRoy Goh Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Tt comes in blue.
The new Audi A7 Sportback. Do you really need a reason?

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

View Received Message

This mail is associated with:

*SMM4748C (2523080604SG)

OD Dec 28 2019 3:25PM [VIDHU GAUTAM] Premium Automobiles Pte Ltd

1		Mark as Unread	Drint Massage	Delete Message	Forward	
Reply	Reply All	Mark as Unread	Print Message	Delete Message	1 OI Ward	

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 03/01/2020 10:05 AM. From

LKK_HQ

Subject

Alert - Adj Mandate Approved (S\$33559.00) - SMM4748C - Claim Handler: Azlan, Syazairdina

Approved:33559.00:Re-inspection to be done for damage check and supplementary items / labour. Note: Why is the Bonnet gas filled strut (Bonnet absorber) necessary to change?

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com From: LKK Auto Consultants Pte Ltd AIG Asia Pacific Insurance Pte. Ltd. To: AIG Building 51 Ubi Ave 1 #01-25 Pava Ubi Industrial Park 78 Shenton Way #08-16 Singapore 408933 Singapore 079120 Date: 02 Jan 2020 Attn: Nadaraja, Deeban **Preliminary Advice** Accident Date : 28/12/2019 : SMM4748C Vehicle No Policy No. : 1900114753 Make : AUDI Q5 Excess : \$\$0.00 Assignment Date : 02/01/2020 : 11.00 Est. Duration of Repair Date of Inspection : 31/12/2019 Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699 Point of Impact / General Description of Damages The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident. :S\$ 83,338.00 Repairer's Estimate (Gross) :S\$ 33,559.00 Revised Amount Check Items (Estimated) :S\$ 9,042.00 :S\$ 42.601.00 Total :S\$ Lump Sum Repair **Total Loss Consideration** New for Old Value :S\$ Pre-Accident Value :S\$ 192,000.00 :S\$ 73,868.00 COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair 118,132.00 Remarks (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. Clase 1/1/2020. Other comments:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	NAMES TO TAXABLE VALUE OF THE PARTY OF THE P
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	771B
Vehicle No.:	SMM4748C
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	DAX055219
Chassis No.:	WAUZZZFY6K2081704
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$43,627.00
Original Registration Date:	28 Jun 2019
First Registration Date:	28 Jun 2019
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$53,078.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2029
PARF Rebate Amount: Intended COE Rebate Details	\$39,808.00
COE Expiry Date:	27 Jun 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,906.00
COE Rebate Amount:	\$34,060.00
Total Rebate Amount:	\$73,868.00

The information contained herein is correct as at 02 Jan 2020

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Gymer Particulare	
Owner ID Type:	Singapore NRIC
Owner ID:	771B
Vehicle Details	
Vehicle No.:	SMM4748C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Dec 2019
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	DAX055219
Chassis No.:	WAUZZZFY6K2081704
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$43,627.00
Original Registration Date:	28 Jun 2019
First Registration Date:	28 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$53,078.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2029
PARF Rebate Amount:	\$39,808.00
Intended COEReante Details	
COE Expiry Date:	27 Jun 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,906.00
COE Rebate Amount:	\$28,724.00
Total Rebate Amount:	\$68,532.00

The information contained herein is correct as at 31 Dec 2019

Rental Cars

Sell My Car

Directory

Products


Insurance


Articles

Resources









For old advertisements, view Expired ads

Make

▼ Model

Price ▼

Depreciation ▼

Reg Date -

Eng Cap ▼

Mileage ▼

TLESTED HESTORY Compare 🙆

Status 20 ▼ results/page

Veh Type ▼



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : VIDHU GAUTAM

Period of Insurance

: 28 Jun 2019 To 27 Jun 2021

Engine No.

: DAX 055219

: WAUZZZFY6K2081704 Chassis No.

Vehicle No. Policy No.

: SMM4748C 1900114753

Endorsement No.

Issued Date

: 06 Jul 2019

ABOUT THE COVER

: AUDI Q5 Sport 2.0 TFSI qu Make/Model

Engine Capacity/Tonnage: 1,984.00 CC **Driver Restriction** : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2019 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition

: 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hirs or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2 Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

VIDHU GAUTAM - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other. Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hottine at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from ITunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125250

PREMIUM LEASING -JY

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE Steffeny Loh

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service Towing service (accident or non-accident related) Advice on Motor Claims procedures
- Medical Referral Assistance

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Keep catm and move your car to a safe place.

 Do not admit or discuss fault or blame with the other party(ies).

 Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

If no one is injured in the accident:

- You are not required to make any police report.

- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).

 Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.

 Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next purplied day of the accident. working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:


- Report the accident to the police, providing full details of the circumstances of the accident.
- Record whice number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aloresala.		
	ACCIDENT STATEMENT	
Date Of Report	28/12/2019 19:09	
Date Of Accident	28/12/2019 15:25	
Exact Location Of Accident	ALEXANDRA ROAD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMM4748C	
Insured/Policyholder		
Name Of Registered Owner	VIDHU GAUTAM	

 NRIC No
 SXXXX771B

 Email Address
 VIDHURUJI07@GMAIL.COM

 Mobile Phone No
 (LOCAL) +65-96759976

 Alternative Phone No
 OFFICE-63480137

Vehicle Particulars

Manufacturer AUDI

Model Q5 SPORT 2.0 TFSI QU

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1900114753

Cover Note Number

Driver

 Name of Driver
 VIDHU GAUTAM

 NRIC No
 SXXXX771B

 Date Of Birth
 07/08/1965

 Occupation
 INDOOR

 Date Of Driving Pass
 06/05/2005

Driving Experience 14 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96759976

Fax Number

Contact Number OFFICE-63480137

EMail Address VIDHURUJI07@GMAIL.COM

41 A BEDOK RIA CRESCENT Address

#01-11

Postcode 489929

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR

DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME:

: NAISHA

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes. Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS EXITING THE CAR PARK OF QUEENSWAY SHOPPING CENTER ENTERING IN THE YELLOW BOX THE LORRY (YP7762H) CAME IN FROM BEHIND & HIT THE CAR FRONT RIGHT HAND SIDE AND DRAGGED PULL THE WAY. DAMAGING ENTIRE FRONT RIGHT HAND SIDE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP7762H

Vehicle Make/Model/Colour

FUSO MITSUBISHI

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

GOH YEOW TONG

NRIC/Passport Number

SXXXX189C

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Work MADNIG SENG, GEORGE NRIC/FIN NO.: 672987143X

GIARUL Samblustons UF

SKETCH PLAN		Alexandra mod	
		riexanous us	
	13,111111111111111111111111111111111111		
	1114		A+5MM4748
		Kiral 18	8-11P7762H
		The state of the s	
	1		ses our peaked (Hoped)
	Extrol		
		1 9	
	the Shaping		
	11 4 Adet De Lids		
DESCRIBE CIRCUMSTANCE	5 OF THE ACCIDENT		
As exiting	the compart of	& Queensway	Showing Center
tours enter	. / . /	un box the	Love (48770A)
Carry in	0 /	1:117 00	to be time of
Part of	on believe &	mr me can	O. The
hard side	and dragged	all the way	4 danagey
entin from	t right have	Side.	
0	0		
		For a street the con-	
THE RESERVE TO STATE OF THE PERSON NAMED IN			
CHARLES THE			
	A CONTRACTOR OF STREET		Charles and the RAL
DECLARATION			
We declare the bretoing part	iculars are true in every respect.		(0.0)
MANNIN			(2)
W 1. 16			2 100
Policyholder's Signature	Driver's Signature		Centre Personnel's Signature
Date & Time:	(If driver is not the policy) Date & Time:	nolder) Name: V	

GIARMC Sketch Flandorm, V3

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 24478

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/1532/2019/NS

Date : 31-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Vidhu Gautam

Address : 41A Bedok Ria Crescent

#01-11

Singapore 489929

Telephone : HP +65 96759976 Type of Claim : Own Damage Claims

Policy No. : 1900114753

Vehicle No : SMM 4748 C

Model Code : Audi Q5 SPORT 2.0 TFSI qu

Model / Year : 28/6/2019 Engine No : DAX 055219

Chassis No : WAUZZZFY6K2081704

Mileage : 82851 Date In : 30-Dec-19

Estimated By : Johnny Boo / Allan Wu

Accident Date : 28-Dec-19
Place of Accident : Alexandra Road

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N	N/A	
2	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid. Renew if necesarry.	S/N	\$ 480.00	
3	To remove and renew, aircon condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,400.00	/ /
4	To carry out first measurement on car o-liner.	S/N	\$ 800.00	X
	SUB TOTAL LABOUR CHARGES	:	\$ 2,680.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
5	To remove and reinstall engine assy with gearbox assy to facilitate cellette bench repairs.	S/N	\$ 2,800.00	X
6	To remove and reinstall front suspension assy with subframe to facilitate car-o-liner repairs. Inspect for damages and renew if necessary.	S/N	\$ 2,400.00	1 ×
7	To set up and place vehicle on car-o-liner.	S/N	\$ 2,400.00	X
8	To dismantle front bumper, bonnet and both front fenders. Align both front chassis frames to specification of origin. Inspect rhs front fender top support for damages. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. reinstall all parts removed.	S/N	\$ 10,400.00	3000 /
	SUB TOTAL LABOUR CHARGES	:	\$ 18,000.00	•

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
3/11	Nature or Jobs		charges	Recommendations
9	To dismantle both front door panel trims, remove and reinstall wing mirror assy.	S/N	\$ 800.00	4 .
10	To respray front bumper, lower spoiler, both front fenders, wheel arch trims, bonnet, hinges, both front doors and engine compartment.	/	\$ 2/50. 7,700:00 2975	3x550 = /650 AIC Trink1 = 300 Hinge x1 = 200
11	To renew rhs front rim and tyre. Carry out wheel alignment.	S/N	\$ 280.00	/ /
12	To carry out diagnostic checks.	S/N	\$ 392.00	//
	TOTAL LABOUR CHARGES	:	\$ 29,852.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/N	Parts Description		Damaged Parts & Prices S/Nett Remarks
	747 16	980	1991.10
1	FRONT BUMPER Pisto-ted	\$	2,364.00 1891.20
2	FRONT BUMPER FIXING PARTS HE WELL	\$	244.00 ? ×
3	FRONT BUMPER SECURING STRIP - LH / RH 2	\$	68:00 34 DE-48
4	FRONT BUMPER CLOSING ELEMENT - LH / RH 1 2	\$	202.00 101 80.80
5	FRONT BUMPER GRILLE - CENTRE +44 m	\$	129.00 ≯
6	FRONT SPOILER DISALL.	\$	685.00 - 548
7	FRONT BUMPER UNDERRUN BAR CM Cd	\$	431.00 - 3HH.80
8	FRONT BUMPER CLOSING ELEMENT Could	\$	156.00 - WH.HO
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH PH Missing 2	\$	1,038.00 519. 414.80
10	FRONT BUMPER END CAP-LH/RH RH Pand 2	\$	166.00-83.65.84
11	LOCKING CLIP Nec 4	\$	15.00 / 11.52
12	RADIATOR GRILLE Could	15	3,258.00 2606.40
13	RADIATOR GRILLE STRIKER PLATE 2 miled .	\$	222.00 ? 177.20
14	FRONT PARKING AID SENSOR - INNER / OUTER 4	\$	924.00 231 184.80
15	FRONT BUMPER WIRING SET ME M	\$	378.00 ⊀
16	FRONT BUMPER FOAM FILLER PIECE	\$	259.00 - 207.30
17	FRONT BUMPER CARRIER He m	\$	831.00 %
18	FRONT BUMPER BRACKET - LH / RH ZAH ML 2	\$	462.00
19	FRONT BUMPER GUIDE SECTION - LH / RH F 2H 2-2	\$	68.00 34. 27.12
20	FRONT BUMPER COVER Here Could	\$	116.00 - 95.40
	SUB TOTAL SPARE PARTS :	\$	12,016.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

<u>5/N</u>	Parts Description			Damaged Parts & Prices S/Nett Remarks
21	CAUTION SIGN STICKER ?	NEC	\$	13.00 - 9.76
22	AIRCON STICKER	NEC	\$	18.00 - 14
23	FRONT WHEEL COVER - LH / RH	2	\$	1,154.00 - 9>3.40
24	FRONT FENDER - LH / RH PIST	2	\$	2,602.00 1301 1040.80
25	FRONT FENDER BRACKET - LH / RH & RH 12 &	2	\$	32.00-16 12.32
26	FRONT FENDER BRACE - LH / RH	2	\$	412,00-206 164-40
- 27	COVER PANEL - LH / RH & could	2	\$	72.00 36. 56.80
- 28	CLOSURE PANEL - LH / RH 201 d 1	2	\$	56,00 28. 44-48
29	INNER SHIELD - LH / RH OUTER	2	\$	142.00 7 56.48
30	S - LINE INSCRIPTION XL	2	\$	225.00 / 180
31	FRONT WHEEL HOUSING LINER - LH / RH PH torn	2	\$	492.00 246. 196.40
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	2	\$	69.00 ? ×
33	WHEEL SPOILER - LH , when		\$	146.00 *
34	WHEEL SPOILER - RH and		\$	139.00 / 110.80
35	LED HEADLIGHT - LH/RH PH could	2	\$	14,454.00 72275781-60
36	LIGHT CONTROL SYSTEM CONTROL UNIT 7		\$	692.00 ×
37	MAIN LIGHT POWER MODULE		\$	693.00 +
* 38	LED WITH HEAT SINK - RH		\$	990.00 + 791.60
39	HEADLAMP ASSEMBLY SPACER PH Om &	2	\$	72.00 36. 29.84
40	HEADLIGHT HOSE - LH / RH KLI ~	2	\$	70.00 ×
	CUD TOTAL CDADE DADTO	1211	_	22 542 00
	SUB TOTAL SPARE PARTS	•	\$	22,543.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/N	Parts Description		Damaged Parts & Prices S/Nett Remarks
3/ N	Parts Description		
41	HEADLIGHT MOUNTING - LH / RH Cold 7	2	\$ 21400 107 17120
42	BONNET Pishola		\$ 3,707.00 - 2965.60
43	BONNET IMPACT PROTECTION - LH / RH / CENTRE ALL	3	\$ 75.00 - 59.44
44	BONNET LID HNGE - LH / RH Bect	2	\$ 292.00 - 233.60
45	BONNET ATTACHMENT PARTS		\$ 127.00 ? ×
46	BONNET GAS FILLED STRUT New	2	\$ 217.00 +
47	BONNET STRIKER - LH / RH Bent	2	\$ 218.00 ? 174.40
48	BONNET SOUND ABSORBER ***		\$ 289.00 *
49	BONNET LID LOCK - FRONT ALL M	2	\$ 391.00 ×
50	BONNET BOWDEN CABLE - CENTRE		\$ 53.00
51	BONNET RELEASE ELEMENT		\$ 53.00 - 41.68
52	BONNET RELEASE LEVER The No		\$ 13.00 +
53	BONNET LID LOCK CABLE		\$ 67.00 +
54	LOCK CARRIER Could		\$ 1,169.00 735.20
55	RADIATOR AIR GUIDE - LH/RH PH combo	2	\$ 100.00 SO 39.68
56	RADIATOR AIR GUIDE - UPPER		\$ 43.00 X
57	RADIATOR AIR GUIDE - CENTRE		\$ 37.00 ×
58	RADIATOR AIR GUIDE - LOWER		\$ 43.00 ×
59	RADIATOR LOUVRE		\$ 483.00 X
60	SERVOMOTOR HAR NEW		\$ 166.00 🗶
	SUB TOTAL SPARE PARTS	:	\$ 7,757.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/N	Parts Description		<u>Damaged Parts & Prices</u> S/Nett Remarks
61	CHARGE AIR COOLER		\$ 724.00 X
62	CHARGE AIR COOLER SEAL RING	2	\$ 82.00 ×
63	HOSE CLAMP		\$ 20.00 +
64	HOSE CLAMP		\$ 18.00 F
65	AIRCON CONDENSER		\$ 547.00 ×
66	RADIATOR		\$ 820.00 4
67	READY MIX COOLANT HEL	4	\$ 165.00 - 131.84
68	COOLANT HOSE - FRONT }		\$ 64.00 ₭
69	MOUNTING - LH / RH	2	\$ 96.00 🔛
70	AIR FILTER		TBC &
71	HORN-RH HIGH TONE Hol ML		\$ 178.00 }
72	SPRING SHACKLE - RH		\$ 38.00 X
73	FLAT CONNECTOR HOUSING *** M		\$ 17.00 *
. 74	LIFT CYLINDER - LH/RH RH could, LT could	2	\$ 256.00 128 204
75	HEADLIGHT HOSE NEW		\$ 113.00 +
76	FRONT NO PLATE	S/N	\$ 40.00 - 40
77	FRONT ALUMINIUM RIM - RH LAT		\$ 923.00 - 73 8.40
78	FRONT TYRE - RH NE W		\$ 1,307.00 ⊁
79	WHEEL BEARING HOUSING - RH THE NEW		\$ 1,035.00 ? ≺
80	WHEEL HUB THE NEW		\$ 451.00 ? ×
	SUB TOTAL SPARE PARTS	:	\$ 6,894.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4748 C

		Damaged Part	Damaged Parts & Prices		
S/N	Parts Description			S/Nett	Remarks
81	DOUBLE ANGLED BALL I		\$	232.00	7 7
82	FRONT WISHBONE LIN		\$	491.00	[
83	SUSPENSION GUIDE	we re	\$	861.00	?
84	FRONT GUIDE - RH UPP		\$	297.00	7
85	REAR GUIDE - RH UPPE	R Not mes	\$	297.00	X
86	SWIVEL JOINT	THE NEC	\$	175.00	7
87	TIE ROD END - RH	Ne mer	\$	180.00	?
88	STEERING GEAR	Ne ner		TBC	?
89	NOISE INSULATION	Not the	\$	743.00	?
90	SUNDRIES	Not nec.	\$	1,000.00	١٠
	TOTAL SPARE PART	s	: \$	53,486.00	
	TOTAL LABOUR CHA	ARGES	: \$	29,852.00	
	GRAND TOTAL		: \$	83,338.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : A

Surveyed Date :

Authorised Date

Excess Cost :

Liability Remarks LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

At Anthonsed, 11 pays.

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Tel:6768 9828 for appointment.

Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 24478

Telefax

Estimate

: Accident Repairs

Workshop Contact No

: Ubi Road 1 : 6366 2323

Fax No

: 6841 1183

Reference

: PA/OD/1532/2019/NS

Date

: 31-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr Vidhu Gautam

Address

: 41A Bedok Ria Crescent

#01-11

Singapore 489929

Telephone

HP+65 96759976

Type of Claim

Own Damage Claims

Policy No.

1900114753

Vehicle No

5MM 4748 C

Model Code

Audi Q5 SPORT 2.0 TFSI qu

Model / Year

28/6/2019

Engine No

DAX 055219

WAUZZZFY6K2081704

Chassis No

82851

Mileage Date In

: 30-Dec-19

Estimated By

Johnny Boo / Allan Wu

Accident Date

: 28-Dec-19

Place of Accident

Alexandra Road

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/n	Nature of Jobs			Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N		N/A	
2	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid. Renew if necesarry.	5/N	S	480.00	
3	To remove and renew, aircon condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$	1,400.00	
4	To carry out first measurement on car o-liner.	S/N	\$	800.00	X
	SUB TOTAL LABOUR CHARGES	:	\$	2,680.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/n	Nature of Jobs			Estimated Charges	Surveyor's Recommendations
5	To remove and reinstall engine assy with gearbox assy to facilitate cellette bench repairs.	S/N	S	2,800.00	×
6	To remove and reinstall front suspension assy with subframe to facilitate car-o-liner repairs. Inspect for damages and renew if necessary.	S/N	\$	2,400.00	1
7	To set up and place vehicle on car-o-liner.	5/N	\$	2,400.00	x
8	To dismantle front bumper, bonnet and both front fenders. Align both front chassis frames to specification of origin. Inspect rhs front fender top support for damages. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. reinstall all parts removed.	S/N	\$	10,409.00	3000
	SUB TOTAL LABOUR CHARGES	:	\$	18,000.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
9	To dismantle both front door panel trims, remove and reinstall wing mirror assy.	S/N	\$ 800.00	+.
10	To respray front bumper, lower spoiler, both front fenders, wheel arch trims, bonnet, hinges, both front doors and engine compartment.	'/	\$ 7,700.00	3x550 = 1650 ALC TriAx1 = 300 Higgs x1 = 200
11	To renew rhs front rim and tyre. Carry out wheel alignment.	5/N	\$ 280.00	
12	To carry out diagnostic checks.	S/N	\$ 392.00	1
	TOTAL LABOUR CHARGES	:	\$ 29,852.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/N	Parts Description			Damaged Parts & Prices S/Nett Remarks
1	FRONT BUMPER Distorted		\$	2,364 00
2	FRONT BUMPER FIXING PARTS ?		\$	244 00 ?
3	FRONT BUMPER SECURING STRIP - LH / RH	2	5	68:00 34
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$	202-00 10 1
5	FRONT BUMPER GRILLE - CENTRE +44 64		\$	129 00 4
6	FRONT SPOILER DISALL.		\$	685.00
(7)	FRONT BUMPER UNDERRUN BAR CL		\$	431.00 -
8	FRONT BUMPER CLOSING ELEMENT Could		S	156.00
(-9)	FRONT BUMPER AIR GUIDE GRILLE CHE RH RH RH MISSING	2	S	1,038.00 519
10	FRONT BUMPER END CAP-LH/RH RH Dend	2	\$	166.00-83
11	LOCKING CLIP Nec	4	\$	15.00
12	RADIATOR GRILLE Canld		5	3,258.00
(13)	RADIATOR GRILLE STRIKER PLATE ? CA		S	222.00
14	FRONT PARKING AID SENSOR - INNER / OUTER / piece de	4	S	924.00 231
15	FRONT BUMPER WIRING SET		\$	378.00 4
16	FRONT BUMPER FOAM FILLER PIECE Com Ld		\$	259.00
17	FRONT BUMPER CARRIER X-0 m		\$	831.00 to
18	FRONT BUMPER BRACKET - LH / RH 285 ALL W	2	\$	462.00
19	FRONT BUMPER GUIDE SECTION - LH / RH 72H 1-1	2	S	68.00 34.
20	FRONT BUMPER COVER Har Could		\$	116.00
	SUB TOTAL SPARE PARTS	:	\$	12,016.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

5/N	Parts Description			Damaged Parts & Prices S/Nett Remarks
21	CAUTION SIGN STICKER ?	NEC	\$	13 00
22	AIRCON STICKER	NEC		18 00 -
23	FRONT WHEEL COVER - LH / RH	2	S	1,154 00 -
4	FRONT FENDER - LH/RH 2HDist. How	2	5	2,502:00 13 01
5	EDGNIT SENDED BRACKET THE ADMIT	2	\$	32.00-16
6	FRONT FENDER BRACE - LH / RH RH P	2	5	412.00- 206
7	COVER PANEL (LH)/RH RH COMME	2	5	22-00-36.
3	CLOSURE PANEL (LHV RH 91) Redd	2	S	56,00-28
9	INNER SHIELD - LH (RH OUTER) The make	2	S	142.00 ×
	S - LINE INSCRIPTION Xu	2	S	225 00
1	FRONT WHEEL HOUSING LINER - LH / RH PA ton	2	S	493.00 216
2	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	2	S	69.00
3	WHEEL SPOILER - LH Jule on		\$	146.00 *
4	WHEEL SPOILER - RH and		\$	139.00
5	LED HEADLIGHT - LH/RH PH could	2	\$	14,454:00 7 2 27
ŝ	LIGHT CONTROL SYSTEM CONTROL UNIT 2		5	692.00 +
71	MAIN LIGHT POWER MODULE SLE ME		5	693.00 +
3	LED WITH HEAT SINK - RH		\$	990.00 +
9	HEADLAMP ASSEMBLY SPACER PH 0 d	2	s	7200 36.
)	HEADLIGHT HOSE - LH / RH KLI ~	2	\$	70.00 4
	SUB TOTAL SPARE PARTS		\$	22,543.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

S/N	Parts Description			Damaged Parts & Prices S/Nett Remarks
41	HEADLIGHT MOUNTING (LH) RH RH CULL	2	\$	214.00 107
42	BONNET DISCOLO		\$	3,707.00
43	BONNET IMPACT PROTECTION - LH / RH / CENTRE MA	3	S	75 00
44	BONNET LID HNGE - LH / RH Best.	2	S	292.00
45	BONNET ATTACHMENT PARTS		\$	127 00 ?
46	BONNET GAS FILLED STRUT MIN	2	Ś	217.00
(47)	BONNET STRIKER - HIRH ? 64	2	S	218 00 ?
48	BONNET SOUND ABSORBER ** ~		5	289.00 4
49	BONNET LID LOCK - FRONT ALL "	2	\$	391 00 ×
50	BONNET BOWDEN CABLE - CENTRE		\$	53.00
51	BONNET RELEASE ELEMENT		S	53.00
52	BONNET RELEASE LEVER The Man		\$	13.00 +
53	BONNET LID LOCK CABLE		S	67.00 +
54	LOCK CARRIER Concld		S	1,169.00
55	RADIATOR AIR GUIDE - LH / RH JH cmld	2	S	100-00-50
56	RADIATOR AIR GUIDE - UPPER		Ś	43.00 X
57	RADIATOR AIR GUIDE - CENTRE		\$	37.00 X
58	RADIATOR AIR GUIDE - LOWER 6		\$	43.00 %
59	RADIATOR LOUVRE		Ś	483.00 X
60	SERVOMOTOR Not New		5	166.00 %
	SUB TOTAL SPARE PARTS	:	\$	7,757.00

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

5/N	Parts Description			Damaged Parts & Prices S/Nett Remarks
61	CHARGE AIR COOLER		5	724 00 k
62	CHARGE AIR COOLER SEAL RING	2	\$	82 DO X
63	HOSE CLAMP		\$	20 00 8
64	HOSE CLAMP		\$	18 00 F
65	AIRCON CONDENSER		\$	547.00 1
66	RADIATOR		S	820 00 4
67	READY MIX COOLANT	4	Ś	165 00
68	COOLANT HOSE - FRONT }		\$	64.00 K
69	MOUNTING - LH / RH	2	\$	96.00 F
70	AIR FILTER			THC &
71	HORN-RHHIGHTONE Wol Ma		S	178.00 }
72	SPRING SHACKLE - RH		\$	38.00 X
73	FLAT CONNECTOR HOUSING ALL M		S	17.00 *
(74)	LIFT CYLINDER (LH) RH ZH COML	2	S	256 0 128
75	HEADLIGHT HOSE NUM		\$	113,004
76 AU	FRONT NO PLATE	S/N	\$	40,00
77	FRONT ALUMINIUM RIM - RH LAT		\$	923.00
78	FRONT TYRE - RH		\$	1,307.00 ×
79	WHEEL BEARING HOUSING - RH		\$	1,035.00
80	WHEEL HUB		\$	451.00
	SUB TOTAL SPARE PARTS		\$	6,894.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4748 C

					Damaged Parts	& Prices
S/N	Parts Description				S/Nett	Remarks
81	DOUBLE ANGLED BALL B	EARING 7		S	232.00	>
82	FRONT WISHBONE LINK	- RH ?		S	491 00	
83	SUSPENSION GUIDE	?		\$	861 00	
84	FRONT GUIDE - RH UPPE	R ?		\$	297 00 ?	
85	REAR GUIDE - RH UPPER	2		S	297.00 ?	
86	SWIVEL JOINT	7		\$	175.00	
87	TIE ROD END - RH	7		S	180.00 ?	
38	STEERING GEAR	7			THC ?	
39	NOISE INSULATION	7		\$	743.00 ?	
90	SUNDRIES	ĵ.		5	1,000.00 ?	
	TOTAL SPARE PARTS		:	\$	53,486.00	
	TOTAL LABOUR CHAP	RGES	3	\$	29,852.00	
	GRAND TOTAL	-1 CCT	121	\$	83,338.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

All Authorised, 11 Days.

Please Note

This estimate is based on visual inspection of the affected vehicle: Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs

Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/1532/2019/NS

Date : 31-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Telephone

MELINANDE

Type of Claim

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Vidhu Gautam

Address : 41A Bedok Ria Crescent

#01-11

Singapore 489929

: HP +65 96759976

: Own Damage Claims

Policy No. : 1900114753

Vehicle No : SMM 4748 C

Model Code : Audi Q5 SPORT 2.0 TFSI qu

Model / Year : 28/6/2019 Engine No : DAX 055219

Chassis No : WAUZZZFY6K2081704

Mileage : 82851

Date In : 30-Dec-19

Estimated By : Johnny Boo / Allan Wu

Accident Date : 28-Dec-19
Place of Accident : Alexandra Road

Hi Adrian

11 days exclude 2 Sundays - ok ib18 Feb 20

WIP: 24478

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMM 4748 C

S/n	Nature of Jobs	-	Estimated Charges	Surveyor's mmendations
1	To tow and recover vehicle from scene of accident.	S/N	N/A	
2	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid. Renew if necesarry.	S/N	\$ 480.00	\$ 480.00
3	To remove and renew, aircon condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,400.00	\$ 1,400.00
4	To carry out first measurement on car o-liner.	S/N	\$ 800.00	
	SUB TOTAL LABOUR CHARGES	:	\$ 2,680.00	\$ 1,880.00

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMM 4748 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's mmendations
				\$ 1,880.00
5	To remove and reinstall engine assy with gearbox assy to facilitate cellette bench repairs.	S/N	\$ 2,800.00	
o.	To remove and reinstall front suspension assy with			
6	subframe to facilitate car-o-liner repairs. Inspect for damages and renew if necessary.	S/N	\$ 2,400.00	
7	To set up and place vehicle on car-o-liner.	S/N	\$ 2,400.00	
8	To dismantle front bumper, bonnet and both front fenders. Align both front chassis frames to specification of origin. Inspect rhs front fender top support for damages. Renew front lock carrier and	S/N	\$ 10,400.00	\$ 3,000.00
-4	align to position. Renew damaged panels. Re- organise front crash management components. reinstall all parts removed.			
	SUB TOTAL LABOUR CHARGES	:	\$ 18,000.00	\$ 4,880.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMM 4748 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's ommendations
			· ·	\$ 4,880.00
9	To dismantle both front door panel trims, remove and reinstall wing mirror assy.	S/N	\$ 800.00	
THE STATE OF	To respray front bumper, lower spoiler, both front			
10	fenders, wheel arch trims, bonnet, hinges, both front doors and engine compartment.		\$ 7,700.00	\$ 2,975.00
11	To renew rhs front rim and tyre. Carry out wheel	S/N	\$ 280.00	\$ 280.00
	alignment.			
12	To carry out diagnostic checks.	S/N	\$ 392.00	\$ 392.00
	TOTAL LABOUR CHARGES	:	\$ 29,852.00	\$ 8,527.00

 Bonnet, LHS/RHS fender, front bumper - 550x4 =2200.00

 Arch trim
 300.00

 Hinges
 200.00

 Front lower spoiler
 275.00

 Total
 \$2,975.00

Telefax

S/N	Parts Description		Damaged Parts S/Nett	Prices Remarks
Ont	Turto Bookingson			
1	FRONT BUMPER		\$ 2,364.00	\$ 1,891.20
2	FRONT BUMPER FIXING PARTS		\$ 244.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 68.00	\$ 26.48
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 202.00	\$ 80.80
5	FRONT BUMPER GRILLE - CENTRE		\$ 129.00	
6	FRONT SPOILER		\$ 685.00	\$ 548.00
7	FRONT BUMPER UNDERRUN BAR		\$ 431.00	\$ 344.80
8	FRONT BUMPER CLOSING ELEMENT		\$ 156.00	\$ 124.40
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,038.00	\$ 414.80
10	FRONT BUMPER END CAP - LH / RH	2	\$ 166.00	\$ 65.84
11	LOCKING CLIP	4	\$ 15.00	\$ 11.52
12	RADIATOR GRILLE		\$ 3,258.00	\$ 2,606.40
13	RADIATOR GRILLE STRIKER PLATE		\$ 222.00	\$ 177.20
14	FRONT PARKING AID SENSOR - INNER / OUTER	4	\$ 924.00	\$ 184.80
15	FRONT BUMPER WIRING SET		\$ 378.00	
16	FRONT BUMPER FOAM FILLER PIECE		\$ 259.00	\$ 207.20
17	FRONT BUMPER CARRIER		\$ 831.00	
18	FRONT BUMPER BRACKET - LH / RH	2	\$ 462.00	
19	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 68.00	\$ 27.12
20	FRONT BUMPER COVER		\$ 116.00	\$ 92.40
	SUB TOTAL SPARE PARTS	:	\$ 12,016.00	\$ 6,802.96

Telefax

			Damaged I S/Nett	Parts	8 & Prices Remarks
S/N	Parts Description	c/f	S/Nett	\$	6,802.96
21	CAUTION SIGN STICKER	NEC	\$ 13.00	\$	9.76
22	AIRCON STICKER	NEC	\$ 18.00	\$	14.00
23	FRONT WHEEL COVER - LH / RH	2	\$ 1,154.00	\$	922.40
24	FRONT FENDER - LH / RH	2	\$ 2,602.00	\$	1,040.80
25	FRONT FENDER BRACKET - LH / RH	2	\$ 32.00	\$	12.32
26	FRONT FENDER BRACE - LH / RH	2	\$ 412.00	\$	164.40
27	COVER PANEL - LH / RH	2	\$ 72.00	\$	56.80
28	CLOSURE PANEL - LH / RH	2	\$ 56.00	\$	44.48
29	INNER SHIELD - LH / RH OUTER	2	\$ 142.00	\$	56.48
30	S - LINE INSCRIPTION	2	\$ 225.00	\$	180.00
31	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 492.00	\$	196.40
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	2	\$ 69.00		
33	WHEEL SPOILER - LH		\$ 146.00		
34	WHEEL SPOILER - RH		\$ 139.00	\$	110.80
35	LED HEADLIGHT - LH / RH	2	\$ 14,454.00	\$	5,781.60
36	LIGHT CONTROL SYSTEM CONTROL UNIT		\$ 692.00		
37	MAIN LIGHT POWER MODULE		\$ 693.00		
38	LED WITH HEAT SINK - RH		\$ 990.00	\$	791.60
39	HEADLAMP ASSEMBLY SPACER	2	\$ 72.00	\$	29.84
40	HEADLIGHT HOSE - LH / RH	2	\$ 70.00		
	SUB TOTAL SPARE PARTS	:	\$ 22,543.00	\$	16,214.64

Telefax

				Damaged Par	ts &	Prices
S/N	Parts Description			S/Nett		Remarks
		c/f			\$	16,214.64
41	HEADLIGHT MOUNTING - LH / RH	2	2 9	214.00	\$	171.20
42	BONNET		5	3,707.00	\$	2,965.60
43	BONNET IMPACT PROTECTION - LH / RH / CENTRE		3 \$	75.00	\$	59.44
44	BONNET LID HNGE - LH / RH	2	2 \$	292.00	\$	233.60
45	BONNET ATTACHMENT PARTS		\$	127.00		
46	BONNET GAS FILLED STRUT		2 \$	217.00		
47	BONNET STRIKER - LH / RH		2 \$	218.00	\$	174.40
48	BONNET SOUND ABSORBER		\$	289.00		
49	BONNET LID LOCK - FRONT		2 \$	391.00		
50	BONNET BOWDEN CABLE - CENTRE		\$	53.00		
51	BONNET RELEASE ELEMENT		5	53.00	\$	41.68
52	BONNET RELEASE LEVER			13.00		
53	BONNET LID LOCK CABLE			67.00		
54	LOCK CARRIER		:	1,169.00	\$	935.20
55	RADIATOR AIR GUIDE - LH / RH		2 ,	100.00	\$	39.68
56	RADIATOR AIR GUIDE - UPPER			43.00		
57	RADIATOR AIR GUIDE - CENTRE		;	37.00		
58	RADIATOR AIR GUIDE - LOWER			43.00		
59	RADIATOR LOUVRE			483.00		
60	SERVOMOTOR			166.00		
	SUB TOTAL SPARE PARTS			\$ 7,757.00	\$	20,835.44

Telefax

			Damaged Par	ts &	
S/N	Parts Description	c/f	 S/Nett	s	Remarks 20,835.44
61	CHARGE AIR COOLER	СЛ	\$ 724.00	•	20,000.
62	CHARGE AIR COOLER SEAL RING	2	\$ 82.00		
63	HOSE CLAMP		\$ 20.00		
64	HOSE CLAMP		\$ 18.00		
65	AIRCON CONDENSER		\$ 547.00		
66	RADIATOR		\$ 820.00		
67	READY MIX COOLANT	4	\$ 165.00	\$	131.84
68	COOLANT HOSE - FRONT		\$ 64.00		
69	MOUNTING - LH / RH	2	\$ 96.00		
70	AIR FILTER		TBC		
71	HORN - RH HIGH TONE		\$ 178.00		
72	SPRING SHACKLE - RH		\$ 38.00		
73	FLAT CONNECTOR HOUSING		\$ 17.00		
74	LIFT CYLINDER - LH / RH	2	\$ 256.00	\$	204.00
75	HEADLIGHT HOSE		\$ 113.00		
76	FRONT NO PLATE	S/N	\$ 40.00	\$	40.00
77	FRONT ALUMINIUM RIM - RH		\$ 923.00	\$	738.40
78	FRONT TYRE - RH		\$ 1,307.00		
79	WHEEL BEARING HOUSING - RH		\$ 1,035.00		
80	WHEEL HUB		\$ 451.00		
	SUB TOTAL SPARE PARTS	:	\$ 6,894.00	\$	21,949.68

Telefax

Material List for Accident Vehicle Regn No. SMM 4748 C

			Damaged Pa	arts 8	ts & Prices		
S/N	Parts Description		S/Nett		Remarks		
		c/f			21949.68		
81	DOUBLE ANGLED BALL BEARING		\$ 232.00				
82	FRONT WISHBONE LINK - RH		\$ 491.00				
83	SUSPENSION GUIDE		\$ 861.00				
84	FRONT GUIDE - RH UPPER		\$ 297.00				
85	REAR GUIDE - RH UPPER		\$ 297.00				
86	SWIVEL JOINT		\$ 175.00				
87	TIE ROD END - RH		\$ 180.00				
88	STEERING GEAR		TBC				
89	NOISE INSULATION		\$ 743.00				
90	SUNDRIES		\$ 1,000.00				
					diana.		
	TOTAL SPARE PARTS		\$ 53,486.00	\$	21,949.68		
	TOTAL LABOUR CHARGES	:	\$ 29,852.00	\$	8,527.00		
	GRAND TOTAL	:	\$ 83,338.00	\$	30,476.68		

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Friday, 21 February 2020 4:22 PM

To:

Carrine Leong; SUR

Cc:

'Boo seng yak'; 'Chang Chee Sing'; jiayee.yap@premiumauto.com.sg;

(nora.khai@premiumauto.com.sg)

Subject:

RE: FINAL REVISION - SMM4748C - OD AIG - SURVEYED 31 DEC 19

Dear Carrine,

Confirm repair cost of \$30,476.68 before excess \$1000 and GST @ 11 days of repairs

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>

Sent: Friday, 21 February 2020 2:11 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR

<sur@lkkauto.com>

Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>;

jiayee.yap@premiumauto.com.sg

Subject: RE: FINAL REVISION - SMM4748C - OD AIG - SURVEYED 31 DEC 19

Hi Adrian / Veron,

Amended revised estimate is attached.

Please confirm repair cost of \$30,476.68 @ 11 days of repairs exclude 2 Sundays.

Your early closure is much appreciated.

Thanks & Best Regard Carrine Leong Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

x	

Fmail Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Tuesday, 18 February, 2020 4:29 PM

To: Adrian Ling <a drianling@lkkauto.com>; Veron Chen <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <a drianling@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>;

jiayee.yap@premiumauto.com.sg

Subject: FINAL REVISION - SMM4748C - OD AIG - SURVEYED 31 DEC 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$30,706.68 @ 11 days of repairs exclude 2 Sundays.

Your early closure is much appreciated.

Best regards - jb