

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24434

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1533/2019/NS
Date : 31-Dec-19

Vehicle NOT IN Workshop. Kindly Arrange For Survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lim Boon Kiang
Address : Blk 561 Choa Chu Kang North 6
#05-88
Singapore 680561
Telephone : HP +65 90615789
Type of Claim : Own Damage Claims
Policy No. : 1800025210-01
Vehicle No : **SLX 268 B**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Mar-18
Engine No : CHZ 675187
Chassis No : WAUZZZ8V2J1048979
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Dec-19
Place of Accident : Car Park Next To Blk 561 Choa Chu Kang North 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 268 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	X
2	To remove and transfer rhs rear door's multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 280.00	/
3	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 300.00	/
4	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00	X
5	To install rear windscreen glass solar film.	S/N \$ 400.00	X
SUB TOTAL LABOUR CHARGES		: \$ 1,860.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 268 B

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00	X
7	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	X
8	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender. To renew rhs rear door. To repair rhs front door and rear bumper. Re-organise crash management components. Reinstall all parts removed. <i>sill panel.</i>	\$ 7,000.00 1500 / 250	
9	To respray rear bumper, rhs front door, rhs rear door, door handles, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 6,500.00 2400	
10	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 18,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 268 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR - RH <i>h/</i>	\$	2,279.00
2	REAR DOOR OUTER SEAL - RH <i>ne/</i>	NEC \$	146.00
3	BONDING AGENT <i>ne/</i>	NEC \$	45.00
4	CLEANING SOLUTION <i>ne/</i>	NEC \$	65.00
5	REAR DOOR CATCH <i>X</i>	\$	85.00
6	REAR EXTERIOR DOOR HANDLE - RH <i>repair</i>	\$	331.00
7	REAR HOUSING - RH <i>X</i>	\$	47.00
8	FRONT EXTERIOR DOOR HANDLE - RH <i>repair</i>	\$	331.00
9	FRONT DOOR CAP <i>X</i>	\$	36.00
10	FRONT DOOR SLIDE VALVE - RH <i>X</i>	\$	12.00
11	FRONT DOOR MOUNTING BAR <i>X</i>	\$	149.00
12	SIDE PANEL - RH <i>bt repair</i>	\$	2,110.00
13	REAR WINDSCREEN <i>X</i>	\$	742.00
14	PRIMER <i>X</i>	\$	19.00
15	SIDE WINDOW - RH <i>X</i>	\$	520.00
16	WHEEL HOUSING LINER <i>X</i>	\$	223.00
17	WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i>	\$	81.00
18	ACRYLIC SEALANT <i>X</i>	S/N \$	180.00
19	CAVITY WAX <i>X</i>	S/N \$	140.00
20	STONE CHIP <i>ne/</i>	S/N \$	180.00
SUB TOTAL SPARE PARTS		: \$	<u><u>7,721.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 268 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	METAL FILLER POWDER X	S/N \$ 280.00	X
22	1/4 GLASS SEALANT X	S/N \$ 100.00	X
23	REAR WINDSCREEN SEALANT X	S/N \$ 200.00	X
24	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 8,701.00	
TOTAL LABOUR CHARGES		: \$ 18,352.00	
GRAND TOTAL		: <u>\$ 27,053.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Rasul - Hp 90010068

Surveyed Date

: 31/12/19 @ 1140

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

6 days

EXCESS: TBA

Revert

Resurvey before print

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9823 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary demo(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant