

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9141B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

31 DEC 2013

AAD1912-188*Not Authorized
Returning B & paint***SHD 9141B**

JTDKB3FU003079215

TOYOTA

PRIUS

29.12.19

TOKIO MARINE

17-01-19

	PART
1	FRONT BUMPER
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING
1	REINFORCEMENT, FRONT BUMPER
1	REINFORCEMENT, FRONT BUMPER, NO.2
1	COVER, FRONT BUMPER HOLE, RH
1	ABSORBER, FRONT BUMPER, LOWER
1	ABSORBER, FRONT BUMPER ENERGY
1	FRONT BUMPER SIDE RETAINER RH
1	COVER SUB-ASSY, ENGINE, NO.1
1	COVER SUB-ASSY, ENGINE UNDER, NO.2
1	EXTENSION, FRONT BUMPER, RH
1	EXTENSION, FRONT BUMPER, LH
1	FRONT LED LAMP (LOWER) RH
1	FRONT HEADLAMP RH
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1
1	MOTOR, HEADLAMP LEVELING, RH
1	FRONT FENDER RH
1	LINER, FRONT FENDER, RH
1	EMBLEM, SIDE PANEL
1	PAD, FRONT WHEEL OPENING EXTENSION, RH
1	PROTECTOR, FRONT FENDER SIDE PANEL, RH
1	GRILLE SUB-ASSY, RADIATOR
1	GRILLE, RADIATOR, LOWER NO.1
1	EMBLEM ASSY, RADIATOR GRILLE
1	FRONT BONNET
1	INSULATOR, HOOD
1	HINGE ASSY, HOOD, RH

	LIST
\$	Bu 516.00 ✓
\$	Lu 103.40 X
\$	Lu 716.60 X
\$	Lu 246.10 X
\$	Lu 29.30 X
\$	Lu 132.70 X
\$	Lu 79.60 X
\$	mi 80.10 ✓
\$	Lu 472.40 X
\$	Lu 241.90 X
\$	Lu 120.10 X
\$	Lu 120.10 X
\$	cm 951.40 ✓
\$	cm 2,637.60 ✓
\$	Lu 960.50 X
\$	Lu 487.50 X
\$	Lu 977.80 X
\$	Lu 206.70 X
\$	Lu 54.60 ✓
\$	Lu 59.60
\$	Lu 93.90
\$	Lu 346.00
\$	Lu 170.10
\$	Lu 90.80
\$	Lu 983.10
\$	Lu 410.90
\$	Lu 58.90

Trans-cab Auto Services Pte Ltd**AAD1912-188**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9141B

1	LOCK ASSY, HOOD	\$	135.00	}	X
1	COVER, RADIATOR SUPPORT OPENING	\$	235.30		
1	GUIDE, RADIATOR AIR, NO. 1 RH	\$	65.30		
1	SEAL, RADIATOR TO SUPPORT, NO. 2	\$	29.60		
1	GUIDE, RADIATOR AIR, NO 3	\$	112.70		
1	SUPPORT SUB-ASSY, RADIATOR , RH	\$	245.10		
1	SUPPORT SUB ASSY, RADIATOR, UPPER	\$	377.10		
1	SUPPORT SUB ASSY, RADIATOR, LOWER	\$	409.90		
1	SUPPORT, RADIATOR, UPPER RH	\$	78.90		
1	CONDENSER ASSY, COOLER	\$	1,783.20		
1	SHAFT ASSY, FRONT DRIVE, RH	\$	1,379.50		
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	760.10		
1	KNUCKLE, STEERING, RH	\$	663.40		
1	LINK ASSY, FRONT STABILIZER, RH	\$	237.10		
1	BAR, STABILIZER, FRONT	\$	367.30		
1	FRONT SHOCK ABSORBER	\$	438.30		
1	SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$	236.40		
1	GEAR ASSY, STEERING	\$	1,955.40		
1	MIRROR ASSY, OUTER REAR VIEW, RH	\$	1,436.60		
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80		
TOTAL		\$	22,888.70		
25%		\$	5,722.18		
		\$	17,166.53		

Special Nett

		Special Net		
1	FRONT WHEEL RIM	\$	1,879.40	X
1	FRONT WHEEL RIM COVER	\$	211.50	X
1	FRONT TYRE 195/65/15	\$	350.00	X
1	CLIP, FRONT FENDER LINER	\$	30.00	X
1	FRONT NUMBER PLATE WITH MOULDING	\$	200.00	X
1	BUMPER CLIP FRT	\$	66.00	✓
1	FRONT BUMPER RETAINER CLIP	\$	30.00	X
1	CLIP (FOR RADIATOR SUPPORT OPENING COVER)	\$	30.00	X
TOTAL		\$	2,796.90	

TOTAL PARTS \$ 19,963.43

Trans-cab Auto Services Pte Ltd**AAD1912-188**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9141B**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	300
Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	440
To Rust-Proofing Of The Affected Areas.	\$	220.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	220.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	380.00	X

Trans-cab Auto Services Pte Ltd**AAD1912-188**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9141B

To vacuum, replace, refix and recharge air condenser \$ *nn* 380.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ *nn* 380.00 X
TOTAL \$ 18,520.00

Over All Total \$ 38,483.43

(PART-BY-PART) Repair Days*25 days**2 day,*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____