



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 . Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM: GBE 9146 D
MAKE & MODEL: TOYOTA DYNA
MILEAGE:
TYRE:
CHASSIS NUM:

NO	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT CABIN REAR PANEL X nn	1	\$ 942.90
2	FRONT GATE X	1	\$ 768.20
3	EGR VALVE X	1	\$ 414.80
4	COOLER PIPE X	1	\$ 297.00
5	AIR FILTER BOX X	1	\$ 301.50
6	TAILGATE dd ✓ X Not consistent.	1	\$ 2197.30
7	TAILGATE SIDE LOCK (L+R) RH-X	2	\$ 597.80
8	TAILGATE "L" BRACKET (L+R) RH X	2	\$ 490.40
9	TAILGATE "L" BRACKET STOPPER SET (L+R) RH X	4	\$ 280.00
10	TAILGATE HINGE SET dx	4	\$ 496.80
11	END PANEL dx NN	1	\$ 969.20
12	END PANEL LOWER LOCK (L+R) RH-X Not consistent	2	\$ 620.20
13	REAR CARPLATE LAMP X	1	\$ 180.90
14	REAR CARPLATE HOLDER X	1	\$ 164.00
15	REAR CARPLATE BRACKET X	2	\$ 190.60
16	FLOOR PANEL X	1	\$ 3640.70
17	REAR CHASSIS (L+R) X	2	Repair
18	TAIL LAMP (L+R) X	2	\$ 679.80
19	TAIL LAMP BRACKET (L+R) X nn	2	\$ 518.00
20	REVERSE SENSOR HOLDER (L+R) X nn	2	\$ 364.00
21	REAR BUZZER X nn	1	\$ 387.90
22	SIDE GATE (L+R) RH X NN LH-RP	2	\$ 5937.40
23	SIDE GATE HINGE SET (L+R) RH-X nn LH-BL 280	10	\$ 1656.00
24	SIDE GATE LOCK CATCH (L+R) RH-X nn LH-BL	2	\$ 217.40
25	SIDE GATE LOCK (L+R) LH-BL/RH X nn.	2	\$ 505.20
26	EXHAUST PIPE X	1	\$ 897.60
27	EXHAUST GASKET X	1	\$ 45.50
28	EXHAUST BRACKET X	1	\$ 201.00
29	SPARE TYRE BRACKET X	1	\$ 246.90
30	REAR TOWING HOOK X	1	\$ 278.40

P. \$1438.80

641.30

SUBTOTAL

\$

-

-25% ~~\$3285.60~~ 25% 480.98 ✓

PARTS TOTAL

\$

-

SPECIAL NETT

QTY

PRICE

1	FRONT CABIN REAR PANEL SEALANT X nn	1	\$ 120.00
2	TAILGATE STICKER (TOYOTA) X nn ✓	1	\$ 600.00
3	TAILGATE STICKER (SPEED) X nn ✓	1	\$ 80.00
4	TAILGATE STICKER (DANGER) X nn ✓	1	\$ 500.00
5	TAILGATE SCUFFING PLATE X nn	1	\$ 3,000.00


6	TAILGATE TOP WOODEN PLANK X nn	1	\$ 600.00
7	TAILGATE LOWER BOX X nn	1	\$ 4,800.00
8	FLOOR PANEL SCUFFING PLATE X nn	1	\$ 8,000.00
9	FLOOR PANEL TOP WOODEN PLANK X nn	1	\$ 8,000.00
10	SIDE GATE SCUFFING PLATE (L+R) X nn	2	\$ 6,000.00
11	SIDE GATE WOODEN TOP PLANK (L+R) LH- cm ✓ RH- nn 300 1400	2	\$ 4,000.00
12	SIDE GATE INNER TOP WOODEN PLANK (L+R) X nn	2	\$ 4,000.00
13	SIDE GATE INNER LOWER WOODEN PLANK (L+R) X nn	2	\$ 4,000.00
14	SIDE GATE WOODEN HANDLE (L+R) cm ✓ LH-900 4- x to check price 7/2	\$ 12,000.00	\$ 6000
15	SIDE GATE HANDLE MOUNTING SET (L+R) RH- x nn LH- 66 ✓ to check price 240 8/16	\$ 3,200.00	\$ 1,600
16	REVERSE SENSOR ✓	2	\$ 300.00
17	END PANEL SEALANT X } nn	1	\$ 120.00
18	FLOOR PANEL SEALANT X }	1	\$ 120.00
19	REAR CARPLATE X }	1	\$ 120.00
20	SPARE TYRE (BIG) X }	1	\$ 800.00
21	SPARE RIM (BIG) X }	1	\$ 1,200.00
22	SPARE TYRE (SMALL) X }	1	\$ 700.00
23	SPARE RIM (SMALL) X nn. 44- 1440 1440 ✓	1	\$ 1,000.00
SPECIAL NETT TOTAL			\$ 63,260.00
LABOUR			QTY PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN 800	1	\$ 4,500.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 800	1	\$ 3,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 30	1	\$ 300.00
4	TO RNR REAR TAILGATE MECHANISM nn 66X	1	\$ 600.00
5	TO RNR SCUFFING PLATE nn X	1	\$ 2,000.00
6	TO RNR TAILGATE AND SIDE GATE WOODEN PLANKS nn X	1	\$ 5,000.00
7	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS (FRONT CABIN) nn X	1	\$ 400.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS nn X	1	\$ 250.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION 30	1	\$ 150.00
10	TO RNR REAR CABIN X	1	\$ 3,000.00
11	TO DO WATER LEAK TEST. X	1	\$ 80.00
12	TO RNR FUEL TANK TO ASSIST WORK LOAD nn X	1	\$ 250.00
13	TO RNR COOLER PIPE X	1	\$ 250.00
14	TO RNR EGR VALVE X	1	\$ 250.00
L: 1660 ✓			
TOTAL			\$ 20,030.00
GRAND TOTAL COST			\$ 83,290.00

Taufik 97495749
-WP-

02/02/190 215pm

Lumpsum

Resolving after repair
sure/khant.com



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:	GBE 9146 D
MAKE & MODEL:	TOYOTA DYNA
MILEAGE:	
TYRE:	
CHASSIS NUM:	

ATTN: _____

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT CENTER GARNISH X } <i>nn</i>	1	\$ 342.10
2	FRONT SIDE GARNISH (L+R) X }	2	\$ 521.80
3	FRONT CENTER PANEL X }	1	\$ 1295.60
4	FRONT CENTER PANEL LOGO (TOYOTA) X <i>nn</i>	1	\$ 70.00
5	FRONT SIDE PANEL (L+R) LH- <i>dd</i> ✓, RH- <i>x</i> <i>nn</i> 282.20 \$489.20	2	\$ 978.40
6	FRONT GRILLE X <i>nn</i>	1	\$ 658.90
7	FRONT GRILLE PANEL X <i>nn</i>	1	\$ 896.70
8	HEAD LAMP (L+R) LH- <i>wt</i> ✓, RH- <i>x</i> <i>nn</i> 658 \$1051.30	2	\$ 2102.60
9	HEAD LAMP BRACKET (L+R) X <i>nn</i>	2	NIL
10	FRONT BUMPER <i>R</i> ✓	1	\$ 786.50
11	FRONT BUMPER RETAINER (L+R) X <i>nn</i>	2	\$ 372.40
12	FRONT BUMPER REINFORCEMENT BAR X <i>nn</i>	1	\$ 299.20
13	FRONT DOOR (LH) <i>bt</i> ✓ 1206.15	1	\$ 1520.90
14	FRONT DOOR HANDLE (LH) X <i>nn</i>	1	\$ 128.10
15	FRONT DOOR WINDOW MOULDING (LH) <i>xt</i> ✓	1	\$ 143.20
16	FRONT DOOR INNER LOCK (LH) X <i>nn</i>	1	\$ 280.70
17	FRONT DOOR INNER LOCK CATCH (LH) X <i>nn</i>	1	\$ 90.00
18	FRONT DOOR HINGE UPPER & LOWER (LH) X <i>nn</i>	2	\$ 156.80
19	FRONT DOOR CHECKER (LH) X <i>nn</i>	1	\$ 68.90
20	FRONT DOOR INNER BOARD (LH) X <i>nn</i>	1	\$ 584.60
21	FRONT DOOR LAMP (LH) X <i>nn</i>	1	\$ 68.70
22	FRONT DOOR POWER WINDOW REGULATOR (LH) X <i>nn</i>	1	\$ 198.40
23	FRONT DOOR POWER WINDOW MOTOR (LH) X <i>nn</i>	1	\$ 362.60
24	FRONT DOOR WEATHER STRIP (LH) <i>nn</i> ✓	1	\$ 158.70
25	FRONT DOOR INNER WEATHER STRIP (LH) X <i>NN</i>	1	\$ 176.20
26	FRONT STEP PANEL (LH) X	1	\$ NIL
27	FRONT STEP GARNISH (LH) X	1	\$ 191.20
28	FRONT ABSORBER (LH) X	1	\$ 481.40
29	FRONT LOWER ARM (LH) X	1	\$ 442.50
30	FRONT KNUCKLE (LH) X <i>nn</i>	1	\$ 470.20
31	FRONT KNUCKLE BEARING (LH) X	1	\$ 279.10
32	FRONT BEARING HUB (LH) X	1	\$ 312.00
33	FRONT CROSSMEMBER X	1	\$ 2961.20
	2448.25. 2. \$322.30		
	25% 1836.19✓ 2. \$322.30		
	SUBTOTAL		\$ -
	LESS 10%		\$ -
	PARTS TOTAL		\$ -
SPECIAL NETT		QTY	PRICE
1	FRONT CENTER PANEL SEALANT X <i>nn</i>	1	\$ 120.00
2	FRONT SIDE PANEL SEALANT <i>nn</i> ✓ 2. \$322.30 30	1	\$ 120.00

3	FRONT CENTER PANEL STICKER (FLAMMABLE) x n/n	1	\$ 300.00
4	FRONT DOOR STICKER (COMPANY REG) n/n ✓ 200 50	1	\$ 500.00
5	FRONT DOOR INNER BOARD CLIPS x n/n	1	\$ 100.00
6	FRONT STEP PANEL SEALANT x n/n	1	\$ 120.00
7	FRONT TYRE SET x n/n	2	\$ 1,600.00
8	FRONT RIM SET x n/n 5125: \$620 80 ✓	2	\$ 3,600.00
SPECIAL NETT TOTAL			\$ 6,460.00
LABOUR		QTY	PRICE
1	TO RNR DOOR MECHANISM 60	1	\$ 400.00
2	TO RNR UNDERCARRIAGE SYSTEM x { x	1	\$ 250.00
3	TO CHECK WHEEL ALIGNMENT n/y { x	1	\$ 250.00
4	TO RNR TYRE AND WHEEL BALANCING { x	1	\$ 250.00
TOTAL			\$ 1,150.00
GRAND TOTAL COST			\$ 7,610.00
60 ✓			

~~R: \$5808.10~~
~~S/N: \$9700~~
~~V: \$1720~~
~~Total: \$17,228.10~~
~~-20% = \$13,100~~

480.98
1440
1660
1836.19
80
60

5557.17
4/5 \$4450

5 days