

INS. CASE OWNER:

CC 61A16 2000 00 23 1 Ues3

LKK:
IDAC:

Surveyor:

MARCUS

DOI:

2/1/2020

Date / Time:

2/1/2020

Registered in Merimen:

2/1/2020

Pre-assign / CCU / FTE



Insured Vehicle No. : SCY1238H

Claim No. : _____

Name of Insured : Tan Kwang Buoy

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : SS D.O.A : 19/12/19

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Driver Tel No. : (V/L: YES NO)

Insured Liability : % Final ? Yes / No

FBN 5503K

INSRS:
WSP: Ban Hock Hin
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date / Time		STAGE	DATE / PIC
	FBN 5503K : CC6/CT/19011330/1416392; D.O.A: 4/10/19 SCY1238H: X	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: MORE 20-01-20 After call ltr to OI:	
21-01-20	Email WSP Liability CLARE.	Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act: (No Mess)	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by: LK
Repair Cost: P/P	SS 1,151.10	(2 days) Reduction: 1% %	Email ☒ Call ☐
FINAL SETTLEMENT	Date/Time: 02.03.20	Confirm with: RAYMOND	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : N/A	If NO or B 28, Ass. Lia :
Repair Cost: w/h	SS 1,231.68	OI TURN INTO MINOR ROAD HIT TP STATIONARY VEH.	
Loss of Rental (LOR):	SS -	(days)	
Loss of Use (LOU):	SS 40.00	(S 20 x 2 days)	
Loss of Income (LOI):	SS -	(S x days)	
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 1,273.68	Global Sum SS:	
FINAL PAYMENT	Date/Time: 02.03.20	Confirm with: RAYMOND	Email ☒ Call ☐
Payee 1:	SS 1,273.68	Name 1: BAN HOCK HIN (O. PIE LTD.)	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

ASS. REC. BY: MORIS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

 Remark: The veh had commenced its
 repair at the time of inspection,

N/S	O/S

Bal. or Market Value: _____

Consistent? : Yes or No

IDAC Accident Rpt: _____

Consistent? : Yes or No

G/A / FR Seen: _____

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

27A 3479
Pfp: +1.15.10 (CED) 19/190 14/1

Veh No: _____

Yr Regn: 10 18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha NMAX 155 c.c. 155Colour: white A/C: Insured / Std / NI / NASp. Reading: 15-253 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH35643/000008397Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or offBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Burn / STD A/Rim orTyre Size: F: 110-70-13R: 130-70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 19/12/19 D.O.I. 2/1/20

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rt, Rt O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

☐

: Prel. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time. File Return to?

Transportation: _____

2)

Add Fee: ☐ : Site Insp (\$ _____)) \$ + RS. \$ _____☐ : Interview (\$ _____)) Photos☐ : Tech. Invs (\$ _____)) Others☐ : Weekend (\$ _____))

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

S/N	Description	Action	Qty	Unit Price	Amount
13	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BACK TO OUTLET ONCE REPAIR DONE		2.00	56.00	112.00
SUB TOTAL					\$1,343.00
GST @ 7 %					\$94.01
GRAND TOTAL					\$1,437.01

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

P: 3949.00
- 10%
= 854.10
L: 397.40
T: 1,151.10

*35435 *

bizSAFE





BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 157000288K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

NO. : 35435

- Rev. 1

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 28/12/2019
CLAIM NO. : 11483
POLICY NO. : AVFMSB0000651901

FROM : HASRIANAH

VEHICLE NO. : FBN5503K
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE FRONT WHEEL P/N: 59126	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60
2	BEARING STEERING CONE LOWER P/N: 58120	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
3	BEARING STEERING CONE UPPER P/N: 36392	REPLACE	1.00	\$42.00 Disc %: 10.00	37.80
4	FORK FRONT ASSY P/N: 59590	REPLACE	1.00	\$763.00 Disc %: 10.00	686.70
5	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	Supply/Install	1.00	\$180.00	180.00
6	LAMP SIGNAL FRONT RH P/N: 59592	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
7	MUDGUARD FRONT (BLUE) P/N: 60913	REPLACE	1.00	\$47.00 Disc %: 10.00	42.30
8	RACE BALL 1 P/N: 55220	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
9	RACE BALL 2 P/N: 55216	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
10	RETAINER BALL BEARING P/N: 55215	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
11	SPRAY LACQUER FRONT MUDGUARD	Spray	1.00	\$45.00	45.00
12	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$37.00	37.00

*35435 *

bizSAFE₃



Address: No. 6, Delta lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2025 1-0003
ISO 9001 2015

Quotation Nos. : 35435 - Rev. 1

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
13	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BACK TO OUTLET ONCE REPAIR DONE		1.00	\$35.00	35.00
SUB TOTAL					\$1,151.10
GST @ 7 %					\$80.58
GRAND TOTAL					<u>\$1,231.68</u>

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*35435 *

bizSAFE₃

Address: No. 6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2003-1-0181
 ISO 9001:2015

Vehicle Details

Vehicle No.	Make / Model
FBN5503K	YAMAHA / NMAX155 ABS
Vehicle Type :	Vehicle Attachment 1 :
P01 - Passenger Scooter	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	MH3SG431000008397
Propellant :	Engine No. :
Petrol	G3H6E0010808
Motor No. :	Engine Capacity :
-	155 cc
Power Rating :	Maximum Power Output :
-	-
Maximum Laden Weight :	Unladen Weight :
295 kg	128 kg
Year Of Manufacture :	Original Registration Date :
2018	24 Oct 2018
Lifespan Expiry Date :	COE Category :
-	D - Motorcycle
Quota Premium :	COE Expiry Date :
\$3,951.00	23 Oct 2028
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
23 Apr 2020	-
Inspection Due Date :	Intended Transfer Date :
23 Oct 2021	25 Dec 2019
CO2 Emission :	CEV/VES Rebate Utilised Amount :
-	-
CO Emission :	HC Emission :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	288K
Vehicle Details	
Vehicle No.:	FBN5503K
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX155 ABS
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	G3H6E0010808
Chassis No.:	MH3SG431000008397
Maximum Power Output:	-
Open Market Value:	\$2,501.00
Original Registration Date:	24 Oct 2018
First Registration Date:	24 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$376.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,951.00
COE Rebate Amount:	\$3,479.00
Total Rebate Amount:	\$3,479.00

The information contained herein is correct as at 02 Jan 2020

OK



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000280K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
AIG ASIA PACIFIC INSURANCE PTE LTD

NO. : 35435

DATE : 28/12/2019
CLAIM NO. : 11483
POLICY NO. : AVFMSB0000651901

FROM : HASRIANAH

VEHICLE NO. : FBN5503K
MAKE/MODEL : YAM / NMAX155 ABS

not Affected
2/1/20
P/P

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE FRONT WHEEL P/N: 59126	REPLACE	1.00	\$14.00	14.00 ?
2	BEARING STEERING CONE LOWER P/N: 58120	REPLACE	1.00	\$12.00	12.00 ?
3	BEARING STEERING CONE UPPER P/N: 36392	REPLACE	1.00	\$42.00	42.00 ?
4	FORK FRONT ASSY P/N: 59590	REPLACE	1.00	\$763.00	763.00 ?
5	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	Supply/Install	4.00 1.00	\$49.00	180 196.00
6	LAMP SIGNAL FRONT RH P/N: 59592	REPLACE	1.00	\$35.00	500 35.00
7	MUDGUARD FRONT (BLUE) P/N: 60913	REPLACE	1.00	\$47.00	cmg 47.00
8	RACE BALL 1 P/N: 55220	REPLACE	1.00	\$12.00	rm 12.00
9	RACE BALL 2 P/N: 55216	REPLACE	1.00	\$12.00	rm 12.00
10	RETAINER BALL BEARING P/N: 55215	REPLACE	1.00	\$12.00	rm 12.00
11	SPRAY LACQUER FRONT MUDGUARD	Spray	1.00	\$49.00	45 49.00
12	STICKER (CISCO) MUDGUARD FRONT P/N: 58818	REPLACE	1.00	\$37.00	nei 37.00

*35435 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
13	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BACK TO OUTLET ONCE REPAIR DONE		2.00 <i>a</i>	\$56.00	35 112.00
SUB TOTAL					\$1,343.00
GST @ 7 %					\$94.01
GRAND TOTAL					\$1,437.01

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



*35435 *

bizSAFE₃



LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : Loh, Chee-HengYour Ref : 8037894883SG
Our Ref : CC6/AIG20000023/UES3
Date : 21 Feb 2020**"WITHOUT PREJUDICE"****ACCIDENT INVOLVING SCY1238H & FBN5503K ON 19/12/2019**

Refer to the above accident.

The accident occurred when insured turn into minor road and hit third party stationary vehicle. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SCY1238H) and third party claimant (vehicle no. FBN5503K).

Summary of offer made to workshop Ban Hock Hin Co. Pte Ltd is as follows :

	Claimed	Revised
Cost of Repairs (w/GST)	\$ 1,437.01	\$ 1,231.68
Loss of Use (2days)		\$ 40.00 2days x \$20
GIA Search Fee		\$ 2.00
Amount of claim at Liability 100%		<u>\$ 1,273.68</u>

Our surveyor recommended 2days repair.

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
Asher Sng Rong Yi
LKK Auto Consultants Pte Ltd

3/2/2020

Merimen e-Claims

Print Received Message

This mail is associated with :

***FBN5503K (8037894883SG)
[SCY1238H]**

TP

BAN HOCK HIN COMPANY PRIVATE LIMITED

Dec 19 2019 12:00AM

[TAN KWANG BUOY]

Ban Hock Hin Co. Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 21/02/2020 19:39 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1273.68) - FBN5503K - Claim Handler: Loh, Chee-Heng

Approved:1273.68.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2019 Edit Reg		02 Jan 2020 00:00 Edit Adj Rpt	\$S\$1,151.10 Edit Estimates	\$S\$1,151.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN KWANG BUOY, ID: S1837535D								
Main Claimant:	BAN HOCK HIN COMPANY PRIVATE LIMITED								
Vehicle Reg. No.:	FBN5503K	Date of Loss:	19/12/2019 00:00 - :59 [13 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8037894883SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SCY1238H	Policy No. (Claimant):							
		Excess:							
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 13/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (21/02/2020): Alert - Adj Mandate Approved (\$S\$1273.68) - FBN5503K - Claim Handler: Loh, Chee-H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBN5503K (8037894883SG)
[SCY1238H]

TP

BAN HOCK HIN COMPANY PRIVATE LIMITED

Dec 19 2019 12:00AM

[TAN KWANG BUOY]

Ban Hock Hin Co. Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Letters/Correspondences						1 per page 1 ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown				Edit	
Assessment Reports						1 per page 1 ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	21/02/20 16:08	Adjuster Immediate Advice				Load HTM	
Photos/Images						3 per page 3 ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	02/01/20 14:40	Odometer Reading			Load JPG	☒	
2	02/01/20 14:41	Chassis Number			Load JPG	☒	
3	02/01/20 14:41	General View			Load JPG	☒	
4	02/01/20 14:41	General View			Load JPG	☒	
5	02/01/20 14:41	General View			Load JPG	☒	
6	02/01/20 14:41	General View			Load JPG	☒	
7	02/01/20 14:41	General View			Load JPG	☒	
8	02/01/20 14:41	General View			Load JPG	☒	
9	02/01/20 14:41	General View			Load JPG	☒	
10	02/01/20 14:41	General View			Load JPG	☒	
11	02/01/20 14:41	General View			Load JPG	☒	
12	02/01/20 14:41	General View			Load JPG	☒	
13	02/01/20 14:41	General View			Load JPG	☒	
14	02/01/20 14:41	General View			Load JPG	☒	
15	02/01/20 14:41	General View			Load JPG	☒	
16	02/01/20 14:41	General View			Load JPG	☒	
17	02/01/20 14:41	General View			Load JPG	☒	
18	02/01/20 14:41	General View			Load JPG	☒	
19	02/01/20 14:41	General View			Load JPG	☒	
20	02/01/20 14:41	General View			Load JPG	☒	
21	02/01/20 14:41	General View			Load JPG	☒	
22	02/01/20 14:41	General View			Load JPG	☒	
23	02/01/20 14:41	General View			Load JPG	☒	
24	02/01/20 14:41	General View			Load JPG	☒	
25	02/01/20 14:41	General View			Load JPG	☒	
26	02/01/20 14:41	General View			Load JPG	☒	
27	02/01/20 14:41	General View			Load JPG	☒	
28	12/02/20 08:52	After Repair Photo			Load JPG	☒	
29	12/02/20 08:52	After Repair Photo			Load JPG	☒	
30	12/02/20 08:52	After Repair Photo			Load JPG	☒	
31	12/02/20 08:52	After Repair Photo			Load JPG	☒	
32	12/02/20 08:52	After Repair Photo			Load JPG	☒	
33	12/02/20 08:52	After Repair Photo			Load JPG	☒	
34	12/02/20 08:52	After Repair Photo			Load JPG	☒	
35	12/02/20 08:52	After Repair Photo			Load JPG	☒	
36	12/02/20 08:52	After Repair Photo			Load JPG	☒	

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	12/02/20 17:33	After Repair Photo		Load JPG	☒
38	12/02/20 17:33	After Repair Photo		Load JPG	☒
39	12/02/20 17:33	After Repair Photo		Load JPG	☒
40	12/02/20 17:33	After Repair Photo		Load JPG	☒
41	12/02/20 17:33	After Repair Photo		Load JPG	☒
42	12/02/20 17:33	After Repair Photo		Load JPG	☒
43	12/02/20 17:33	After Repair Photo		Load JPG	☒
44	12/02/20 17:33	After Repair Photo		Load JPG	☒
45	12/02/20 17:33	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/01/20 15:04	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT		Load PDF	
2	13/01/20 14:44	TP GIA REPORT		Load PDF	
3	13/01/20 14:44	TP ESTIMATE-MARKED		Load PDF	
4	22/01/20 10:31	LETTER TO OI		Load PDF	
5	21/02/20 16:03	TP ESTIMATED - MARKED (FINAL)		Load PDF	
6	04/03/20 08:45	WORKSHOP INVOICE		Load PDF	
7	04/03/20 08:45	Release Voucher		Load PDF	
8	04/03/20 08:45	GIA SEARCH		Load PDF	
9	04/03/20 08:45	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	06/01/20 16:56	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCY1238H (Insd veh)	Model:	YAMAHA NMAX155 155CC
	FBN5503K (TP veh)		
Date of Accident:	19/12/2019		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	1,437.01	
Final Repair Cost	:	\$	1,231.68	
Loss of Use	:	\$	40.00	2.00 days at \$20.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	1,273.68	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Ban Hock Hin Co. Pte Ltd	:	\$ 1,273.68
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

04 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000023/UES3Q2

Date: 04/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : FBN5503K Insured Vehicle No : SCY1238H

Date of Loss: 19/12/2019 Nature of Claim: TP Claim No: 8037894883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBN5503K
 Make & Model: YAMAHA NMAX155, 155cc Engine No: G3H6E0010808
 Reg. Date: 24/10/2018 (Man. Year: 2018) Chassis No: MH3SG431000008397
 Colour: White Odometer: 15253 km
 Engine Capacity: 155 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110-70-13 Rear Tyre Size: 130-70-13
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	986.00	891.10	94.90	9.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	357.00	260.00	97.00	27.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,343.00	1,151.10	191.90	14.29
+ GST 7.00/7.00% (S\$)	94.01	80.58	13.43	14.29
Nett Amount (S\$)	1,437.01	1,231.68	205.33	14.29
+ Loss of Use (2.0 x S\$20.00/day) (S\$)		40.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,273.68		

INSPECTION

Date of Assignment: 02/01/2020

Date Inspected: 02/01/2020 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
 No. 6 Defu Lane 4
 Singapore 539410

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE FRONT WHEEL	Bent	14.00 F	*14.00 FL
2	1		*BEARING STEERING CONE LOWER	Necessary	12.00 F	*12.00 FL
3	1		*BEARING STEERING CONE UPPER	Necessary	42.00 F	*42.00 FL
4	1		*FORK FRONT ASSY	Bent / Twisted	763.00 F	*763.00 FL
5	1		*LAMP SIGNAL FRONT RH	Scratched	35.00 F	*35.00 FL
6	1		*MUDGUARD FRONT (BLUE)	Cracked	47.00 F	*47.00 FL
7	1		*RACE BALL 1	Necessary	12.00 F	*12.00 FL
8	1		*RACE BALL 2	Necessary	12.00 F	*12.00 FL
9	1		*RETAINER BALL BEARING	Necessary	12.00 F	*12.00 FL
10	1		*STICKER (CISCO) MUDGUARD FRONT	Necessary	37.00 FS	*37.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	986.00	986.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	94.90
Total Parts (\$\$)	986.00	891.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT CHARGES	New	112.00	35.00
2	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	196.00	180.00
3	SPRAY LACQUER FRONT MUDGUARD	New	49.00	45.00
Gross Labour Cost (S\$)			357.00	260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >