



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
AIG ASIA PACIFIC INSURANCE PTE LTD

NO. : 35435

DATE : 28/12/2019
CLAIM NO. : 11483
POLICY NO. : AVFMSB0000651901
FROM : HASRIANAH

VEHICLE NO. : FBN5503K
MAKE/MODEL : YAM / NMAX155 ABS

not Affected
2/1/20
2/1/20
P/P

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE FRONT WHEEL P/N: 59126	REPLACE	1.00	\$14.00	14.00 ?
2	BEARING STEERING CONE LOWER P/N: 58120	REPLACE	1.00	\$12.00	12.00 ?
3	BEARING STEERING CONE UPPER P/N: 36392	REPLACE	1.00	\$42.00	42.00 ?
4	FORK FRONT ASSY P/N: 59590	REPLACE	1.00	\$763.00	763.00 ?
5	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	Supply/Install	4.00 1.00	\$49.00	180 196.00
6	LAMP SIGNAL FRONT RH P/N: 59592	REPLACE	1.00	\$35.00	35.00
7	MUDGUARD FRONT (BLUE) P/N: 60913	REPLACE	1.00	\$47.00	47.00
8	RACE BALL 1 P/N: 55220	REPLACE	1.00	\$12.00	12.00
9	RACE BALL 2 P/N: 55216	REPLACE	1.00	\$12.00	12.00
10	RETAINER BALL BEARING P/N: 55215	REPLACE	1.00	\$12.00	12.00
11	SPRAY LACQUER FRONT MUDGUARD	Spray	1.00	\$49.00	49.00
12	STICKER (CISCO) MUDGUARD FRONT P/N: 58618	REPLACE	1.00	\$37.00	37.00

*35435 *

bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
13	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BACK TO OUTLET ONCE REPAIR DONE		2.00	\$56.00	112.00
SUB TOTAL					\$1,343.00
GST @ 7 %					\$94.01
GRAND TOTAL					\$1,437.01

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*35435 *

bizSAFE₃



CERT NO : 2002-1-0383
ISO 9001 : 2015