

Date: 02.01.2020
Vehicle No: SJU221A
Model: MERCEDES BENZ GLC250
Chassis: WDC2539462F126695 - 2016
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SMJ209J
Date of Accident: 29.12.2019

*Not Authorised
Accident Repair
6 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>bu</i> \$1,031.50
2	REAR BUMPER LOWER DIFFUSER	1		<i>bu</i> \$681.85
3	REAR BUMPER LOWER DIFFUSER CHROME MOULDING	1		<i>cm</i> \$471.50
4	REAR BUMPER CLIPS	10	\$8.20	<i>bu</i> \$82.00
5	REAR BUMPER SIDE BRACKET LH	1		\$146.50
6	FRONT BONNET	1		<i>bu</i> \$2,042.50
7	FRONT GRILLE	1		<i>cm</i> \$305.30
8	FRONT GRILLE EMBLEM	1		<i>cm</i> \$132.06
9	FRONT GRILLE GARNISH ASSY	1		<i>cm</i> \$311.75
10	FRONT GRILLE CHROME MOULDING	4	\$100.00	\$400.00
11	FRONT GRILLE CLIPS	8	\$6.80	<i>bu</i> \$54.40
12	FRONT NUMBER PLATE HOLDER BRACKET	1		<i>cm</i> \$174.60
13	FRONT BUMPER	1		<i>bu</i> \$1,820.00
14	FRONT BUMPER FIXING COVER	1		<i>cm</i> \$85.00
15	FRONT BUMPER LOWER GRILLE	1		<i>bu</i> \$180.00
16	FRONT BUMPER CLIPS	12	\$8.20	<i>bu</i> \$98.40
17	FRONT HEADLAMP LH	1		\$2,925.50
18	FRONT HEADLAMP RH	1		\$2,925.50
19	REAR TAILGATE	1		REPAIR
20	FRONT SUPPORT PANEL	1		REPAIR
SUB TOTAL				\$13,868.36
LESS 10%				-\$1,386.84
PARTS TOTAL				\$12,481.52

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR	1		<i>bu</i> \$350.00
2	FRONT NUMBER PLATE	1		<i>bu</i> \$40.00
3	FRONT NUMBER PLATE HOLDER	1		\$40.00
S/N TOTAL				\$430.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Signature:

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 02.01.2020
Vehicle No: SJU221A
Model: MERCEDES BENZ GLC250
Chassis: WDC2539462F126695 - 2016
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SMJ209J
Date of Accident: 29.12.2019

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE,REFIX,REPLACE,REPAIR,READJUST FRONT & REAR
ACCIDENT AREAS & ETC.

80d
\$1,200.00

LABOUR CHARGES TO REMOVE,REPLAE,REFIX REAR BUMPER REVERSE SENSOR ASSY
& ETC.

\$100.00 *60d*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS
AT FRONT BONNET, FRONT BUMPER, REAR TAILGATE, REAR BUMPER & ETC.

\$1,000.00 *80d*

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 *4d*

LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMORY.

\$150.00 *?*

LABOUR TOTAL \$2,530.00

ONG TOTAL \$15,441.52