

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Dec 2019		12 May 2020 15:36 Edit Adj Rpt	S\$5,276.00 Edit Estimates	S\$5,276.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured:	-, Co. Reg. No.: -			
Main Claimant:	CHER TAU WEI, ID: S7840046C			
Vehicle Reg. No.:	SKQ8781G	Date of Loss:	27/12/2019 16:00 - :59 [59 Months and 27 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D206158C02	Policy/Cover Note No.:	DMPCSN30046619044	
Vehicle Reg. No. (Insured):	SJV5496K	Policy No. (Claimant):	VA1/GA294599	
		Excess:	S\$500.00	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]			
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/05/2020]			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS			View All	Search Tasks
			Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

*SKQ8781G (SNM19D206158C02)
[SJV5496K]
TP
CHER TAU WEI
Dec 27 2019 4:00PM
[-]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports				
		1 per page ▼		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	30/12/19 18:27	Accident Statement	 Load HTM	

Photos/Images				
		3 per page ▼		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
11	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
12	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
13	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
14	30/12/19 18:22	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
15	30/12/19 18:26	CONVERSATION MESSAGE [Linked Accident Report Documents]	 Load JPG	☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/05/20 12:30	General View	 Load JPG	☒
2	14/05/20 12:30	General View	 Load JPG	☒
3	14/05/20 12:30	General View	 Load JPG	☒
4	14/05/20 12:30	General View	 Load JPG	☒
5	14/05/20 12:30	General View	 Load JPG	☒
6	14/05/20 12:30	General View	 Load JPG	☒
7	14/05/20 12:30	General View	 Load JPG	☒
8	14/05/20 12:30	General View	 Load JPG	☒
9	14/05/20 12:30	General View	 Load JPG	☒
10	14/05/20 12:30	General View	 Load JPG	☒
11	14/05/20 12:30	General View	 Load JPG	☒

Documentation				
		1 per page ▼		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	30/12/19 18:21	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	30/12/19 18:21	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

View

View in Browser

Assessment Reports				1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	30/12/19 18:27	Accident Statement	i	Load HTM	
Photos/Images				3 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	30/12/19 18:22	Accident Photo	i	Load JPG	
2	30/12/19 18:22	Accident Photo	i	Load JPG	
3	30/12/19 18:22	Accident Photo	i	Load JPG	
4	30/12/19 18:22	Accident Photo	i	Load JPG	
5	30/12/19 18:22	Accident Photo	i	Load JPG	
6	30/12/19 18:22	Accident Photo	i	Load JPG	
7	30/12/19 18:22	Accident Photo	i	Load JPG	
8	30/12/19 18:22	Accident Photo	i	Load JPG	
9	30/12/19 18:22	Accident Photo	i	Load JPG	
10	30/12/19 18:22	Accident Photo	i	Load JPG	
11	30/12/19 18:22	Accident Photo	i	Load JPG	
12	30/12/19 18:22	Accident Photo	i	Load JPG	
13	30/12/19 18:22	Accident Photo	i	Load JPG	
14	30/12/19 18:22	Accident Photo	i	Load JPG	
15	30/12/19 18:26	CONVERSATION MESSAGE	i	Load JPG	
Documentation				1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	30/12/19 18:21	Sketch Plan	i	Load JPG	
2	30/12/19 18:21	Sketch Plan #2	i	Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20000049/ATD3S2**Date:** 19/05/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30046619044
Claimant Vehicle No :	SKQ8781G	Insured Vehicle No :	SJV5496K
Date of Loss:	27/12/2019	Nature of Claim:	TP
		Claim No:	SNM19D206158C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ8781G	Engine No:	CHV025494
Make & Model:	AUDI A7 SPORTBACK, 2.8 FSI (A)	Chassis No:	WAUZZZ4G6EN154129
Reg. Date:	31/12/2014 (Man. Year: 2014)	Odometer:	78276 km
Colour:	White		
Engine Capacity:	2773 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,328.00	2,724.00	2,604.00	48.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,252.00	2,552.00	700.00	21.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,580.00	5,276.00	3,304.00	38.51
+ GST 7.00/7.00% (S\$)	600.60	369.32	231.28	38.51
Nett Amount (S\$)	9,180.60	5,645.32	3,535.28	38.51

INSPECTION

Date of Assignment:	12/05/2020		
Date Inspected:	07/01/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/19/2020

Adjuster Report

THE VEHICLE HAS NOT SEND IN FOR REPAIR.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$300.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2020)
Parts:	143	AUDI A7 SPORTBACK 2.8 FSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ8781G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,724.00 FS	*2,724.00 FS
2	1		*REAR BUMPER SPOILER	Repair	480.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	249.00 FS	*- FS
4	1		*REAR BUMPER COVER	Not Necessary	209.00 FS	*- FS
5	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	34.00 FS	*- FS
6	2		*REAR PARKING AID SENSOR	Not Necessary	419.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Not Necessary	887.00 FS	*- FS
8	2		*REAR BUMPER SEAL - LH / RH	Not Necessary	26.00 FS	*- FS
9	1		*SUNDRIES	*Check	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					5,328.00	2,724.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR ASSY. CHECK FUNCTION.	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER ASSY. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMMOVED.	New	1,200.00	800.00
3	TO RESPRAY REAR BUMPER AND LOWER SPOILER.	New	1,500.00	1,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			3,252.00	2,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >