

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24601

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/1540/2019/NS  
Date : 2-Jan-20

5276

**Vehicle NOT IN workshop. Kindly arrange for survey.**  
**Your insured vehicle : SJV 5496 K**

## China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

## Motor Claims Dept

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Cher Tau Wei  
Address : 1 Bishan Street 15  
#37-05  
Singapore 573910  
Telephone : (HP) +65 93639650  
Type of Claim : Third Party Claims  
Policy No. : VA1/GA294599  
Vehicle No : **SKQ 8781 G**  
Model Code : Audi A7 SB 2.8 FSI QU  
Model / Year : Dec-14  
Engine No : CHV 025494  
Chassis No : WAUZZZSgEN154129  
Mileage : -  
Date In : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 27-Dec-20  
Place of Accident : After Zebra Crossing At PIE Bukit Batok Exit

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle, SKQ 8781 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor assy. Check function.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 <sup>800</sup> ✓	✓
3	To respray rear bumper and lower spoiler.	\$ 1,500.00 <sup>400</sup> <sup>1200</sup> ✓	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 3,252.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKQ 8781 G

		<u>Damage Parts &amp; Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER <i>Delon d</i>	\$ 2,724.00 ✓	✓
2	REAR BUMPER SPOILER <i>Rejo</i>	\$ 480.00 ✓	
3	REAR BUMPER FIXING PARTS <i>2</i>	\$ 249.00 ✓	
4	REAR BUMPER COVER <i>2</i>	\$ 209.00 ✓	
5	REAR BUMPER GUIDE SECTION - LH / RH INM 2	\$ 34.00 ✓	
6	REAR PARKING AID SENSOR <i>2</i>	\$ 419.00 ✓	
7	REAR BUMPER CARRIER <i>2</i>	\$ 887.00 ✓	
8	REAR BUMPER SEAL - LH / RH <i>me me</i> 2	\$ 26.00 ✓	
9	SUNDRIES <i>Not Nee</i>	\$ 300.00 ?	X
<b>TOTAL SPARE PARTS</b>		<b>: \$ 5,328.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 3,252.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 8,580.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Alden Lim  
**Surveyed Date** : 07/01/20  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : Not Authorised, 03 Days  
H.S.

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant