

L Soon Auto Services
No.10 Ang Mo Kio Industrial Park 2A
#03-18 Ang Mo Kio Auto Point
Singapore 568047
Tel: 6482 1513 Fax: 6556 2590

SGH1326D Honda Civic

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front bumper assy / Dis.	\$ 752.30	638
2	1	Front bumper left bracket x BT NN	\$ 44.40	X
3	1	Front bumper left retainer / Dis.	\$ 41.70	20.5
4	1	Front left headlamp / CRA	\$ 898.70	-
5	1	Front left headlamp bracket / BT.	\$ 28.80	-
6	1	Front left fender / Dis	\$ 898.20	594.8
7	1	Front left fender inner cowling / ec.	\$ 215.50	24.8
8	1	Front left fender lamp / Dis.	\$ 120.70	80
9	1	Front left door wing mirror complete assy x repair	\$ 578.20	X
10	1	Front left door panel / buc.	\$ 928.60	84.3
11	1	Front left door protector / cut.	\$ 162.80	137.55
12	1	Front left door lock mechanism X	\$ 213.30	X
13	1	Front left door glass outer moulding X LNN	\$ 176.10	X
14	1	Front left door outer handle X	\$ 178.40	X
15	1	Front left suspension assy	\$ 526.40	486.2
16	1	Front left lower arm	\$ 410.30	268.8
17	1	Front left wheel hub bearing	\$ 268.70	112.5
18	1	Front left knuckle arm	\$ 233.70	-
19	2	Front left door hinges	\$ 66.60	-
20	1	Front left door checker linkage	\$ 166.60	30
21	1	Front left headlamp module	\$ 698.80	-
22	1	Front left door regulator with motor	\$ 478.80	-
23	1	Front bumper left mudflap / mis	\$ 88.80	-
			\$ 8,176.40	5808.4
		Less 20%	\$ 1,635.28	
			\$ 6,541.12	4646.72
		<u>Special Nett Items</u>		
1	10	Front bumper clips	\$ 50.00	3e
2	6	Front left fender inner cowling clips	\$ 30.00	2e
3	4	Front left door protector clips	\$ 20.00	1e
4	1	Front left wheel rim	\$ 750.00	300
5	1	Front left tyre	\$ 350.00	180.
			\$ 1,200.00	
		Total parts	\$ 7,741.12	580

L Soon Auto Services
No.10 Ang Mo Kio Industrial Park 2A
#03-18 Ang Mo Kio Auto Point
Singapore 568047
Tel: 6482 1513 Fax: 6556 2590

SGH1326D Honda Civic

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy / <i>CRP</i>	\$ 698.10 <i>638</i>
2	1	Rear bumper left bracket <i>X NN</i>	\$ 31.80 <i>X</i>
3	1	Rear bumper left retainer <i>/ 22</i>	\$ 33.20 <i>265</i>
4	1	Rear left door panel <i>/ BT</i>	\$ 928.60 <i>753.4</i>
5	1	Rear left door protector <i>- CRP</i>	\$ 162.80 <i>137.55</i>
6	1	Rear left door outer handle <i>X</i>	\$ 178.40 <i>X</i>
7	1	Rear left door outer glass moulding <i>X NN</i>	\$ 176.10 <i>X</i>
8	1	Rear left door mechanism <i>X</i>	\$ 213.30 <i>X</i>
9	1	Rear left fender assy <i>X repair</i>	\$ 1,297.40 <i>X</i>
10	1	Rear left trailing arm <i>X NN</i>	\$ 212.20 <i>X</i>
11	1	Rear left knuckle arm <i>X NN</i>	\$ 372.70 <i>X</i>
12	1	Rear left wheel hub bearing <i>/ 9.5</i>	\$ 253.70 <i>/</i>
13	1	Rear left shock absorber <i>X NN</i>	\$ 298.10 <i>X</i>
14	1	Rear bumper left mudflap <i>- CRP</i>	\$ 88.80 <i>/</i>
15	1	Rear left door regulator with motor <i>X NN</i>	\$ 428.80 <i>X</i>
16	1	Rear left sill panel <i>X repair</i>	\$ 1,600.00 <i>X</i>
17	1	Rear windscreen glass moulding <i>X NN</i>	\$ 288.10 <i>X</i>
			\$ 7,262.10 <i>2165.2</i>
		Less 20%	\$ 1,452.42
			\$ 5,809.68 <i>1732.16</i>
		<u>Special Nett Items</u>	
1	10	Rear bumper clips <i>/</i>	\$ 50.00 <i>30</i>
2	4	Rear left door protector clips <i>/</i>	\$ 20.00 <i>10</i>
3	1	Rear left wheel rim <i>/</i>	\$ 750.00 <i>300</i>
4	1	Rear left tyre <i>/ CRP</i>	\$ 350.00 <i>180</i>
5	1	Rear left fender sealant <i>X</i>	\$ 80.00 <i>X</i>
6	1	Rear windscreen glass sealant <i>X NN</i>	\$ 80.00 <i>X</i>
			\$ 1,330.00
		Total parts	\$ 7,139.68 <i>520</i>

L Soon Auto Services
No.10 Ang Mo Kio Industrial Park 2A
#03-18 Ang Mo Kio Auto Point
Singapore 568047
Tel: 6482 1513 Fax: 6556 2590

SGH1326D Honda Civic

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten accident affected area and replace accident damaged parts.	\$ 1,200.00	1000
2	To putty and spray painting accident affected portion.	\$ 1,200.00	1100
3	To transfer front left door glass to new door.	\$ 80.00	40
4	To transfer rear left door glass to new door.	\$ 80.00	40
5	To check door central locking for function.	\$ 80.00	X NN
6	To apply anti rust proofing to accident affected area.	\$ 140.00	80
7	To remove and install front left door lock mechanism.	\$ 80.00	20
8	To remove and install rear left door lock mechanism.	\$ 80.00	20
9	To remove and install both front left and rear left door visor.	\$ 100.00	20
10	To remove and install front left undercarriage parts.	\$ 300.00	200
11	To balance front left wheel.	\$ 50.00	} 20
12	To balance rear left wheel.	\$ 50.00	
13	To conduct wheel alignment.	\$ 80.00	60
14	To remove and install rear left undercarriage parts.	\$ 300.00	80
15	Towing service.	\$ 100.00	80
16	To remove and install rear fuel tank to facilitate the repair.	\$ 180.00	X
17	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	X NN
		\$ 4,240.00	2760

Gua Qiang - 82880282
 upon repair.
 After repair photos.
 9 Days.
 02/01/2020.

Total parts : \$ 14,880.80
Total labour : \$ 4,240.00
Total repair cost : \$ 19,120.80

9019.2
 20% 5500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: