

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5055Z**AAD1912-171***Not Authorised**Clamp &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5055Z

VF1ABL15AUC276075

RENAULT

LATITUDE

24.12.19

III

02-12-13

PART

1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT LH
1	BUMPER SUPPORT FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER FOG LAMP GRILLE LH
1	BUMPER BEAM FRT
2	BUMPER BEAM PAD FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	HEADLAMP HARNESS
1	HORN
1	HORN BRACKET
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	CHASSIS PANEL FRT RH
1	CHASSIS PANEL SUPPORT FRT RH
1	FENDER PANEL INNER FRT RH L70Y

LIST

\$	<i>CM</i>	747.20	✓
\$	<i>mis</i>	344.70	✓
\$	<i>CM</i>	394.68	✓
\$	<i>Dis</i>	101.40	✓
\$	<i>SL</i>	10.70	X
\$	<i>CM</i> <i>CM</i>	101.40	✓
\$	<i>EM</i>	10.70	✓
\$	<i>CM</i>	292.50	✓
\$	<i>CM</i>	147.00	✓
\$	<i>mis</i>	207.21	✓
\$	<i>SL</i>	207.21	X
\$	<i>R</i>	663.70	✓
\$	<i>SL</i>	24.50	X
\$	<i>CRA</i>	743.60	✓
\$	<i>R</i>	128.30	✓
\$	<i>SL</i>	743.60	X
\$	<i>R</i>	127.70	X
\$	<i>SL</i>	928.29	X
\$	<i>SL</i>	449.90	X
\$	<i>R</i>	21.90	
\$	<i>R</i>	437.10	✓
\$	<i>CM</i>	191.40	✓
\$	<i>.</i>	106.40	?
\$	<i>SL</i>	11.80	X
\$	<i>SL</i>	66.30	X
\$	<i>R</i>	592.90	?
\$	<i>R</i>	431.70	X
\$	<i>R</i>	838.40	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5055Z**AAD1912-171**

1	FENDER PANEL SUPPORT FRT RH L70Y	\$	432.00	?
1	FENDER PANEL BRACKET FRT RH L70Y	\$	n 73.60	x
1	WHEEL HOUSING PANEL FRT RH	\$	n 2,698.60	x
1	FENDER PANEL FRT LH	\$	n 414.40	}
1	WHEELARCH FRT LH	\$	sn 112.30	
1	FENDER BRACKET LOWER LH	\$	sn 11.80	
1	FENDER INSULATOR LH	\$	sn 65.50	
1	FENDER BRACKET FRT LH	\$	n 38.90	
1	TOW COVER FRT	\$	sn 60.90	}
1	FRONT BRACE PANEL	\$	n 177.22	
1	RADIATOR GRILLE	\$	cm 969.90	✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	n 225.36	✓
1	RADIATOR GRILLE FRAME	\$	cm 686.00	✓
1	FRAME FULL SUPPORT PANEL	\$	cm 592.70	✓
1	FRAME FULL SUPPORT BRACKET	\$	n 41.60	x
1	BONNET	\$	n 1,312.70	x
1	BONNET INSULATOR	\$	cm sn 294.30	✓
1	BONNET STRUT RH	\$	sn 53.30	x
1	BONNET HINGE RH	\$	n 237.40	x
1	BONNET STRUT LH	\$	sn 53.30	x
1	BONNET HINGE LH	\$	n 236.50	x
1	BONNET LOCK	\$	dis 152.80	✓
1	BONNET CABLE	\$	sn 55.20	x
1	BONNET CABLE COVER	\$	sn 80.60	x
1	BONNET SEAL OUTER	\$	sn 83.20	x
1	BONNET SEAL INNER	\$	sn 70.10	x
2	BONNET BUFFER	\$	sn 26.80	x
1	LOWER ARM RH L70Y	\$	192.70	?
1	KNUCKLE ARM RH L70Y	\$	481.50	?
1	ABSORBER FRT RH L70Y	\$	203.50	?
1	DRIVESHAFT RH	\$	1,355.70	?
1	STABILIZER BAR FRT	\$	sn 427.90	x
2	STABILIZER LINK FRT	\$	sn 69.50	x
1	KNUCKLE HUB+BEARING LH/RH L70Y	\$	272.30	?
1	ABSORBER FRT RH L70Y	\$	203.50	?
1	ABSORBER MOUNTING KIT RH L70Y	\$	273.60	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5055Z**AAD1912-171**

1	ABSORBER DUST COVER	\$	76.30	X
1	BRAKE DISC FRT L70Y	\$	158.80	}
1	BRAKE CALIPER FRT RH L70Y	\$	536.10	
1	ABS SENSOR FRT RH L70Y	\$	152.50	
1	BRAKE HOSE FRT RH L70Y	\$	80.70	
1	BRAKE PAD FRT L70Y	\$	146.20	
1	ENGINE UNDERTRAY	\$	583.10	X
1	STEERING PINION RACK L70Y	\$	3,765.30	?
1	WIPER RESERVOIR MOTOR	\$	CM 82.60	✓
1	WIPER RESERVOIR	\$	na 179.60	✓
1	WIPER RESERVOIR NECK	\$	29.30	?
1	SUBFRAME OUTER FRT	\$	1,094.20	?
1	SUBFRAME BRACKET OUTER LH	\$	49.00	?
1	SUBFRAME BRACKET OUTER RH	\$	49.00	?
1	A/C CONDENSER	\$	TT 1,537.80	✓
1	A/C PIPE CONDENSER TO COMPRESSOR	\$	76.20	}
1	A/C PIPE CONDENSER TO EXPANSION VALVE	\$	380.20	
1	A/C PIPE COMPRESSOR	\$	222.70	
1	A/C PIPE	\$	486.50	
1	A/C CONDENSER GARNISH LH UPPER	\$	57.30	
1	A/C CONDENSER GARNISH RH UPPER	\$	56.70	
1	A/C CONDENSER GARNISH LH	\$	67.90	
1	A/C CONDENSER GARNISH RH	\$	67.70	
1	A/C COMPRESSOR	\$	na 2,142.30	
1	AIR COOLER	\$	76.90	
1	AIR INTERCOOLER HOSE (LONG)	\$	598.90	}
1	AIR INTERCOOLER HOSE (Short)	\$	1,014.13	
1	TRANSMISSION COOLER	\$	375.14	}
1	TRANSMISSION COOLER PAD	\$	76.30	
1	RADIATOR	\$	9.50	871.20 ?
2	RADIATOR STUD UPPER	\$	na 11.10	X
2	RADIATOR BUSH UPPER	\$	na 11.10	X
2	RADIATOR MTG LOWER	\$	na 30.10	X
1	RADIATOR FAN COWLING	\$	417.00	?
1	RADIATOR FAN MOTOR LH	\$	826.70	?
1	RADIATOR FAN MOTOR RH	\$	821.20	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5055Z**AAD1912-171**

1	RADIATOR TANK	\$	174.80	✓
1	RADIATOR HOSE UPPER	\$	97.50	X
1	RADIATOR HOSE LOWER	\$	254.10	X
1	RADIATOR TANK HOSE	\$	56.20	X
1	DIESEL FILTER	\$	839.78	?
1	ENGINE MOUNTING RH	\$	153.50	?
1	ENGINE MOUNTING UPPER	\$	592.02	?
1	A/C HEATER VALVE	\$	484.50	?
1	TURBO DUCT	\$	1,027.80	?
1	BASE BATTERY TRAY	\$	363.40	X
1	ALTERNATOR	\$	1,442.30	?
1	ENGINE HARNESS	\$	1,501.60	?
1	BATTERY COVER	\$	363.40	?
1	FUSE BOX	\$	987.39	?
1	AIR CLEANER LOWER	\$	271.26	?
1	AIR CLEANER HOSE	\$	175.85	?
1	AIR CLEANER BOX	\$	464.20	?
1	DOOR PANEL FRT RH	\$	2,844.66	X
1	DOOR HARNESS RH	\$	2,640.00	X
1	DOOR MIRROR ASSY RH	\$	1,483.40	X
1	SUBFRAME INNER FRT	\$	746.00	?
1	SUBFRAME BRACKET INNER LH	\$	101.00	?
1	SUBFRAME BRACKET INNER RH	\$	101.00	?
1	SUBFRAME SUPPORT INNER	\$	69.50	X

TOTAL	\$	57,438.89
10%	\$	5,743.89
	\$	51,695.01

Special Nett

1	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X
1	BUMPER GRILLE LOWER CLIP	\$	69.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X

Trans-cab Auto Services Pte Ltd

AAD1912-171

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5055Z

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	✓
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1	WHEELARCH CLIP FRT RH	\$	na	30.50	✓
1	FRONT RIGHT TYRE	\$		300.00	?
1	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT RIGHT TYRE RIM	\$	na	380.00	✓
1SET	Front licence plate with holder	\$	na	80.00	X
1SET	RADIATOR GRILLE SCREW	\$	na	16.00	} X
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	
1	WINDSCREEN SEALANT	\$	na	109.20	
1	FRONT WINDSCREEN MOULDING	\$	na	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30	
2	BONNET CABLE CLIP L70Y	\$	na	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	na	80.00	
1	FRONT DOOR STICKER 'Classic'	\$	na	80.00	
1	FRONT LEFT TYRE	\$	na	300.00	} X
1	FRONT LEFT TYRE RIM	\$	na	380.00	
TOTAL		\$		2,382.67	

TOTAL PARTS	\$	54,077.68
--------------------	-----------	------------------

LABOUR

To transfer of front windscreen glass to facilitate bodywork repair.

\$	na	170.00	X
----	----	--------	---

To transfer of bonnet fittings, attachment and perform water seepage test.

\$	na	170.00	X
----	----	--------	---

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$		9,000.00	Pool
----	--	----------	------

To rust-proofing of the affected areas.

\$		170.00	bol
----	--	--------	-----

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5055Z**AAD1912-171**

To transfer of front fender fittings, attachment and perform water seepage test.	\$	350.00	X
Putty and spray painting of the affected portion.	\$	9,000.00	11000
To Check Electrical Lighting Concerned.	\$	170.00	200
To check steering geometry and computer wheel alignment	\$	220.00	600
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	?
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
Towing Fees	\$	170.00	500
To check ABS and brake efficiency, final checking and testing.	\$	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	} 1000
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	
To lift-up engine with gear box and refit.	\$	440.00	X

Trans-cab Auto Services Pte Ltd

AAD1912-171

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5055Z

To transfer of front door fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	L	380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$		380.00	?
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	L	440.00	X
To remove and renew engine and gear box mounting.	\$	L	380.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	L	480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	L	380.00	X
To replace, refix and top up coolant for radiator	\$		170.00	501
To vacuum, replace, refix and recharge Air Intercooler	\$	nn	170.00	X
TOTAL	\$		25,430.00	

Over All Total \$ 79,507.68**LUMP SUM (REPAIR DAY)**~~30~~ DAYS
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: