



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2006828  
INV Date 05/10/2020  
Reference CC4/EQI20000063/R1ga3q2  
Code EQI



### PROFESSIONAL SERVICE FEE

Vehicle No. GBG 5789P  
Insured Veh. SGF 1893T  
Claim No. DM19HO03360-JG  
Policy No. DMPPHQ19-002472  
Accident Date 20/12/2019  
Inspection Date 30/12/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI20000063/R1ga3q2

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 05-10-2020



Code : EQI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SGF 1893T	<b>Veh. Inspected</b>	GBG 5789P
<b>Policy No.</b>	DMPPHQ19-002472	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	DM19HO03360-JG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JOEL	<b>Assign Date</b>	27/12/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN NV200 1.5 MT	<b>c.c</b>	1461
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	VSKYBAM20Z0146157	<b>Colour</b>	GREY
<b>Odometer</b>	51822	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	175/70 R14	GREENLANDER	6 mm
<b>L/H Front Tyre</b>	175/70 R14	GREENLANDER	6 mm
<b>R/H Rear Tyre</b>	175/70 R14	GREENLANDER	6 mm
<b>L/H Rear Tyre</b>	175/70 R14	GREENLANDER	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	20/12/2019	<b>Inspection Date</b>	30/12/2019
<b>Survey held at</b>	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>8 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 5789P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (N)	DEFORMED	583.00	583.00
2	REAR BUMPER SIDE BRACKET @\$70.00 (N)	NECESSARY	140.00	140.00
2	REAR BUMPER REFLECTOR LAMP @\$48.00 (N)	CRACKED	96.00	96.00
1	REAR BUMPER TOWING COVER (N)	SERVICEABLE	20.00	-
2	REAR BUMPER CLIPS @\$4.00 (N)	NECESSARY	8.00	8.00
1	REAR LH DOOR (N)	BENT	980.00	980.00
1	REAR LH DOOR (NV200) EMBLEM (N)	NECESSARY	70.00	70.00
1	REAR LH DOOR (LOGO) (N)	NECESSARY	70.00	70.00
2	REAR LH DOOR HINGE (N)	BENT (1 PCS ONLY)	240.00	120.00
1	REAR LH DOOR CHECKER (N)	SERVICEABLE	120.00	-
1	REAR LH DOOR LOCK (N)	JAMMED	380.00	380.00
1	REAR LH DOOR RUBBER (N)	NECESSARY	290.00	290.00
1	REAR RH DOOR (N)	BENT	975.00	975.00
2	REAR RH DOOR HINGE @\$120.00 (N)	BENT	240.00	240.00
1	REAR RH DOOR CHECKER (N)	SERVICEABLE	120.00	-
1	REAR LH DOOR NOZZLE (N)	SERVICEABLE	35.00	-
1	REAR LH DOOR THIRD BRAKE LAMP (N)	SERVICEABLE	230.00	-
1	REAR RH DOOR LOCK (N)	JAMMED	335.00	335.00
1	REAR RH DOOR RUBBER (N)	NECESSARY	290.00	290.00
1	REAR RH DOOR INNER TRIM (N)	SERVICEABLE	330.00	-
1	REAR LH DOOR INNER TRIM (N)	SERVICEABLE	350.00	-
1	REAR LH DOOR GARNISH (N)	CRACKED	235.00	235.00
1	REAR END PANEL OUTER (N)	BENT	799.00	799.00
1	REAR END PANEL INNER (N)	BENT	645.00	645.00
1	REAR END PANEL PLATE (N)	CRACKED	298.00	298.00
2	TAIL LAMP @\$323.00 (N)	SERVICEABLE	646.00	-
1	FRONT BUMPER (N)	CUT	595.00	595.00
1	FRONT BUMPER SPONGE (N)	SERVICEABLE	130.00	-
1	FRONT BUMPER REINFORCEMENT (N)	SERVICEABLE	483.00	-

Report Ref No. CC4/EQI20000063/R1ga3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-973.30	-714.90
			8,759.70	6,434.10
	<b><u>SPECIAL NETT ITEMS</u></b>			
2	FRONT & REAR NUMBER PLATE @\$50.00 (SN)	FRONT BENT	100.00	35.00
1	SET REAR PARKING SENSOR (SN)	NOT WORKING	200.00	200.00
2	REAR DOOR GLASS SEALANT @\$40.00 (SN)	NECESSARY	80.00	60.00
1	REAR DOOR 70KM/H STICKER (SN)	NECESSARY	15.00	10.00
1	REAR DOOR (6 PAX) STICKER (SN)	NECESSARY	15.00	10.00
			410.00	315.00
	<b><u>LABOUR</u></b>			
	TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST.		40.00	40.00
	TO REMOVE AND TRANSFER ITEMS TO REAR LH & RH NEW DOOR .		200.00	160.00
	TO REMOVE AND INSTALL REAR DOOR LH & RH GLASS.		200.00	120.00
	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES ,CARPET & ETC IN ORDER TO CUT OFF END PANEL OUTER ,INNER .		200.00	120.00
	TO CUT OFF END PANEL ,OUTER ,INNER ,AND STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS.		1,200.00	1,000.00
	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS .		60.00	40.00
	TO APPLY RUST PROOF ON AFFECTED AREAS.		100.00	80.00
	TO SPRAY PAINT ON REPLACED ,REPAIRED AREAS.		1,000.00	600.00
			3,000.00	2,160.00
<b>GRAND TOTAL</b>			<b>12,169.70</b>	<b>8,909.10</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>8,909.10</b>

Report Ref No. CC4/EQI20000063/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBG 5789P

### INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBG 5789P

### RE-INSPECTION





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

