

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8660S

DATE 26/12/2019 9:30

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>cra</i>			\$ 553.00	
	Rear Bumper Reinforcement <i>R xnn</i>			\$ 428.40	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>R xnn</i>		\$ 80.30	\$ 160.60	
	Rear Bumper Clip 10 pcs <i>nec</i>			\$ 22.00	
	Rear Bumper Bracket <i>R xnn</i>		\$ 35.60	\$ 71.20	
	Rear Bumper Sponge <i>R xnn</i>			\$ 103.50	
	Rear Bumper Under Cover <i>xnn</i>			\$ 228.00	



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition	
1. Date: <u>24/12/19</u> Time Received: <u>1743</u>	3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : Contact No. : <u>96605081</u> Vehicle No. : <u>SHA8660S</u> Make / Model / Colour : Email :	4. Type of Towing: <input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks:
7. Location: <u>Braddell Rd</u>	8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others:	10. Odometer Reading : Fuel Level : <input type="checkbox"/> F <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> E
11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input type="checkbox"/> GAO <input checked="" type="checkbox"/> TZ <input type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS Name of Driver : <u>GADAY</u> Vehicle No. : <u>YJ55663</u> Time Dispatch : <u>1743</u> Time of Arrival : <u>1800</u> Time Completed :
<p># : Cracked X : Dented / : Scratched O : Missing</p> <p>Signature of Customer</p>	

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

24/12/19
Date

1800
Time

[Signature]
Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S COPY