

Accident Photo



Accident Photo



偉利摩哆公司
WILLY MOTOR COMPANY

27-A Jurong Port Road #01-32 Singapore 619101
Tel: 6261 7873, 6268 0977 Fax: 6265 1726
Branch: 3 Pioneer Road North #01-17 Singapore 628457
Tel: 6264 1596, 6261 1238
Business Reg. No: 225146/00B GST Reg. No: M8-8003347-6

30 November 2019

JJ-SINGAPORE SALES & MARKETING PTE LTD
C/O 27A Jurong Port Road
#01-32 Singapore 619101

REPAIR BILL FOR VEHICLE NO. YL 8312 M

| | |
|--|-------------------|
| Total Repair cost (Part – By – Part) | \$8,716.27 |
| Add 7% GST | \$ 610.13 |
| Total: | <u>\$9,326.40</u> |

Your Ref : GBC 2799B
Our Ref : YL 8312M/WM/ms/hk
Date : 31 October 2019

Fax : 6538 3708
Tel : 3152 0981
Email : accident@kscgp.com

Sompo Insurance Singapore Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 24 OCTOBER 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of YL 8312M to notify you of a road traffic accident on 24 October 2019 at about 3.25pm at the junction of New Bridge Road and Eu Tong Sen Street, involving our client's vehicle registration number YL 8312M and vehicle registration number **GBC 2799B** which was insured by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

f HK

Enc.

Your Ref : CMTD1905050/RUC
Our Ref : YL 8312M/WM/ms/hk
Date : 31 October 2019

Fax : 6538 3708
Tel : 3152 0981
Email : accident@kscgp.com

Sompo Insurance Singapore Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 24 OCTOBER 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email dated 31 October 2019.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

| S/no. | Name of Surveyor | Company Name |
|-------|-----------------------|--------------------------------------|
| 1. | Foo Philip | Precision Appraisal Services |
| 2. | Ronald Ng | Precision Appraisal Services |
| 3. | Lee Kok Weng | Lee Automobile Appraisals Services |
| 4. | Dave Chang | Sincere Appraisal Services |
| 5. | Ng Kong Beng, Patrick | Carlink Consultancy |
| 6. | Andrew How | Prominent Appraiser Services Pte Ltd |
| 7. | Gan Song Sing, Roger | ROG Associates |
| 8. | Dennis Yap | Pal's Appraiser Pte Ltd |
| 9. | Michael Yap | Mc-Coy Appraiser Pte Ltd |
| 10. | Nicky Seah | Absolute Appraisal Services |

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Willy Motor Company
27A Jurong Port Road
#01-32
Singapore 619101
Contact Person/Tel : Ms Khoo/ Tel: : 9276 7180

Yours faithfully

Your Ref : CMTD1905050/RUC
Our Ref : YL 8312M/WM/ms/hk
Date : 31 October 2019

Acknowledgement

This is to confirm that I _____ [Full Name of Surveyor] of
_____ [Surveyor's Company] have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-19-177896
Date of Request: 29/10/2019

Your Ref No: YL8312M/WM/MS/HK

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 24/10/2019
Place of Accident: AT THE JUNCTION OF NEW BRIDGE
Client Vehicle No: YL8312M

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

| REQ. VEHICLE | ACCIDENT LOCATION | ACCIDENT DATE |
|--------------|--------------------------------------|------------------|
| GBC2799B | NEW BRIDGE ROAD INTO ENTRANCE OF SGH | 24/10/2019 15:30 |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

)
This is a computer generated document and requires no signature.

TAX INVOICE

Our Ref No: GR-19-178002
Date of Request: 30/10/2019

Your Ref No: YL8312M/WM/MS/HK

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Date of Accident: 24/10/2019
Vehicle No: YL8312M
Place of Accident: JUNCTION OF NEW BRIDGE RD & EU TONG SEN ST
Involving Vehicle No: GBC2799B

With reference to your application for the accident report, we have attached the following accident reports as requested:

| DOCUMENTS | ACCIDENT LOCATION | PER DOC (S\$) | QTY | AMOUNT (S\$) |
|----------------------------------|--|---------------|-----|--------------|
| GBC2799B | JUNCTION OF NEW BRIDGE RD & EU TONG SEN ST | 14.00 | 1 | 13.0 |
| GST Amount | | | | 0.9 |
| Total Amount Due (GST Inclusive) | | | | 14.0 |

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

PDS INTERNATIONAL PTE LTD
10 Pandan Crescent #05-03/04 (LL2) S128466
Tel: 6776 6200 Fax: 6776 6842
Email: pds@safety.com.sg
Website: www.safety.com.sg

Policyholder's Signature

Date & Time: 25/10/19

Driver's Signature

(If driver is not the policyholder)

Date & Time: 25/10/19

Reporting Centre Personnel's Signature

Name: Wang Chay Lan

NRIC/FIN No.: S15555557

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG NEW BRIDGE ROAD
 INTENDING TO MAKE A RIGHT TURN INTO ENTRANCE
 OF SGL AS THE TRAFFIC WAS CLEAR, I PROCEEDED
 TO MAKE THE TURN. SUDDENLY, I HEARD A 'BANG'
 AND DISCOVERED THAT A VEHICLE YL 831200 HAD
 COLLIDED INTO MY VEHICLE REAR LEFT SIDE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

PDS INTERNATIONAL PTE LTD

10 Pandan Crescent #05-03/04(LL2) S128466

Tel: 6776 6290 Fax: 6776 6882

Email: pds@safety.com.sg

Website: www.safety.com.sg

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

HU WEI SUI

25.10.2017



Reporting Centre Personnel's Signature

Name WONG CHAY LIA

PRC/EN No.

21111117

Enquire Vehicle & Owner Information (Vehicle No. GBC2799B As At 24 Oct 2019 / 15:25:00)

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: YL8312M/WM/MS/HK

Owner ID Type: Company
Owner ID: 199302758Z
Owner Name: PDS INTERNATIONAL PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 10
Registered Street Name: PANDAN CRESCENT
Registered Unit No.: #05 - 03/04
Registered Building Name: -
Registered Postal Code: 128466

Vehicle No.: GBC2799B
Make Description/Model: TOYOTA / HIACE MANUAL
Insurance Company Name: SOMPO INSURANCE SINGAPORE PTE. LTD.

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 6444 4886 Company Registration No. 53139926E

To:

**JJ-SINGAPORE SALES &
MARKETING PTE LTD
C/O 27A Jurong Port Road #01-32
Singapore 619101**

Invoice No.: 191112

DATE : 30 November 2019

| <u>DESCRIPTION</u> | AMOUNT |
|--|-----------------|
| Vehicle Registration No. : YL 8312 M Type of Claims : Third Party Claims Our Reference No. : PAS/WM/191112/TP Your Reference No. : - Inspection Report Fees : (including transportation charges & photographs) Reinspection Report Fees : - Transportation Charges : - Additional Photographs : - Others (Specify) : - | \$824.00 |
| DOLLARS EIGHT HUNDRED AND TWENTY-FOUR ONLY TOTAL: | \$824.00 |



PRECISION APPRAISAL SERVICES

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

**JJ-SINGAPORE SALES &
MARKETING PTE LTD
C/O 27A Jurong Port Road #01-32
Singapore 619101**

REFERENCE

Assigned By : As above
Accident Date : 24 October 2019
Assignment Date : 31 October 2019
Inspection Date : 31 October 2019
Our Reference No. : PAS/WM/191112/TP

PARTICULARS OF VEHICLE

Registration No. : YL 8312 M
Make/Model : ISUZU NQR70P
Yr of Manuf/Regn : 2004
Carrying Capacity : -
Chassis No. : JAAN1R70P47101153
Engine No. : 4HE1106494
Colour : White
Class : Goods (Lorry)

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

Inspection Report Date : 30 November 2019

Workshop Name :

Willy Motor Company

Inspection Address :

27A Jurong Port Road #01-32

Singapore 619101

Mileage : 506673 Km/h
Radio/Cassette : Fitted
CD Disc Player : Fitted
Air Conditioner : Fitted
Clock : Fitted
Seat Belt : Fitted
Wing Mirror : Fitted
Other Accessories : Fitted

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent : None
Eng Modifications

VEHICLE VALUE

Market Value : -
Wreck Value (Part) : -

TYRE SIZE & CONDITION

Front N/s Size : 7.50R16 90 %
Make : OHTSU
Rear N/s size : 7.50R16 90 % 90
Make : OHTSU
Spare Size : 7.50R16 80 %
Make : OHTSU

Front O/s Size : 7.50R16 90 %
Make : OHTSU
Rear O/s Size : 7.50R16 90 % 90
Make : OHTSU
Spare Size :
Make :
Jack & Tools : Intact/Missing

Type of Wheel Rims: Standard


VEHICLE REGISTRATION NO. : YL 8312 M

APPENDIX A

POINT OF IMPACT

Direction of impact/damage marked (→) (X)

The vehicle
sustained impact
on its Front N/s
Portion.
(see Diagram B)

**GENERAL DESCRIPTION OF DAMAGES**

Parts damaged were :

The front bumper and centre cab panel, front n/s door and pillar, front n/s corner panel and headlamp panel were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 31/10/2019 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s Willy Motor Company as per attached Appraisalment Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Part - By - Part Repair Basis of \$ 8,716.27 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

| | Repairer's | | Our | |
|---------------------|------------|--------|---------|--------|
| | Estimate | Amount | Revised | Amount |
| Repares Parts | 9657 | 20 | 6226 | 27 |
| Towing Charges | - | - | - | - |
| LAB Labour Charges | 1800 | 00 | 1400 | 00 |
| Others Misc Charges | 370 | 00 | 290 | 00 |
| Paintwork | 1200 | 00 | 800 | 00 |
| Total | \$ 13027 | 20 | \$ 8716 | 27 |

Under normal circumstances, the duration of repairs should not exceed Seven (07) days excluding Pre - repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame & Public Holidays.

Attached photographs taken during inspection Forty - Four (44) Photographs

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 04/11/2019, we examined the extent of damages.
3. On 08/11/2019, we examined the new replacement parts.
4. On 11/11/2019, we examined the repaired vehicle

Yours Faithfully




T F NG PHILIP FOO
ACII CAE, AMIMI

OUR REFERENCE : PAS/WM/191112/TP

INSPECTION REPORT DATE : 30-Nov-19

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO :

1

| S/No | Qty | Parts / Labour Descriptions | Remarks / Condition | Repairer's Estimate Amount \$ cts | Recommendation / Revised Amount \$ cts |
|------|------|---|---------------------|--------------------------------------|---|
| | | <u>PARTS SUPPLY - LIST ITEMS</u> | | | |
| 1 | 1pc | Front panel | Badly Dented | 1201.00 | 1201.00 983/ |
| 2 | 1pc | Front windscreen | Cracked | 1985.00 | 1985.00 1280/ |
| 3 | 1pc | Front windscreen weatherstrip | Necessary | 380.00 | 380.00 150/ |
| 4 | 1pc | N/s Headlamp | Broken | 772.00 | 772.00 545/ |
| 5 | 7pcs | N/s Headlamp bolt@\$4 | Necessary | 28.00 | 28.00 10/ |
| 6 | 1pc | N/s Headlamp rim | Broken | 160.00 | 160.00 85/ |
| 7 | 1pc | Front n/s side lamp | Broken | 192.00 | 192.00 / |
| 8 | 1set | Front bumper w reinforcement | Badly Dented | 1850.00 | 1850.00 1190/ |
| 9 | 1pc | Front N/s Corner panel | Badly Dented | 480.00 | 480.00 310/ |
| 10 | 1pc | Wiper cab garnish | Badly Dented | 380.00 | Repair R |
| 11 | 1pc | Front N/s Door | Dented/Bent | 1961.00 | Repair R |
| 12 | 1pc | Front N/s door lower step garnish | Ripped off | 218.20 | 218.20 / |
| | | | 4873-20 | 9607.20 | 7266.20 |
| | | Less: 15% discount | -15% | - | 1089.93 |
| | | | 4142-22 | 9607.20 | 6176.27 |
| | | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | 1pc | Front windscreen sealant | Necessary | 50.00 | 50.00 X |
| | | Total Spare Parts | 5882-22 | 9657.20 | 6226.27 |
| | | <u>LABOUR & MISC. CHARGES</u> | | | |
| 1 | | Remove the necessary affected parts, straighten front n/s door pillar and hinges, front n/s door and headlamp panel, repair front cab wiper garnish and replace parts | 7 hrs | 1800.00 | 1400.00 1000/ |
| 2 | | Remove and refit front n/s door parts | | 120.00 | 100.00 X |
| 3 | | Putty and Spraypaint | | 1200.00 | 800.00 500/ |
| 4 | | Check electrical | | 50.00 | 40.00 |
| 5 | | Rewire front portion and refocus n/s headlamp beam | | 50.00 | 30.00 |
| 6 | | Remove and refit front windscreen | | 150.00 | 120.00 |
| | | | XXX | 13027.20 | 8716.27 |
| | | | SUB / GRAND TOTAL | | |

*Reconditioned / Used Parts were not available for this model during the period of repair.

PRECISION APPRAISAL SERVICES



A copy each of the supporting documents are enclosed.

| <u>S/NO.</u> | <u>AVAILABLE DOCS</u> | <u>PARTICULARS</u> |
|---|---------------------------|--|
| <u>Client's Documents</u> | | |
| 1. | 25.10.2019 | GIA Statement / Traffic Police report |
| 2. | | Witness(es) Statement |
| 3. | | Accident-site photographs |
| 4. | | Video footage / CCTV / CD recording |
| 5. | 30.11.2019 | Repair bill / invoice / Excess Tax invoice |
| 6. | | Rental bill / invoice and agreement / receipts |
| 7. | | Vehicle Entry Permit receipt / E-day license for off-peak vehicle |
| 8. | | Towing fees / receipt (Singapore / Malaysia) |
| 9. | | Client sold off vehicle and produce letter from LTA |
| 10. | | Spare Part Ordering Form |
| 11. | | Levy at Custom / receipts |
| 12. | 30.11.2019 | Survey invoice and surveyor's report |
| 13. | 30.11.2019 | 44 Original / Copies of damage photographs |
| 14. | | Enquire PARF / COE Rebate for Registered Vehicle |
| 15. | | Enquire Transfer fee |
| 16. | | Certificate of Insurance / Motor Cover Note / New Policy Schedule / Registration Card / Grant / Road Tax |
| 17. | 31.10.2019 | Pre-repair Inspection Notices |
| 18. | | Traffic Police investigation results |
| 19. | | Estimated agreement between surveyor and repairer |
| 20. | 29.10.2019, 30.10.2019 | Tax invoices and search results from General Insurance Association of Singapore (GIA) and Traffic Police search fees |
| <u>Third Party's Documents</u> | | |
| 21. | 25.10.2019 | GIA Statement / Traffic Police report |
| 22. | | Admission Note |
| 23. | 31.10.2019 | LTA search / receipt / tax invoice |
| 24. | | Malaysia Vehicles Searches / service |
| 25. | | RCB / ACRA search |
| 26. | | Enhanced Individual search / receipt |
| 27. | | Property tax search / receipt |
| <u>Others (Apply only in chain collisions and/or any other documents)</u> | | |
| 28. | | |

We have on 31 October 2019 notified you of the accident and a pre-repair inspection of our client's motor vehicle was carried out by the appointed surveyors.

Subject to our client's instructions, please confirm in writing within 7 days hereof if you or your insured wish to inspect our client's vehicle or conduct a second re-inspection.

Please note that you or your insured should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured. In this event, you will be liable for any and all legal costs incurred.

Please also note that if your insured has a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter, which we will then forward to our client and/or the insurers for consideration on a without prejudice basis.

For avoidance of doubt, kindly note that this claim is made without prejudice to our client's personal injury claim.

Yours faithfully,



(Main Office)

Enc.

Cc client

Cc owner – PDS International Pte Ltd

Cc driver – Hu Weisai

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO19019282/Eqf3s2-1

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 06-01-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|---------------------|-----------------------|------------|
| Insured Veh. | GBC 2799B | Veh. Inspected | YL 8312M |
| Policy No. | D19MTPCVE003243 | Coverage (\$) | 0.00 |
| Claim No. | CMTD1905050 | Excess (\$) | 0.00 |
| Assign From | RUTH CHUA GEK TIANG | Assign Date | 02/01/2020 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|--------------------|
| Make & Model | ISUZU NQR70P | c.c | 4751 |
| Engine No. | HIDDEN | Year of Reg. | 2004 |
| Chassis No. | JAAN1R70P47101153 | Colour | WHITE |
| Odometer | 506673 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|----------|-------|---------|
| R/H Front Tyre | 7.50 R16 | OHTSU | 4 mm |
| L/H Front Tyre | 7.50 R16 | OHTSU | 4 mm |
| R/H Rear Tyre | 7.50 R16 | OHTSU | 4 mm |
| L/H Rear Tyre | 7.50 R16 | OHTSU | 4 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|-----------------------|--|------------------------|------------|
| Accident Date | 24/10/2019 | Inspection Date | 01/11/2019 |
| Survey held at | WILLY MOTOR COMPANY 27A JURONG PORT ROAD #01-32 SINGAPORE 619101 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 7 Working Days |
|-------------------------------------|-----------------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 8312M

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | FRONT PANEL | BADLY DENTED | 1,201.00 | 983.00 |
| 1 | FRONT WINDSCREEN | CRACKED | 1,985.00 | 1,280.00 |
| 1 | FRONT WINDSCREEN WEATHERSTRIP | NECESSARY | 380.00 | 150.00 |
| 1 | N/S HEADLAMP | BROKEN | 772.00 | 545.00 |
| 7 | N/S HEADLAMP BOLT @ \$4.00 | NECESSARY | 28.00 | 10.00 |
| 1 | N/S HEADLAMP RIM | BROKEN | 160.00 | 85.00 |
| 1 | FRONT N/S SIDE LAMP | BROKEN | 192.00 | 192.00 |
| 1 | SET FRONT BUMPER W REINFORCEMENT | BADLY DENTED | 1,850.00 | 1,100.00 |
| 1 | FRONT N/S CORNER PANEL | BADLY DENTED | 480.00 | 310.00 |
| 1 | WIPER CAB GARNISH | TO REPAIR SEE LABOUR | 380.00 | - |
| 1 | FRONT N/S DOOR | TO REPAIR SEE LABOUR | 1,961.00 | - |
| 1 | FRONT N/S DOOR LOWER STEP GARNISH | RIPPED OFF | 218.20 | 218.20 |
| | LESS 15% DISCOUNT | | - | -730.98 |
| | | | 9,607.20 | 4,142.22 |
| SPECIAL NETT ITEMS | | | | |
| 1 | FRONT WINDSCREEN SEALANT (SN) | NOT NECESSARY | 50.00 | - |
| | | | 50.00 | - |
| LABOUR | | | | |
| | REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN FRONT N/S DOOR PILLAR AND HINGES, FRONT N/S DOOR AND HEADLAMP PANEL, REPAIR FRONT CAB WIPER GARNISH AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF WIPER CAB GARNISH AND FRONT N/S DOOR. | | 1,800.00 | 1,000.00 |
| | REMOVE AND REFIT FRONT N/S DOOR PARTS. | NOT NECESSARY | 120.00 | - |
| | PUTTY AND SPRAY PAINT. | | 1,200.00 | 500.00 |
| | CHECK ELECTRICAL. } | | 50.00 | 30.00 |
| | REWIRE FRONT PORTION AND REFOCUS N/S HEADLAMP BEAM. } | | 50.00 | - |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|------------------------------------|-----------|---------------------------|-------------------|
| | REMOVE AND REFIT FRONT WINDSCREEN. | | 150.00 | 80.00 |
| | | | 3,370.00 | 1,610.00 |
| | GRAND TOTAL | | 13,027.20 | 5,752.22 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 4,600.00 |

Report Ref No. CS3/SMO19019282/Eqf3s2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.