

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR.LO KHEE TIAN, MARK
53 SUNRISE AVENUE #02-22
SINGAPORE 806746

TP FWD
Xiao Tony

ESTIMATE

Repair Code : CLM14814

Date in : 30/12/2019

Vehicle Num. : SMM3868X

Model : SUZUKI S-CROSS 1.0T GL+ AT

Chassis/Eng# : TSMJYA02S00679136/K10C1192292

Contact : 96238976 , 96300183

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR PROTECTOR <i>Dehnd.</i>	1	108.85	108.85 ✓
REAR AXLE <i>7H per</i>	1	1520.20	1,520.20 X
REAR BUMPER <i>Dehd</i>	1	580.30	580.30 ✓
REAR BUMPER LH REFLECTOR <i>cracked.</i>	1	34.30	34.30 ✓
REAR BUMPER LOWER LID <i>Dehd</i>	1	480.70	480.70 ✓
REAR BUMPER REINFORCEMENT <i>Bent</i>	1	305.30	305.30 ✓
REAR BUMPER SIDE RETAINER L/R <i>Lt Dmgd</i>	2	32.50	65.00 32.50
REAR END PANEL <i>Regrs</i>	1	430.60	430.60 X
REAR LH DOOR <i>Dented</i>	1	780.20	780.20 ✓
REAR LH DOOR BLACK TAPE <i>new</i>	1	42.30	42.30 ✓
REAR LH DOOR HINGE (LOWER) <i>Not mee</i>	1	39.70	39.70 X
REAR LH DOOR PROTECTOR <i>Dehnd.</i>	1	103.70	103.70 ✓
REAR LH DOOR WEATHER STRIP <i>Not new</i>	1	128.90	128.90 X
REAR LH FENDER ARCH GARNISH <i>lt</i>	1	138.50	138.50 ✓
REAR LH FENDER INNER SHIELD <i>Not new</i>	1	99.70	99.70 X
REAR LH SPORT RIM <i>lt</i>	1	850.00	850.00 550.00
REAR LH TAILLAMP <i>cracked</i>	1	495.20	375 495.20
REAR LH WHEEL BEARING <i>Dmgd</i>	1	283.00	283.00 ✓

*** This is a computer-generated document which requires no signature.***

winCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.LO KHEE TIAN, MARK
53 SUNRISE AVENUE #02-22
SINGAPORE 806746

Contact : 96238976 , 96300183

ESTIMATE

Repair Code : CLM14814
Date in : 30/12/2019
Vehicle Num. : SMM3868X
Model : SUZUKI S-CROSS 1.0T GL+ AT
Chassis/Eng# : TSMJYA02S00679136/K10C1192292

ROCKER GARNISH LH	3623.35	SN: 550	1	408.70	408.70	✓
	3078.84				6,895.15	
					Subtotal before discount	
					1,034.27	
Percentage discount 15%						
					5,860.88	
					Sub-total 1	
FRONT LH DOOR PROTECTOR CLIPS - SET			1	40.00	40.00	20
REAR BUMPER CLIPS - SET			1	80.00	80.00	30
REAR LH 215/55R17 TYRE			1	450.00	450.00	✓
REAR LH DOOR PROTECTOR CLIPS - SET			1	40.00	40.00	20
REAR LH FENDER ARCH GARNISH CLIPS - SET			1	40.00	40.00	20
REAR LH FENDER INNER SHIELD CLIPS - SET			1	50.00	50.00	✓
REAR LH TAILLAMP CLIPS - SET			1	25.00	25.00	10
ROCKER GARNISH LH CLIPS - SET			1	50.00	50.00	30
					Subtotal before discount	
					775.00	
Percentage discount 0%					0.00	
					775.00	
					Sub-total 2	
					6,635.88	
					Parts-total	

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

80 100.00
80 400.00

*** This is a computer-generated document which requires no signature.***

winCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No : +65 6842 0051 Fax No : +65 6741 0510

E-Mail : sales@wncar.sg

Company Reg. No : 200714616M

GST Registration No : 200714616M

MR. LO KHEE TIAN, MARK

53 SUNRISE AVENUE #02-22

SINGAPORE 806746

Contact : 96238976 , 96300183

ESTIMATE

Repair Code : CLM14814

Date in : 30/12/2019

Vehicle Num. : SMM3868X

Model : SUZUKI S-CROSS 1.0T GL+ AT

Chassis/Eng# : TSMJYA02S00679136/K10C1192292

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

80 120.00

60 148.00

80 1,200.00

600 1,200.00

50 120.00

3,280.00

9,915.88

*** This is a computer-generated document which requires no signature.***

page 3

Total: 5509.84

4/s: 4.4K. ✓

06 Days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: