

TP A16
Khunchan

SGW234SM
BMW 116i
WBAJA120X0J212996

Reer	Number Plate	NN	30(SN) +
Reer	Number Plate Holder	NW	30(SN) +
Reer	Bumper	Distorted	1080 -
Reer	Bumper Clips	~	50 -
Reer	Bumper Side Holder	x 02 LH ^{could}	101 x 2 = 202 ¹⁰¹
Reer	Bumper Inner Frame	^{could}	195 -
Reer	Bumper Reinforcement	Best	650(SN) -
Reer	Bumper Lower Spoiler	^{could}	1200(SN) 1000(SN) -
Reer	End Panel	Dented	698 -
Reer	End Panel Top Garnish	"new"	258 +
Reer	End Panel Sealant	~	60(SN) -
	Taillamp LH	^{could}	560 -
	Taillamp Panel LH	Ryir	295 +
	Reverse Sensor	x 04 2 pieces ^{damaged}	260 x 4 = 1040 520
	Tailgate	Dented	1136 -
	Tailgate Weatherstripe	new	195 -
	Tailgate Lock	ALP ^{new}	272 +

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SGW2345M.

Tailgate Glass Moulding. ?

95 ✓

Tailgate Glass Sealant

60 (SN) ✓

BMW Logo.

98 ✓

Rear Exhaust Pipe.

Revised

988 ✓

Rear Exhaust Mounting.

2 new

35 x

Rear Exhaust Heat Shield

85. x

hist: 5716.

Len 5%: 5430.22

S.N. : 1770

Labour: 2790

total: 9990.2

4/5 8K

07 days

81c

Panel Beating.

~~1200~~ 1100

Spray Painting.

~~1200~~ 1100

Wiring

~~50~~ 30

To underseal

~~150~~ 80

To remove reverse sensor

~~100~~ 60

To remove upholstery.

~~150~~ 100

To transfer tailgate fittings.

~~150~~ 100

To remove tailgate glass

~~180~~ 120

To remove exhaust pipe.

~~150~~ 100