

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5462G**AAD1912-168***Not Authorized
1/2mp \$3400*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

26 DEC 2019

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5462G

VF1ABL15AUC280947

RENAULT

LATITUDE

24.12.19

EQ

18/12/2014

PART**LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu</i>	561.70	✓
2	1	BUMPER LOWER REAR	\$	<i>nu</i>	411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i>	98.10	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i>	82.10	X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i>	59.80	X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i>	16.60	X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i>	80.80	X
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i>	54.20	X
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i>	16.60	X
10	1	BUMPER BEAM REAR	\$	<i>B1</i>	547.80	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>SL</i>	114.50	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>SL</i>	100.90	X
13	1	OUTER PANEL REAR (End Panel)	\$	<i>SL</i>	745.80	X
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>SL</i>	404.56	X
15	1	TAILLAMP RH	\$	<i>SL</i>	313.10	X
16	1	TAILLAMP PANEL RH	\$	<i>SL</i>	401.40	X
17	1	TAILLAMP LH	\$	<i>SL</i>	401.40	X
18	1	TAILLAMP PANEL LH	\$	<i>SL</i>	401.40	X
19	1	BOOT REAR	\$	<i>B1</i>	1,677.20	✓
20	1	BOOT FINISHER	\$	<i>SL</i>	344.70	X
21	1	BOOT WHEATERSTRIP	\$	<i>SL</i>	178.20	X
22	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i>	277.70	X
23	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i>	277.70	X
24	1	BOOT BADGE 'RENAULT'	\$	<i>nu</i>	82.40	✓
25	1	BOOT BADGE	\$	<i>nu</i>	95.80	✓
26	1	BOOT STRUT LH	\$	<i>SL</i>	145.10	X
27	1	BOOT STRUT RH	\$	<i>SL</i>	145.10	X
28	1	BOOT HINGE LH	\$	<i>SL</i>	254.20	X
29	1	BOOT HINGE RH	\$	<i>SL</i>	253.80	X
30	2	BOOT RUBBER PLUG	\$	<i>SL</i>	139.90	X

Trans-cab Auto Services Pte Ltd**AAD1912-168**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5462G

31	1	SPARE TYRE BOARD	\$	680.90	} <i>Sub X</i>
32	1	BOOT LOCK LINKAGE	\$	20.60	
33	1	BOOT LOCK LINKAGE HOLDER	\$	99.50	
34	1	BOOT INNER TRIM BOARD	\$	611.00	
35	1	BOOT SWITCH	\$	113.00	
36	1	BOOT LOCK	\$	246.60	
37	1	BOOT LOCK CATCH	\$	41.70	
38	1	EXHAUST CAP REAR	\$	125.40	
TOTAL			\$	10,623.16	
10%			\$	1,062.32	
			\$	9,560.84	

Special Nett

1	1SET	PARKING AID	\$	<i>Sub</i> 700.00	<i>X</i>
2	1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00	<i>—</i>
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	<i>—</i>
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	<i>X</i>
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00	<i>X</i>
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	<i>X</i>
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00	<i>X</i>
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	<i>X</i>
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	<i>✓</i>
10	1	BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00	<i>—</i>
11	1	BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00	<i>—</i>
12	2	REAR WINDSCREEN SEALANT	\$	<i>na</i> 80.00	} <i>X</i>
13	1	WINDSCREEN MOULDING	\$	<i>na</i> 100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00	
15	1	BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00	
16	1SET	BOOT FINISHER CLIP	\$	<i>na</i> 24.20	
17	1	TAILLAMP CLIP LH	\$	<i>na</i> 5.00	
18	1	TAILLAMP CLIP RH	\$	<i>na</i> 5.00	
19	1	Rear Bumper Protector	\$	<i>na</i> 100.00	
20	1	EXHAUST MOUNTING REAR	\$	<i>Sub</i> 16.00	
21	1	REAR LICENCE PLATE WITH HOLDER	\$	<i>Sub</i> 80.00	
TOTAL			\$	1,562.20	
TOTAL PARTS			\$	11,123.04	

LABOUR

Trans-cab Auto Services Pte Ltd**AAD1912-168**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5462G

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To Check Electrical Lighting Concerned.	\$	170.00	151
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	4001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To repair and realign rear exhaust pipe.	\$	4 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
Putty and spray painting of the affected portion.	\$	4401 6,000.00	4401
TOTAL	\$	14,510.00	

Over All Total \$ 25,633.04**LUMP SUM (REPAIR DAY)****28 DAYS**
2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: