



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2006262  
INV Date 11/09/2020  
Reference CC3/EQI20000081/Qpa3q2  
Code EQI



### PROFESSIONAL SERVICE FEE

Vehicle No. SG 5774E  
Insured Veh. FBL 2843J  
Claim No. DM20HO00164/SG  
Policy No. DMMPHQ19-000842  
Accident Date 23/12/2019  
Inspection Date 30/12/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC3/EQI20000081/Qpa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 11-09-2020	
			Code : EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	FBL 2843J	<b>Veh. Inspected</b>	SG 5774E
	<b>Policy No.</b>	DMMPHQ19-000842	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	DM20HO00164/SG	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	30/12/2019
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	MAN A95	<b>c.c</b>	10518
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
	<b>Chassis No.</b>	WMAA95ZZ7G7003250	<b>Colour</b>	MULTI COLOUR
	<b>Odometer</b>	249792	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	275/70 R22.5	FIRENZA	5 mm
	<b>L/H Front Tyre</b>	275/70 R22.5	FIRENZA	5 mm
	<b>R/H Rear Tyre</b>	275/70 R22.5	FIRENZA	5 mm
	<b>L/H Rear Tyre</b>	275/70 R22.5	FIRENZA	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	23/12/2019	<b>Inspection Date</b>	30/12/2019
	<b>Survey held at</b>	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>1 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5774E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LAMP STOP LED (MAN BUS)	CRACKED	1,141.70	1,141.70
1	LAMP INDICATOR LED (MAN BUS)	SERVICEABLE	1,274.10	-
	LESS 10% DISCOUNT		-	-114.17
			2,415.80	1,027.53
	<b><u>LABOUR</u></b>			
	TO REMOVE & INSTALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		530.00	265.00
	TO PUTTY & RESPRAY .		432.00	262.00
			962.00	527.00
<b>GRAND TOTAL</b>			<b>3,377.80</b>	<b>1,554.53</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,350.00</b>

Report Ref No. CC3/EQI20000081/Qpa3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SG 5774E

INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SG 5774E

RE-INSPECTION

