

Our Job Ref No : 305370745

Date : 17. Jan. 2020

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHC2933J

Date of Accident: 27. Dec. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SJB6262S

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$4,767.72

(b) Labour Charges

\$1,510.00

Total for Part-By-Part Repair Cost

\$6,277.72

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Ram

Date : 17/1/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305370745
 REGN NO : SHC2933J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 12.07.2018
 DATE/TIME IN : 30.12.2019 12:30
 ACCIDENT DATE : 27.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0595-G	IONIQ PANEL ASSY-REAR DOO	1	1,789.90	20.00	1,431.92	DD
0002 04-01-0104-0592-G	IONIQ PANEL ASSY-FRONT DO	1	1,797.20	20.00	1,437.76	DD
0003 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00	2.00-	80.00	new
0004 28-01-0103-0003-A	(I40)FRT DOOR LOGO SONATA	1	75.00	0.20	75.00	new
0005 03-01-0104-2020-A	IONIQ WHEEL ASSY-ALLOY (S	1	1,124.20	20.00	899.36	Scr
0006 04-01-0104-2538-G	IONIQV2 MIRROR ASSY-OUTSI	1	1,054.60	20.00	843.68	Br

SUB-TOTAL : 4,767.72

JOB NATURE

0000 PB	PANEL BEATING	720.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
0003 L	TRANSFER OF DOOR	80.00
0004 20-08	ADJUST REAR WHEEL ALIGNMENT	80.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305370745
REGN NO : SHC2933J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 12.07.2018
DATE/TIME IN : 30.12.2019 1:
ACCIDENT DATE : 27.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,510.00

TOTAL : 6,277.72

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2933J

DATE 30/12/2019

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) x(R)			\$ 1,768.30
	Rear Fender Inner Lining (RH) x(R)			\$ 73.60
	Rear Windscreen Moulding xun			\$ 28.20
	Rear Door (RH) DD			\$ 1,789.90
	Front Door (RH) DD			\$ 1,797.20
	Rear Tyre Rim (RH) SCR			\$ 1,124.20
	SUB TOTAL			\$ 6,581.40
	LESS 20%			\$ 1,316.28
	DISCOUNTED TOTAL			\$ 5,265.12
				\$ 3769.04
	Rear Bumper Rubber Mat xun			\$ 50.00
	Rear Windscreen Sealant xun			\$ 46.00
	Rear Door Comfortdelgro & Apps Sticker (RH) nec			\$ 80.00
	Front Door Coloured Comfort Logo (RH) nec			\$ 75.00
				\$ 251.00
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 800.00
	Tuff Kote			\$ 50.00
	Transfer of Door			\$ 80.00
	Rear Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 2,210.00
	ESTIMATE TOTAL			\$ 7,726.12
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

ACG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

\$30

Ram(LKK)

31/12/19 1215

812222228
88622128
3/4 repair
P/P

Def paint
photo

Larry Ng