

**Team AutoPro Pte Ltd** 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722  
Tel: 6258 1955 Email: tap.finalization@gmail.com /teamautooffice@gmail.com

SJE : \_\_\_\_\_ Vehicle Nos : **SMM 575 K**  
Date of Survey : \_\_\_\_\_ Model : Hyundai avante S  
Date of ReSurvey: \_\_\_\_\_ After-Paint: \_\_\_\_\_ Year : \_\_\_\_\_  
Contacts : \_\_\_\_\_ Chassis No : \_\_\_\_\_

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_ Working Day: \_\_\_\_\_

| Nos. | PARTS                           | Qty | Unit S\$    | TOTAL S\$   |
|------|---------------------------------|-----|-------------|-------------|
| 1    | Bootlid                         | 1   | \$ 1,864.20 | \$ 1,864.20 |
| 2    | Bootlid logo                    | 1   | \$ 105.20   | \$ 105.20   |
| 3    | Bootlid inner trim              | 1   | \$ 158.10   | \$ 158.10   |
| 4    | Bootlid taillamp                | 2   | \$ 854.20   | \$ 1,708.40 |
| 5    | Bootlid lock                    | 1   | \$ 453.60   | \$ 453.60   |
| 6    | Bootlid weatherstrip            | 1   | \$ 265.40   | \$ 265.40   |
| 7    | Rear bumper                     | 1   | \$ 1,154.30 | \$ 1,154.30 |
| 8    | Rear bumper lower garnish       | 1   | \$ 581.60   | \$ 581.60   |
| 9    | Rear bumper side lower cover RH | 1   | \$ 163.40   | \$ 163.40   |
| 10   | Rear bumper inner sponge        | 1   | \$ 235.40   | \$ 235.40   |
| 11   | Rear bumper reinforcement       | 1   | \$ 453.01   | \$ 453.01   |
| 12   | Rear bumper retainer            | 2   | \$ 68.90    | \$ 137.80   |
| 13   | Rear bumper reflector           | 2   | \$ 150.00   | \$ 300.00   |
| 14   | Taillamp                        | 2   | \$ 1,054.00 | \$ 2,108.00 |
| 15   | Exhaust assy                    | 1   | \$ 879.00   | \$ 879.00   |
| 16   | Exhaust mounting                | 1   | \$ 238.00   | \$ 238.00   |
| 17   | Rear end panel                  | 1   | \$ 935.40   | \$ 935.40   |
| 18   | Rear end panel top garnish      | 1   | \$ 342.10   | \$ 342.10   |

NDX  
NNX  
NDX  
NDX  
NDX  
NDX  
BR✓  
CUT✓  
BR✓  
BR✓  
BR✓  
NEC✓  
BR✓  
NDX  
NNX  
DD✓  
BR✓

Parts Sub Total : \$2953.51 / 12,576.51  
20% Discount \$ 590.70 2,515.30  
**PARTS TOTAL : \$ 2362.81 / 10,061.21**

2362.81

| Nos.                 | SPECIAL NETT                    | Qty | Unit S\$  | TOTAL S\$          |
|----------------------|---------------------------------|-----|-----------|--------------------|
| 1                    | Rear bumper clip                | 1   | \$ 60.00  | \$ 30.00 60.00     |
| 2                    | Rear bumper lower garnish clip  | 1   | \$ 80.00  | \$ 30.00 80.00     |
| 3                    | Rear bumper lower cover clip    | 1   | \$ 60.00  | \$ 60.00           |
| 4                    | Bootlid taillamp seal           | 2   | \$ 60.00  | \$ 120.00          |
| 5                    | Bootlid inner trim clip         | 1   | \$ 60.00  | \$ 60.00           |
| 6                    | Taillamp seal                   | 2   | \$ 60.00  | \$ 120.00          |
| 7                    | Rear end panel sealant          | 1   | \$ 100.00 | \$ 40.00 100.00    |
| 8                    | Rear end panel top garnish clip | 1   | \$ 60.00  | \$ 30.00 60.00     |
| 9                    | Rear number plate               | 1   | \$ 80.00  | \$ 80.00           |
| 10                   | Reverse camera                  | 1   | \$ 400.00 | \$ 400.00          |
| 11                   | Reverse sensor                  | 2   | \$ 200.00 | \$ 200 400.00      |
| SPECIAL NETT TOTAL : |                                 |     |           | \$ 330.00 1,540.00 |

NEC ✓  
NNX  
NNX  
NNX  
NECV  
NECV  
NNX  
NDX  
SC ✓

| Nos.           | LABOUR                                                            | S\$                 |
|----------------|-------------------------------------------------------------------|---------------------|
| 1              | Check wiring                                                      | \$ 30.00 100.00     |
| 2              | Panel beating                                                     | \$ 600.00 1,200.00  |
| 3              | To drill holes on replaced rear bumper and install reverse sensor | \$ 60.00 80.00      |
| 4              | R&R exhaust                                                       | \$ 180.00           |
| 5              | Spray paint                                                       | \$ 600.00 1,400.00  |
| LABOUR TOTAL : |                                                                   | \$ 1290.00 2,960.00 |

NNX

Survey 30/12/19  
1500 hrs  
T Gum Min

Resurvey 28/1/2020  
1500 hrs  
T Gum Min

Lump sum Repair  
Repair days 5

PARTS TOTAL : \$ 2302.81 10,061.21  
SPECIAL NETT TOTAL : \$ 330 1,540.00  
LABOUR TOTAL : \$ 1290.00 2,960.00  
GRAND TOTAL : \$ 14,561.21

3982.81  
@ 20%  
3187.25

4/5 3100/2

T Gum Min  
6/2/2020

T Gum Min  
13/2/2020

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: