

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SMA5005U

No.	Qty	List Items			
1	1	Rear bumper	Bulgem	\$ 1,250.00	✓
2	2	Rear bumper reflector	Nissan	\$ 570.00	4
3	2	Rear bumper reverse sensor	cm/sen	\$ 1,436.70	44
4	1 set	Rear bumper clips	\$	40.00	✓
5	2	Rear bumper side retainer	\$	171.80	X
6	1	Rear bumper inner foam	\$	189.50	7
7	1	Rear bumper inner reinforcement	\$	695.90	7
8	1	Rear tailgate centre "LEXUS" logo	\$	80.95	X
9	1	Rear boot RH "RX270" emblem	\$	55.65	X
10	1	Rear boot LH "LEXUS" emblem	\$	60.95	X
11	1	Rear end panel	\$	717.90	X
			\$	5,269.35	
			Less 10%	\$ 526.94	
			Total :	\$ 4,742.42	

	Labour		
1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 800.00	300
2	To putty and spray Spray Paintings charges.	\$ 800.00	300
3	To remove, refix and reset reverse sensors.	\$ 100.00	60
4	To check wirings & lightings.	\$ 80.00	15h
5	To supply and apply anti rust treatment	\$ 60.00	X
		Total :	\$ 1,840.00

Total Parts and Labour : \$ 6,582.42

Not Authorised
 L/Ling &?
 Recovery After Repair
 2-3 days