

INS. CASE OWNER:

SALIHA

CC4/AIG20000089/Kea3

LKK:
IDAC:

Surveyor:

KENNETH

DOI: 31/12/2019

Date / Time: 30/12/2019

Registered in Merimen: 02/01/2020

Pre-assign / CCU / FTE



Insured Vehicle No. : SLT 8576E
Name of Insured : TAN CHIAH WAH
Insured Tel No. : HP: +65-96311386
Excess Sec II :SS D.O.A : 21/12/2019
Is driver the owner? (☒ YES / NO) Nature of Accident :

Claim No. :
Policy No. : 1700077396
Make / Model : MERCEDES-BENZ C180
Place of Accident : ALONG THOMSON RD (BEF THOMSON MEDICAL

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability : % Final ? Yes / No

SKT 3930K



INSRS:
WSP: S THREE
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	SKT 3930K - X	SLT 8576E - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
13-03-20	FILE INFORM RECD TP LAYHER LOD, REQUEST TO SUBMIT W/ REPORT.		Notification ltr (if non-pickup):	
			Call OI:	13-03-20
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	☐
			After call ltr to OI:	☐
			Authorisation To Act:	☐
			Release Voucher:	☐
			Final Repair Bill:	☐
			Car Rental Invoice:	☐
			Towing Invoice:	☐
			LTA / GIA :	☐
			Medical Bill:	☐
			PIR:	☐
			Mandate/Reject Instruction:	☐
			LOD	☐
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	S\$	(days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. :	S	If NO or B 28, Ass. Lia :
Repair Cost:	S\$	on major A RISKY TRUCK @ CONDUIT JUNCTION.		
Loss of Rental (LOR):	S\$	(days)		
Loss of Use (LOU):	S\$	(\$ x days)		
Loss of Income (LOI):	S\$	(\$ x days)		
LOR only ☐ LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	S\$			
Medical:	S\$			
Disbursement:	S\$	(e.g. Tow/ Independent)		
Legal Cost	S\$			
Total:	S\$	Global Sum S\$:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1:	S\$	Name 1:		
Payee 2: (Strike if N.A.)	S\$	Name 2:		
Payee 3: (Strike if N.A.)	S\$	Name 3:		

CS/SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP / COP
3) Survey fee: 290

REF: A19

0089/16

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 31.12.2019

Estimated Cost: _____

DD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKT 3930K

at Workshop n/s S Three Automotive

of BKE 8 sin ming Industrial Estate #01-64/66

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Acura 10.000.00

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 558K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No

SKT 3930K Yr Regn: 06 15

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Peugeot 308 c.c. 1199

Colour

M. Black A/C: Insured / Std / NI / NA

Sp. Reading

72984 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF3LP1HNYWES264944

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

J mm

R/Bal.

J mm

L/Bal.

J mm

L/Bal.

J mm

D.O.A.

2.1/12/19

D.O.I.

3.1/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or *

Frt o/s & u/c

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time Action / Instruction

No parts prices yet.

4/3: +11,750 (USD: +6,869.60 3T/1)

M.Y: +58,000.00

LTA: +39,838.00

Net: +18,162.00

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Picks

Odds

TOTAL

Rep. Form:

Lump Sum / L.R. C.:

He

Not Notarized
 C/Sy 8 11,75qk
 Resonay After Pain

TO :
 ATTN : MOTOR CLAIM DEPT. T/P VEH NO. : SLT8576E

ESTIMATE REPORT 1st QUOTATION

JOB NO. _____

OWNER'S PARTICULAR

NAME : CITIPONICS PTE LTD
 ADDRESS :

CONTACT :

LICENSE NO. : SKT3930K TRANS. :
 MAKE / MODEL : PEUGEOT 308
 OWNER'S INSURER :
 JOB CODE : TP S/A : JOEY

CHASSIS NO. :
 ENGINE NO. :

ACCIDENT DATE : 21-Dec-19

CLAIM DETAIL

MATERIALS

		QTY	QUG PRICE	DISC %	DISC PRICE	SUR DISP	REV PRICE
1	FRONT BUMPER SPONGE	Sn 1.00	185.00	10.00	166.50	Y	X
2	FRONT BUMPER 785-co	Tn 1.00	1458.00	10.00	1312.20	Y	✓
3	FRONT BUMPER RETAINER LH & RH	cls cm 2.00	150.00	10.00	135.00	Y	4
4	FRONT BUMPER REINFORCMENT 482	Ry 1.00	590.00	10.00	531.00	Y	✓
5	FRONT BUMPER FOG LAMP COVER RH	cm 1.00	290.00	10.00	261.00	Y	✓
6	FRONT BUMPER LOWER GRILLE	mis 1.00	218.00	10.00	196.20	Y	✓
7	FRONT BUMPER LOWER AIR GARNISH	cm 1.00	205.00	10.00	184.50	Y	✓
8	FRONT BUMPER BRACKET RH	mis 1.00	125.00	10.00	0.00	Y	✓
9	FRONT BUMPER TOWING COVER	mis 1.00	58.00	10.00	0.00	Y	✓
10	RADIATOR GRILLE	mj cm 1.00	295.00	10.00	0.00	Y	✓
11	FRONT GRILLE LOGO	na 1.00	78.00	10.00	0.00	Y	✓
12	FOG LAMP COVER CHROME	cm 1.00	220.00	10.00	0.00	Y	✓
13	FOG LAMP LED RH	cm 1.00	315.00	10.00	0.00	Y	✓
14	FOG LAMP BRACKET	mis 1.00	85.00	10.00	0.00	Y	✓
15	HEADLAMP ASSY HID RH	Bro 1.00	1150.00	10.00	0.00	Y	✓
16	HEADLAMP ASSY HID LH	cm 1.00	1150.00	10.00	0.00	Y	✓
17	HEADLAMP PANEL RH	mis 1.00	195.00	10.00	0.00	Y	✓
18	HEADLAMP PANEL LH	R 1.00	195.00	10.00	0.00	Y	X
19	FRONT FENDER RH 362	Ry 1.00	555.00	10.00	0.00	Y	✓
20	FRONT FENDER INNER SHIELD RH	cm 1.00	138.00	10.00	0.00	Y	✓
21	FRONT SPORT RIM RH	Sn 1.00	1050.00	10.00	945.00	Y	X
22	RADIATOR SIDE GARNISH RH	cm 1.00	205.00	10.00	184.50	Y	✓
23	BONNET 1350	Ry 1.00	1750.00	10.00	1575.00	Y	✓
24	BONNET LOCK	R 1.00	85.00	10.00	76.50	Y	X
25	BONNET INSULATOR	Sn 1.00	185.00	10.00	166.50	Y	✓
26	WASHER TANK	Red 1.00	218.00	10.00	196.20	Y	✓
27	FRONT BRACE PANEL	R 1.00	105.00	10.00	94.50	Y	X
28	NUMBER PLATE HOLDER	Sn 1.00	85.00	10.00	76.50	Y	X

29	FRONT SUPPORT PANEL TOP COVER	<i>DD</i>	1.00	288.00	10.00	259.20	Y	☒
30	FRONT SUPPORT PANEL	<i>CM</i>	1.00	598.00	10.00	538.20	Y	☒
31	AIRCON CONDENSOR	<i>Ry</i>	1.00	789.00	10.00	710.10	Y	☒
32	AIRCON PIPE - CONDENSOR TO COMPRESSOR	<i>Sn</i>	1.00	420.00	10.00	378.00	Y	☒
33	RADIATOR	<i>hows cm</i>	1.00	395.00	10.00	355.50	Y	☒
34	AIRCON PIPE - CONDENSOR TO COOLING COIL	<i>Sn</i>	1.00	330.00	10.00	297.00	Y	☒
35	INNER COOLER	<i>Ry</i>	1.00	1050.00	10.00	945.00	Y	☒
36	INNER COOLER INTAKE HOSE	<i>DD</i>	1.00	385.00	10.00	346.50	Y	☒
37	INNER COOLER EXHAUST HOSE	<i>Sn</i>	1.00	365.00	10.00	328.50	Y	☒
38	INNER COOLER AIR VENT	<i>DD</i>	1.00	105.00	10.00	94.50	Y	☒
39	INNER COOLER BRACKET 3PCS	<i>CM</i>	3.00	240.00	10.00	216.00	Y	☒
40	HEADLAMP INNER PLASTIC RETAINER RH	<i>CM</i>	1.00	135.00	10.00	121.50	Y	☒
41	RADIATOR SPARE TANK	<i>Sn</i>	1.00	285.00	10.00	256.50	Y	☒
42	RADIATOR SPARE TANK HOSE	<i>Sn</i>	1.00	60.00	10.00	54.00	Y	☒
43	AIR BAG SENSOR RH	<i>Sn</i>	1.00	295.00	10.00	265.50	Y	☒
44	FRONT LOWER ARM RH	<i>DD</i>	1.00	320.00	10.00	288.00	Y	☒
45	FRONT KNUCKLE ARM RH <i>565</i>	<i>Ry</i>	1.00	1080.00	10.00	972.00	Y	☒
46	FRONT SHOCK ABSORBER RH <i>365</i>	<i>Ry</i>	1.00	495.00	10.00	445.50	Y	☒
47	FRONT KNUCKLE ARM BEARING RH <i>256</i>	<i>Sn</i>	1.00	380.00	10.00	342.00	Y	☒
48	WING MIRROR ASSY RH	<i>Sn</i>	1.00	750.00	10.00	675.00	Y	☒
TOTAL (PARTS):				20103.00		13989.60		

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS 1SET	<i>Sn</i>	1.00	50.00	0.00	50.00	Y	☒
2	BONNET INSULATOR CLIPS	<i>Sn</i>	1.00	80.00	0.00	80.00	Y	☒
3	FRONT FENDER INNER SHIELD CLIPS 1SET	<i>Sn</i>	1.00	50.00	0.00	50.00	Y	☒
4	FRONT NUMBER PLATE	<i>Sn</i>	1.00	50.00	0.00	50.00	Y	☒
5	RADIATOR COOLANT	<i>Sn</i>	1.00	80.00	0.00	80.00	Y	<i>30Sn</i>
6	FRONT TYRE RH	<i>Sn</i>	1.00	480.00	0.00	480.00	Y	☒
TOTAL (PARTS):				790.00		790.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA		1.00	1500.00	0.00	1500.00	Y	<i>700h</i>
2	SPRAY PAINTING ON AFFECTED AREA		1.00	1400.00	0.00	1400.00	Y	<i>800h</i>
3	CHECK WIRING SYSTEM & RESET HEADLAMP SYS		1.00	120.00	0.00	120.00	Y	<i>30h</i>
4	RESPRAY TUFF KOTE ON ACCIDENT AREA	<i>Sn</i>	1.00	120.00	0.00	120.00	Y	☒
5	CONDUCT FULL WHEEL ALIGNMENT		1.00	120.00	0.00	120.00	Y	<i>60h</i>

6	R&R AIRCON CONDENSOR & TOP UP AIR CON GAS	1.00	150.00	0.00	150.00	Y	<u>100/-</u>
7	R&R FRONT LH SUSPENSION SYSTEM	1.00	280.00	0.00	280.00	Y	<u>180/-</u>
	TOWING CHARGES	1.00	150.00	0.00	150.00	Y	<u>60/-</u>

TOTAL (LABOUR) : 3840.00 3840.00

TOTAL PARTS & LABOUR : 24733.00 18619.80

EXCESS : S\$ _____

NO. OF DAY : 09 days

☐ SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY :

SURVEY BY : _____

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

S THREE AUTOMOTIVE RECOVERY PTE LTD

Blk 8 Sin Ming Industrial Estate
#01-6466 Singapore 575643
Tel : 6284 1542 / 6284 1575
Fax : 6487 5315
sthreeautomotive@gmail.com

TO :

ATTN : MOTOR CLAIM DEPT.

T/P VEH NO : SLT8576E

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : CITIPONICS PTE LTD

CONTACT : _____

ADDRESS :

LICENSE NO : SKT3930K TRANS :

CHASSIS NO :

MAKE / MODEL : PEUGEOT 308

ENGINE NO :

OWNER'S INSURER :

JOB-CODE : TP S/A : JOEY

ACCIDENT DATE : 21-Dec-19

SUPPLYMENTARY

1 FRONT RADIATOR GRILLE CHROME

Qty 1.00 495.00 10.00 445.50 ✓ _____

2 WASHER TANK HOSE

Qty 1.00 120.00 10.00 108.00 ✓ _____

EXCESS : S\$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY : / /

SURVEY BY :

CONTACT N° :

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.



ANNOUNCING Autotruster Traders Pte Ltd as sgCarMart Premium Dealer for the 4th Consecutive Year



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Peugeot 308 1.6A Turbo Allure Glass Roof @ \$28,800.



Low Mileage, Low Deprec, 1.50% Interest, Buy From Reputable Company
Hamilton Autohub Pte Ltd



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

2 vehicles

Peugeot 308

Advanced Search 🔍

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection Peugeot 308		Any	Any	2016	Any	Any	Any	Available
	Peugeot 308 SW 1.2A PureTech Allure	\$63,800	\$8,400 /yr	23-Nov-2016	1,199 cc	36,524 km	Stationwagon	Available
Rare Midnight Blue, High Specs Peugeot 308 1.2A Wagon With Loads Of High Tech Features! Genuine Low Mileage Done 36524km, Valid 5-yr Agent Warranty, Like Brand New. 1 Owner. New Paintwork, Nice/New Car Number, Road Tax Till May 20. 100% Accident Free. Call... Lake View Credit Pte Ltd								
Posted: 01-Jan-2020 Tags: 2016 Peugeot 308, 2016 peugeot 308, Peugeot 308, peugeot 308, Peugeot, 308, Used Peugeot								
	Peugeot 308 1.2A PureTech EAT6 Allure	\$64,777	\$8,710 /yr	16-Dec-2016	1,199 cc	64,123 km	Hatchback	Available
1 Fussy Owner! Very Well Maintained, Full Agent Serviced Records With Agent, Lowest Deprecation In The Market, Value Buy, Elegance Silver With Sporty Black And Red Interior, Flexible Loan Package Available, GST Included, Call Us For More Details. HTS Motor								
Posted: 20-Dec-2019 Tags: 2016 Peugeot 308, 2016 peugeot 308, Peugeot 308, peugeot 308, Peugeot, 308, Used Peugeot								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Peugeot 308, Peugeot 308 Singapore, used Peugeot 308 Singapore, used Peugeot 308, used vehicles Singapore or even buy used Peugeot 308 Singapore. We have now car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2020 sgCarMart. All rights reserved.

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	380G
Vehicle Details	
Vehicle No.:	SKT3930K
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	PEUGEOT
Vehicle Model:	308 SDR ACTIVE PURETECH 1.2 A/T 2WD
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	10XT180029716
Chassis No.:	VF3LPNNYWE5264944
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$16,374.00
Original Registration Date:	04 Jun 2015
First Registration Date:	04 Jun 2015
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jun 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,590.00
COE Rebate Amount:	\$36,088.00
Total Rebate Amount:	\$39,838.00

The information contained herein is correct as at 02 Jan 2020

OK

Not Authorized
 U/Sing B?
 Recovery After Paint

TO :
 ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SLT8576E

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

NAME : CITIPONICS PTE LTD

CONTACT : _____

ADDRESS : _____

LICENSE NO. : SKT3930K TRANS. :

CHASSIS NO. :

MAKE / MODEL : PEUGEOT 308

ENGINE NO. :

OWNER'S INSURER :

JOB-CODE : TP S/A : JOEY

ACCIDENT DATE : 21-Dec-19

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER SPONGE	1.00		10.00	0.00	Y	7
2 FRONT BUMPER	1.00	1.00	10.00	0.00	Y	1
3 FRONT BUMPER RETAINER LH & RH	1.00	0.15 cm	10.00	0.00	Y	4
4 FRONT BUMPER REINFORCMENT	1.00	Ry	10.00	0.00	Y	1
5 FRONT BUMPER FOG LAMP COVER RH	1.00	CMH	10.00	0.00	Y	1
6 FRONT BUMPER LOWER GRILLE	1.00	2.11	10.00	0.00	Y	1
7 FRONT BUMPER LOWER AIR GARNISH	1.00	CM	10.00	0.00	Y	1
8 FRONT BUMPER BRACKET RH	1.00		10.00	0.00	Y	1
9 FRONT BUMPER TOWING COVER	1.00	2.11	10.00	0.00	Y	1
10 RADIATOR GRILLE	1.00	2.11 cm	10.00	0.00	Y	1
11 FRONT GRILLE LOGO	1.00	2.00	10.00	0.00	Y	1
12 FOG LAMP COVER CHROME	1.00	CM	10.00	0.00	Y	1
13 FOG LAMP LED RH	1.00	CM	10.00	0.00	Y	1
14 FOG LAMP BRACKET	1.00	2.11	10.00	0.00	Y	1
15 HEADLAMP ASSY HID RH	1.00	B2	10.00	0.00	Y	1
16 HEADLAMP ASSY HID LH	1.00		10.00	0.00	Y	?
17 HEADLAMP PANEL RH	1.00		10.00	0.00	Y	?
18 HEADLAMP PANEL LH	1.00	R	10.00	0.00	Y	X
19 FRONT FENDER RH	1.00	Ry	10.00	0.00	Y	1
20 FRONT FENDER INNER SHIELD RH	1.00	CMH	10.00	0.00	Y	1
21 FRONT SPORT RIM RH	1.00	Pm	10.00	0.00	Y	X
22 RADIATOR SIDE GARNISH RH	1.00	.	10.00	0.00	Y	?
23 BONNET	1.00	Ry	10.00	0.00	Y	1
24 BONNET LOCK	1.00	R	10.00	0.00	Y	X
25 BONNET INSULATOR	1.00	2.11	10.00	0.00	Y	X
26 WASHER TANK	1.00		10.00	0.00	Y	?
27 FRONT BRACE PANEL	1.00	R	10.00	0.00	Y	X
28 NUMBER PLATE HOLDER	1.00	2.11	10.00	0.00	Y	X

29	FRONT SUPPORT PANEL TOP COVER	1.00		10.00	0.00	Y	?
30	FRONT SUPPORT PANEL	1.00	CM	10.00	0.00	Y	✓
31	AIRCON CONDENSOR	1.00	in	10.00	0.00	Y	X
32	AIRCON PIPE - CONDENSOR TO COMPRESSOR	1.00		10.00	0.00	Y	X
33	RADIATOR	1.00		10.00	0.00	Y	?
34	AIRCON PIPE - CONDENSOR TO COOLING COIL	1.00		10.00	0.00	Y	?
35	INNER COOLER	1.00	R	10.00	0.00	Y	✓
36	INNER COOLER INTAKE HOSE	1.00		10.00	0.00	Y	?
37	INNER COOLER EXHAUST HOSE	1.00		10.00	0.00	Y	?
38	INNER COOLER AIR VENT	1.00	R	10.00	0.00	Y	✓
39	INNER COOLER BRACKET 3PCS	1.00	CM	10.00	0.00	Y	✓
40	HEADLAMP INNER PLASTIC RETAINER RH	1.00	CM	10.00	0.00	Y	✓
41	RADIATOR SPARE TANK	1.00		10.00	0.00	Y	?
42	RADIATOR SPARE TANK HOSE	1.00	in	10.00	0.00	Y	X
43	AIR BAG SENSOR RH	1.00	in	10.00	0.00	Y	X
44	FRONT LOWER ARM RH	1.00		10.00	0.00	Y	?
45	FRONT KNUCKLE ARM RH	1.00		10.00	0.00	Y	?
46	FRONT SHOCK ABSORBER RH	1.00		10.00	0.00	Y	?
47	FRONT KNUCKLE ARM BEARING RH	1.00		10.00	0.00	Y	?
48	WING MIRROR ASSY RH	1.00	in	10.00	0.00	Y	X
TOTAL (PARTS) :				0.00	0.00		

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS 1SET	1.00	in	50.00	0.00	50.00	Y	✓
2	BONNET INSULATOR CLIPS	1.00	in	80.00	0.00	80.00	Y	X
3	FRONT FENDER INNER SHIELD CLIPS 1SET	1.00	in	50.00	0.00	50.00	Y	✓
4	FRONT NUMBER PLATE	1.00	in	50.00	0.00	50.00	Y	X
5	RADIATOR COOLANT	1.00	in	80.00	0.00	80.00	Y	70.00
6	FRONT TYRE RH	1.00		480.00	0.00	480.00	Y	?
TOTAL (PARTS) :				790.00		790.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	1.00		1500.00	0.00	1500.00	Y	700
2	SPRAY PAINTING ON AFFECTED AREA	1.00		1400.00	0.00	1400.00	Y	800
3	CHECK WIRING SYSTEM & RESET HEADLAMP SYS	1.00		120.00	0.00	120.00	Y	300
4	RESPRAY TUFF KOTE ON ACCIDENT AREA	1.00	in	120.00	0.00	120.00	Y	X
5	CONDUCT FULL WHEEL ALIGNMENT	1.00		120.00	0.00	120.00	Y	600

6	R&R AIRCON CONDENSOR & TOP UP AIR CON GAS	1.00	150.00	0.00	150.00	Y	<u>1000</u>
7	R&R FRONT LH SUSPENSION SYSTEM	1.00	280.00	0.00	280.00	Y	<u>?</u>
	TOWING CHARGES	1.00	150.00	0.00	150.00	Y	<u>600</u>

TOTAL (LABOUR) : 3840.00 3840.00

TOTAL PARTS & LABOUR 4630.00 4630.00

EXCESS : S\$

NO. OF DAY : 07 days

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY : 31.12.18

SURVEY BY : Kenneth

CONTACT NO : 9691 0663

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PRE-REPAIR INSPECTION REQUEST – SKT3930K vs SLT8576E (OI) on D.O.A.: 21/12/2019

From: Subramaniam, Divyashni
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Hor, Yinnul, Serene Chui
Sent: 12/30/2019 2:47:02 PM
Attachments:  [OIA REQUEST.pdf](#)

Hi,

Please refer to the enclosed request from **Liberty Law Practice LLP**.

Claim no : 6537228859SG003
Case Owner : Saliba

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as **Single Joint Expert** as requested.

Thanks & Regards,

Divyashni Subramaniam
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Divyashni.Subramaniam@aig.com | www.aig.sg

Sur. Kenneth

P: Yinnul

T: 348 p.m 30.12.19

V: 011

G. ✓

From: Serene Chui Yoke Har <serene@libertylaw.com.sg>
Sent: Monday, December 30, 2019 2:22 PM
To: Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Hor, Yinnul <Yinnul.Hor@aig.com>
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT8576E AND SKT3930K ON 21/12/2019

This message is from an external sender; be cautious with links and attachments.

Dear Divyashni,

We refer to your email of even date.

Kindly arrange for **Kenneth Kong** from **LKK Auto Consultants Pte Ltd**, to carry out the pre-repair survey of our client's vehicle SKT 3930K as a 'single joint expert'.

Please be informed that the said vehicle can be surveyed / inspected at:

Venue : **S Three Automotive Recovery Pte Ltd**
Blk 8 Sin Ming Industrial Estate
#01-64/66
Singapore 575643
Contact / Tel : **Ms. Joey / 9662 0282**

Kindly acknowledge receipt hereof.

Regards,
Serene
for and on behalf of Christine Sekhon
Liberty Law Practice LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
DID: 3152 0980

Privileged and/or confidential information may be contained in this email or its attachments. If you are not the intended recipient, you must not disclose, copy or distribute the contents therein or take any action in reliance of such contents. Communication of any information in this email or its attachments to an unauthorized person is prohibited.

Please consider the environment before printing this e-mail.

On Mon, Dec 30, 2019 at 12:32 PM Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com> wrote:



This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo

adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo:

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2020-01-05 23:32 EST to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

From: Divyashni.Subramaniam@aig.com

To: serene@libertylaw.com.sg

Cc: Andy-SY.Fong@aig.com, Winnie-LW.Fan@aig.com, NoorMariessa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com

,Aashweeryeelkaur.Mithoosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com, Yinnul.Hor@aig.com

Subject: aigencryp! PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT8576E AND SKT3930K ON 21/12/2019

Date: Mon, 30 Dec 2019 04:32:44 +0000

Without Prejudice

Your Reference : CS/1157/19/S3

Our Reference : 6537228859SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashni Subramaniam

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations - Auto

Divyashni.Subramaniam@aig.com | www.aig.sg

From: Serene Chui Yoke Har

Sent: Monday, December 30, 2019 12:23:55 PM (UTC+08:00) Kuala Lumpur, Singapore

To: Hor, Yinnul

Subject: [EXTERNAL] Your insured: SLT 8576E. Pre-Repair Survey for SKT 3930K. Our ref no.: CS/1157/19/S3

This message is from an external sender; be cautious with links and attachments.

Accident on 21.12.2019 involving SKT 3930K and SLT 8576E at the T junction of Thomson Road and Novena Rise.

Dear Sirs,

We refer to the above matter.

Please find the attached copy of the Notice to Conduct Pre-Repair Survey dated 30 December 2019 together with our client's Accident Statement /Traffic Police Report and accident scene photographs for your necessary action.

Kindly acknowledge receipt hereof.

Regards,

Serene

for and on behalf of Christine Sekhon

Liberty Law Practice LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

DiD: 3152 0980

Privileged and/or confidential information may be contained in this email or its attachments. If you are not the intended recipient, you must not disclose, copy or distribute the contents therein or take any action in reliance of such contents. Communication of any information in this email or its attachments to an unauthorized person is prohibited.

Please consider the environment before printing this email



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG20000089/Kea3

22 JAN 2020

TAN CHIAH WAH
6 BUKIT TUNGGA RD
SINGAPORE 309692

Dear Sir/Madam,

ACCIDENT INVOLVING SLT 8576E AND SKT 3930K ON 21/12/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Asher Sng (LKKAUTO)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Thursday, 13 February 2020 9:03 AM
To: Asher Sng (LKKAUTO)
Subject: AIG ref: 6537228859SG-003

Follow Up Flag: Follow up
Flag Status: Completed

Dear Asher,

Kindly submit all documents onto merimen as we have received LOD from TP lawyer.

Kind Regards,
Saliha

Saliha Syed Yusoff
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16, Singapore 079120
Tel +(65) 6419 1917 |
www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Dec 2019 Edit Reg		30 Dec 2019 00:00 Edit Adj Rpt	S\$11,750.00 Edit Estimates	S\$11,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN CHIAH WAH , ID: S0101027A								
Main Claimant:	CITIPONICS PTE LTD , Co. Reg. No.: 200302380G								
Vehicle Reg. No.:	SKT3930K	Date of Loss:	21/12/2019 11:00 - :59 [54 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6537228859SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLT8576E	Policy No. (Claimant):	5110373099						
		Excess:							
Repaire:	S Three Automotive & Recovery Pte Ltd - Sin Ming (HQ) BLK 8 SIN MING IND EST #01-64/66, 575643 Sin Ming - Tel: 9766 2745								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (03/01/2020): TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKT3930K (6537228859SG)
[SLT8576E]

TP

CITIPONICS PTE LTD

Dec 21 2019 11:00AM

[TAN CHIAH WAH]

S Three Automotive & Recovery Pte Ltd - Sin Ming

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	26/02/20 10:24	General View														Load JPG	☒	
2	26/02/20 10:24	Odometer Reading														Load JPG	☒	
3	26/02/20 10:24	General View														Load JPG	☒	
4	26/02/20 10:24	General View														Load JPG	☒	
5	26/02/20 10:24	General View														Load JPG	☒	
6	26/02/20 10:24	General View														Load JPG	☒	
7	26/02/20 10:24	General View														Load JPG	☒	
8	26/02/20 10:24	General View														Load JPG	☒	
9	26/02/20 10:24	General View														Load JPG	☒	
10	26/02/20 10:24	General View														Load JPG	☒	
11	26/02/20 10:24	General View														Load JPG	☒	
12	26/02/20 10:24	General View														Load JPG	☒	
13	26/02/20 10:24	General View														Load JPG	☒	
14	26/02/20 10:24	General View														Load JPG	☒	
15	26/02/20 10:24	General View														Load JPG	☒	
16	26/02/20 10:24	General View														Load JPG	☒	
17	26/02/20 10:24	General View														Load JPG	☒	
18	26/02/20 10:24	General View														Load JPG	☒	
19	26/02/20 10:24	Chassis Number														Load JPG	☒	
20	26/02/20 10:24	General View														Load JPG	☒	
21	26/02/20 10:24	General View														Load JPG	☒	
22	26/02/20 10:24	General View														Load JPG	☒	
23	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
24	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
25	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
26	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
27	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
28	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
29	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
30	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
31	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
32	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
33	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
34	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
35	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
36	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
37	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
38	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
39	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
40	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
41	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
42	26/02/20 10:25	Reinspection Photo														Load JPG	☒	
43	26/02/20 10:25	Reinspection Photo														Load JPG	☒	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	26/02/20 10:25	Reinspection Photo		Load JPG	☒
45	26/02/20 10:26	After Repair Photo		Load JPG	☒
46	26/02/20 10:26	After Repair Photo		Load JPG	☒
47	26/02/20 10:26	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/01/20 17:55	EMAIL FROM AIG DD 30.12.19		Load PDF	
2	02/01/20 17:55	ACKNOWLEDGEMENT EMAIL TO AIG DD 30.12.19		Load PDF	
3	03/01/20 21:02	TP ESTIMATE - MARKED		Load PDF	
4	03/01/20 21:02	TP GIA REPORT		Load PDF	
5	22/01/20 10:23	LETTER TO OI		Load PDF	
6	26/02/20 10:23	EMAIL FROM AIG DD 260220		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	03/01/20 14:56	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000089/KEA3Q2

Date: 03/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SKT3930K

Insured Vehicle No : SLT8576E

Date of Loss: 21/12/2019

Nature of Claim: TP

Claim No: 6537228859SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKT3930K

Make & Model: PEUGEOT 308, 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A)

Engine No: 10XT180029716

Reg. Date: 04/06/2015 (Man. Year: 2014)

Chassis No: VF3LPHNYWES264944

Colour: Metallic Black

Odometer: 72984 km

Engine Capacity: 1199 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Continental 8 mm

Rear Left Side: Continental 8 mm

Front Right Side: Continental 8 mm

Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,436.20	12,824.50	6,611.70	34.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	1,930.00	1,910.00	49.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,276.20	14,754.50	8,521.70	36.61
Approved Total (Overridden) (S\$)		11,750.00		
Nett Amount (S\$)	23,276.20	11,750.00	11,526.20	49.52
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 30/12/2019

Date Inspected: 31/12/2019 Inspected At:

S Three Automotive & Recovery Pte Ltd - Sin Ming (HQ)
BLK 8 SIN MING IND EST #01-64/66
Singapore 575643

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE : \$58,000.00

LTA REIMBURSEMENT VALUE (RV) : \$39,838.00

NETT VALUE : \$18,162.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER SPONGE	Serviceable	185.00 FL	*- FL
2	1	*FRONT BUMPER	Torn	1,458.00 FL	*785.00 FL
3	1	*FRONT BUMPER RETAINER LH & RH	O/S Cracked	150.00 FL	*75.00 FL
4	1	*FRONT BUMPER REINFORCEMENT	Bent	590.00 FL	*482.00 FL
5	1	*FRONT BUMPER FOG LAMP COVER RH	Cracked	290.00 FL	*290.00 FL
6	1	*FRONT BUMPER LOWER GRILLE	Missing	218.00 FL	*218.00 FL
7	1	*FRONT BUMPER LOWER AIR GARNISH	Cracked	205.00 FL	*205.00 FL
8	1	*FRONT BUMPER BRACKET RH	Distorted	125.00 FL	*125.00 FL
9	1	*FRONT BUMPER TOWING COVER	Missing	58.00 FL	*58.00 FL
10	1	*RADIATOR GRILLE	Mtg Cracked	295.00 FL	*295.00 FL
11	1	*FRONT GRILLE LOGO	Necessary	78.00 FL	*78.00 FL
12	1	*FOG LAMP COVER CHROME	Cracked	220.00 FL	*220.00 FL
13	1	*FOG LAMP LED RH	Cracked	315.00 FL	*315.00 FL
14	1	*FOG LAMP BRACKET	Missing	85.00 FL	*85.00 FL
15	1	*HEADLAMP ASSY HID RH	Broken	1,150.00 FL	*1,150.00 FL
16	1	*HEADLAMP ASSY HID LH	Cracked	1,150.00 FL	*1,150.00 FL
17	1	*HEADLAMP PANEL RH	Distorted	195.00 FL	*195.00 FL
18	1	*HEADLAMP PANEL LH	Repair	195.00 FL	*- FL
19	1	*FRONT FENDER RH	Bent	555.00 FL	*362.00 FL
20	1	*FRONT FENDER INNER SHIELD RH	Cracked	138.00 FL	*138.00 FL
21	1	*FRONT SPORT RIM RH	Serviceable	1,050.00 FL	*- FL
22	1	*RADIATOR SIDE GARNISH RH	Cracked	205.00 FL	*205.00 FL
23	1	*BONNET	Bent	1,750.00 FL	*1,350.00 FL
24	1	*BONNET LOCK	Repair	85.00 FL	*- FL
25	1	*BONNET INSULATOR	Serviceable	185.00 FL	*- FL
26	1	*WASHER TANK	Dented	218.00 FL	*218.00 FL
27	1	*FRONT BRACE PANEL	Repair	105.00 FL	*- FL
28	1	*NUMBER PLATE HOLDER	Serviceable	85.00 FL	*- FL
29	1	*FRONT SUPPORT PANEL TOP COVER	Dented	288.00 FL	*288.00 FL
30	1	*FRONT SUPPORT PANEL	Cracked	598.00 FL	*598.00 FL
31	1	*AIRCON CONDENSOR	Bent	789.00 FL	*789.00 FL
32	1	*AIRCON PIPE -CONDENSOR TO COMPRESSOR	Serviceable	420.00 FL	*- FL
33	1	*RADIATOR	Housing Cracked	395.00 FL	*395.00 FL
34	1	*AIRCON PIPE-CONDENSOR TO COOLING COIL	Serviceable	330.00 FL	*- FL
35	1	*INNER COOLER	Bent	1,050.00 FL	*1,050.00 FL
36	1	*INNER COOLER INTAKE HOSE	Dented	385.00 FL	*385.00 FL
37	1	*INNER COOLER EXHAUST HOSE	Serviceable	365.00 FL	*- FL
38	1	*INNER COOLER AIR VENT	Dented	105.00 FL	*105.00 FL
39	3	*INNER COOLER BRACKET	Cracked	240.00 FL	*240.00 FL
40	1	*HEADLAMP INNER PLASTIC RETAINER RH	Cracked	135.00 FL	*135.00 FL
41	1	*RADIATOR SPARE TANK	Serviceable	285.00 FL	*- FL
42	1	*RADIATOR SPARE TANK HOSE	Serviceable	60.00 FL	*- FL
43	1	*AIR BAG SENSOR RH	Serviceable	295.00 FL	*- FL
44	1	*FRONT LOWER ARM RH	Distorted	320.00 FL	*320.00 FL
45	1	*FRONT KNUCKLE ARM RH	Bent	1,080.00 FL	*565.00 FL
46	1	*FRONT SHOCK ABSORBER RH	Bent	495.00 FL	*365.00 FL
47	1	*FRONT KNUCKLE ARM BEARING RH	Necessary	380.00 FL	*256.00 FL
48	1	*WING MIRROR ASSY RH	Serviceable	750.00 FL	*- FL
49	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
50	1	*BONNET INSULATOR CLIPS	Not Necessary	80.00 FS	*- FS
51	1	*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS
52	1	*FRONT NUMBER PLATE	Serviceable	50.00 FS	*- FS
53	1	*RADIATOR COOLANT	Necessary	80.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*FRONT TYRE RH	Serviceable	480.00 FS	*. FS
55	1		*FRONT RADIATOR GRILLE CHROME	Cracked	495.00 FL	*495.00 FL
56	1		*WASHER TANK HOSE	Dented	120.00 FL	*120.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,508.00	14,235.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,071.80	1,410.50
Total Parts (\$\$)	19,436.20	12,824.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	New	1,500.00	700.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,400.00	800.00
3	CHECK WIRING SYSTEM & RESET HEADLAMP SYS	New	120.00	30.00
4	RESPRAY TUFF KOTE ON ACCIDENT AREA	New	120.00	0.00
5	CONDUCT FULL WHEEL ALIGNMENT	New	120.00	60.00
6	R&R AIRCON CONDENSOR & TOP UP AIR CON GAS	New	150.00	100.00
7	R&R FRONT LH SUSPENSION SYSTEM	New	280.00	180.00
8	TOWING CHARGES	New	150.00	60.00
Gross Labour Cost (S\$)			3,840.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >