

Not Authorized
 U/Sing B?
 Recovery After Repair

TO :
 ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO.: SLT8576E

ESTIMATE REPORT 1st QUOTATION

JOB NO: _____

OWNER'S PARTICULAR

NAME : CITIPONICS PTE LTD

CONTACT :

ADDRESS :

LICENSE NO.: SKT3930K TRANS.:

CHASSIS NO.:

MAKE / MODEL: PEUGEOT 308

ENGINE NO.:

OWNER'S INSURER

JOB-CODE: TP

S/A: JOEY

ACCIDENT DATE: 21-Dec-19

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER SPONGE	1.00		10.00	0.00	Y	7
2 FRONT BUMPER	1.00	1.1	10.00	0.00	Y	1
3 FRONT BUMPER RETAINER LH & RH	1.00	0.15 CM	10.00	0.00	Y	4
4 FRONT BUMPER REINFORCMENT	1.00	R ₁	10.00	0.00	Y	1
5 FRONT BUMPER FOG LAMP COVER RH	1.00	CMH	10.00	0.00	Y	1
6 FRONT BUMPER LOWER GRILLE	1.00	M11	10.00	0.00	Y	1
7 FRONT BUMPER LOWER AIR GARNISH	1.00	CM	10.00	0.00	Y	1
8 FRONT BUMPER BRACKET RH	1.00		10.00	0.00	Y	7
9 FRONT BUMPER TOWING COVER	1.00	M11	10.00	0.00	Y	1
10 RADIATOR GRILLE	1.00	M11 CM	10.00	0.00	Y	1
11 FRONT GRILLE LOGO	1.00	M	10.00	0.00	Y	1
12 FOG LAMP COVER CHROME	1.00	CM	10.00	0.00	Y	1
13 FOG LAMP LED RH	1.00	CM	10.00	0.00	Y	1
14 FOG LAMP BRACKET	1.00	M11	10.00	0.00	Y	1
15 HEADLAMP ASSY HID RH	1.00	B ₁	10.00	0.00	Y	1
16 HEADLAMP ASSY HID LH	1.00		10.00	0.00	Y	?
17 HEADLAMP PANEL RH	1.00		10.00	0.00	Y	?
18 HEADLAMP PANEL LH	1.00	K	10.00	0.00	Y	X
19 FRONT FENDER RH	1.00	R ₁	10.00	0.00	Y	1
20 FRONT FENDER INNER SHILED RH	1.00	CMH	10.00	0.00	Y	1
21 FRONT SPORT RIM RH	1.00	P ₁	10.00	0.00	Y	X
22 RADIATOR SIDE GARNISH RH	1.00	.	10.00	0.00	Y	7
23 BONNET	1.00	R ₁	10.00	0.00	Y	1
24 BONNET LOCK	1.00	M	10.00	0.00	Y	X
25 BONNET INSULATOR	1.00	J ₁	10.00	0.00	Y	X
26 WASHER TANK	1.00		10.00	0.00	Y	?
27 FRONT BRACE PANEL	1.00	K	10.00	0.00	Y	X
28 NUMBER PLATE HOLDER	1.00	J ₁	10.00	0.00	Y	X

29	FRONT SUPPORT PANEL TOP COVER	1.00		10.00	0.00	Y	?
30	FRONT SUPPORT PANEL	1.00	CM	10.00	0.00	Y	✓
31	AIRCON CONDENSOR	1.00	in	10.00	0.00	Y	X
32	AIRCON PIPE - CONDENSOR TO COMPRESSOR	1.00		10.00	0.00	Y	X
33	RADIATOR	1.00		10.00	0.00	Y	?
34	AIRCON PIPE - CONDENSOR TO COOLING COIL	1.00		10.00	0.00	Y	?
35	INNER COOLER	1.00	R	10.00	0.00	Y	✓
36	INNER COOLER INTAKE HOSE	1.00		10.00	0.00	Y	?
37	INNER COOLER EXHAUST HOSE	1.00		10.00	0.00	Y	?
38	INNER COOLER AIR VENT	1.00	R	10.00	0.00	Y	✓
39	INNER COOLER BRACKET 3PCS	1.00	CM	10.00	0.00	Y	✓
40	HEADLAMP INNER PLASTIC RETAINER RH	1.00	CM	10.00	0.00	Y	✓
41	RADIATOR SPARE TANK	1.00		10.00	0.00	Y	?
42	RADIATOR SPARE TANK HOSE	1.00	in	10.00	0.00	Y	X
43	AIR BAG SENSOR RH	1.00	in	10.00	0.00	Y	X
44	FRONT LOWER ARM RH	1.00		10.00	0.00	Y	?
45	FRONT KNUCKLE ARM RH	1.00		10.00	0.00	Y	?
46	FRONT SHOCK ABSORBER RH	1.00		10.00	0.00	Y	?
47	FRONT KNUCKLE ARM BEARING RH	1.00		10.00	0.00	Y	?
48	WING MIRROR ASSY RH	1.00	in	10.00	0.00	Y	X

TOTAL (PARTS) :

0.00

0.00

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS 1SET	ME	1.00	50.00	0.00	50.00	Y	✓
2	BONNET INSULATOR CLIPS	nn	1.00	80.00	0.00	80.00	Y	X
3	FRONT FENDER INNER SHIELD CLIPS 1SET	nn	1.00	50.00	0.00	50.00	Y	✓
4	FRONT NUMBER PLATE	in	1.00	50.00	0.00	50.00	Y	X
5	RADIATOR COOLANT	nn	1.00	80.00	0.00	80.00	Y	30.00
6	FRONT TYRE RH		1.00	480.00	0.00	480.00	Y	?

TOTAL (PARTS) :

790.00

790.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA		1.00	1500.00	0.00	1500.00	Y	700
2	SPRAY PAINTING ON AFFECTED AREA		1.00	1400.00	0.00	1400.00	Y	800
3	CHECK WIRING SYSTEM & RESET HEADLAMP SYS		1.00	120.00	0.00	120.00	Y	300
4	RESPRAY TUFF KOTE ON ACCIDENT AREA	nn	1.00	120.00	0.00	120.00	Y	X
5	CONDUCT FULL WHEEL ALIGNMENT		1.00	120.00	0.00	120.00	Y	600

6	R&R AIRCON CONDENSOR & TOP UP AIR CON GAS	1.00	150.00	0.00	150.00	Y	<u>1000</u>
7	R&R FRONT LH SUSPENSION SYSTEM	1.00	280.00	0.00	280.00	Y	<u>?</u>
	TOWING CHARGES	1.00	150.00	0.00	150.00	Y	<u>600</u>

TOTAL (LABOUR) : 3840.00 3840.00

TOTAL PARTS & LABOUR 4630.00 4630.00

EXCESS : : S\$ _____

NO. OF DAY : 07 days

RE-SURVEY : BEFORE / AFTER PAINING

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 31/12/19

SURVEY BY : Kenneth

CONTACT NO : 96910663

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: