

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MR. TAN CHEE SHEN (CHEN QISHEN)
 BLK 288A PUNGGOL PLACE #12-809
 SINGAPORE 821288

TP 111

Lealia

Contact : 90905635

ESTIMATE

Repair Code : CLM15890

Date in : 26/12/2019

Vehicle Num. : SKV5309G

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1468350/HRA2178304A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON ALUMINIUM PIPE <i>Bent</i>	1	85.20	✓ 85.20
ENGINE UNDER COVER <i>torn</i>	1	285.00	✓ 285.00
FRONT BONNET <i>Not new</i>	1	961.40	X 961.40
FRONT BONNET HINGES L/R	2	56.10	✓ 112.20
FRONT BONNET INNER RUBBER	1	89.00	✓ 89.00
FRONT BONNET INNER SAFETY LOCK CATCH	1	82.80	✓ 82.80
FRONT BONNET INNER SIDE STOPPER L/R	2	7.50	✓ 15.00
FRONT BONNET INNER STAND BRACKET HOLDER	1	8.10	✓ 8.10
FRONT BONNET INNER TOP RUBBER	1	89.00	✓ 89.00
FRONT BONNET INSULATOR	1	185.50	✓ 185.50
FRONT BONNET MECHANISM LOCK	1	67.60	✓ 67.60
FRONT BUMPER <i>distorted</i>	1	717.00	✓ 717.00
FRONT BUMPER FOGLAMP GARNISH L/R <i>RH cut</i>	2	102.00	102 204.00
FRONT BUMPER LOWER REINFORCEMENT <i>Bent</i>	1	337.30	✓ 337.30
FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	675.40	✓ 675.40
FRONT BUMPER REINFORCEMENT BRACKET L/R <i>Bent RH</i>	2	145.00	145 290.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	25.90	✓ 51.80
FRONT BUMPER SPONGE (LOWER) L/R <i>torn</i>	2	97.90	✓ 195.80

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MR. TAN CHEE SHEN (CHEN QISHEN)
 BLK 288A PUNGGOL PLACE #12-809
 SINGAPORE 821288

Contact : 90905635

ESTIMATE

Repair Code : CLM15890
 Date in : 26/12/2019
 Vehicle Num. : SKV5309G
 Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
 Chassis/Eng# : SJNFEAJ11U1468350/HRA2178304A

FRONT BUMPER SPONGE (TOP) <i>cracked</i>	1	195.70	✓	195.70
FRONT BUMPER TOW HOOK COVER <i>wt</i>	1	21.20	✓	21.20
FRONT FENDER ARCH GARNISH L/R <i>LH cracked, RH wt</i>	2	483.00	✓	966.00
FRONT FENDER INNER SHIELD L/R <i>torn</i>	2	87.50	✓	175.00
FRONT FENDER L/R <i>RH Dented, LH Repair</i>	2	622.70		1,245.40 <i>622.70</i>
FRONT GRILLE <i>Missing</i>	1	461.20	✓	461.20
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	109.20	✓	109.20
FRONT HEADLAMP L/R <i>cracked.</i>	2	612.20	✓	1,224.40
FRONT HEADLAMP LOWER BRACKET L/R <i>new</i>	2	15.30	✓	30.60
FRONT HEADLAMP TOP PANEL L/R <i>Repair</i>	2	145.30	✓	290.60
FRONT SUPPORT PANEL <i>cracked.</i>	1	617.50	✓	617.50
FRONT SUPPORT PANEL SIDE GUIDE STOPPER L/R <i>new</i>	2	7.50	✓	15.00
OIL COOLANT RUBBER HOSE <i>new</i>	2	42.00	✓	84.00
RADIATOR SIDE GUIDE L/R <i>cracked</i>	2	89.60	✓	179.20
Subtotal before discount				10,067.10
Percentage discount 10%				1,006.71
Sub-total 1				9,060.39
AIR DUCT <i>Delivered</i>	1	95.90	✓	95.90

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MR. TAN CHEE SHEN (CHEN QISHEN)
BLK 288A PUNGGOL PLACE #12-809
SINGAPORE 821288

Contact : 90905635

ESTIMATE

Repair Code : CLM15890

Date in : 26/12/2019

Vehicle Num. : SKV5309G

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1468350/HRA2178304A

AIRCON CONDENSER	<i>Dented</i>	1	658.20	✓	658.20
AIRCON DISCHARGE PIPE	<i>Beit</i>	1	197.80	✓	197.80
AIRCON SUCTION PIPE	<i>Beit</i>	1	140.00	✓	140.00
ENGINE MOUNTING (FRONT)	<i>} New</i>	1	74.90	✗	74.90
ENGINE MOUNTING (REAR)		1	91.60	✗	91.60
FAN MOTOR ASSY	<i>Cabled</i>	1	621.70	✓	621.70
FRONT BONNET INSULATOR CLIPS - SET	<i>new</i>	1	80.00	✗	80.00
FRONT BONNET MECHANISM LOCK CABLE	<i>new</i>	1	43.40	✗	43.40
FRONT BUMPER CLIPS - SET	<i>new</i>	1	80.00	30	80.00
FRONT BUMPER FOGLAMP L/R	<i>PH cabled</i>	2	321.60	321.60	643.20
FRONT BUMPER NUMBER PLATE	<i>Beit</i>	1	25.00	✓	25.00
FRONT BUMPER NUMBER PLATE HOLDER	<i>new</i>	1	50.00	30	50.00
FRONT ENGINE CROSSMEMBER	<i>Beit</i>	1	674.10	✓	674.10
FRONT FENDER ARCH GARNISH CLIPS L/R - SET	<i>} new</i>	2	30.00	✓	60.00
FRONT FENDER INNER SHIELD CLIPS L/R - SET		2	40.00	60	80.00
FRONT GRILLE CLIPS - SET	<i>} Missing</i>	1	40.00	20	40.00
FRONT GRILLE TOP COVER		1	81.00	✓	81.00
FRONT HORN L/R	<i>PH cabled</i>	2	89.60	89.60	179.20

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MR. TAN CHEE SHEN (CHEN QISHEN)
 BLK 288A PUNGGOL PLACE #12-809
 SINGAPORE 821288

Contact : 90905635

ESTIMATE

Repair Code : CLM15890
 Date in : 26/12/2019
 Vehicle Num. : SKV5309G
 Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
 Chassis/Eng# : SJNFEAJ11U1468350/HRA2178304A

FRONT LOWER ARM L/R	2	249.80	X	499.60
FRONT OUTSIDE TEMPERATURE SENSOR	1	114.60	X	114.60
FRONT SHOCK ABSORBER L/R	2	560.30	X	1,120.60
FRONT SPORT RIM L/R	2	1231.90	X	2,463.80
FRONT WASHER TANK NICK	1	25.00	X	25.00
FRONT WASHER TANK WITH MOTOR	1	171.30	✓	171.30
OIL COOLER	1	567.20	✓	567.20
OIL COOLER RETURN PIPE	1	80.70	✓	80.70
RADIATOR (AUTO)	1	687.40	✓	687.40
RADIATOR COOLANT	1	60.00	40.	60.00
RADIATOR LOWER GARNISH	1	94.50	✓	94.50
RADIATOR LOWER HOSE	1	185.30	X	185.30
RADIATOR TOP HOSE	1	103.60	X	103.60
RADIATOR TOP SUPPORT	1	81.00	X	81.00
REAR AXLE	1	1322.80	X	1,322.80
TURBO INTERCOOLER	1	2121.60	✓	2,121.60
TURBO INTERCOOLER LOWER HOSE	1	417.00	X	417.00
TURBO INTERCOOLER MOUNTING	2	17.60	X	35.20

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MR. TAN CHEE SHEN (CHEN QISHEN)
 BLK 288A PUNGGOL PLACE #12-809
 SINGAPORE 821288

Contact : 90905635

ESTIMATE

Repair Code : CLM15890
 Date in : 26/12/2019
 Vehicle Num. : SKV5309G
 Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
 Chassis/Eng# : SJNFEAJ11U1468350/HRA2178304A

TURBO INTERCOOLER TOP HOSE	<i>Not new</i>	1	242.20	<i>X</i>	242.20
Subtotal before discount					14,309.40
Percentage discount	0%				0.00
	<i>6867.60</i>	Sub-total 2			14,309.40
	<i>6180.84</i>	Parts-total			23,369.79

LABOUR

To remove, change air con parts, vacuums, refill air con gas		120	140.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)		30	100.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.		320	400.00
To remove, change rear suspension parts, axle carriage absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.		<i>X</i>	380.00
To road test driving, check and resetting wheel alignments system.	<i>2400</i>	80	140.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.		<i>9w</i>	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.		<i>9w</i>	1,100.00
To apply anti-rust chemical on repaired and replaced panel.		50	140.00
Labour Total			3,600.00
Parts & Labour Total			26,969.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total 15030.78
h/s 12K.
08 Days