

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5660B**AAD1912-158***Not Authenticated*
11 Sep & 2030h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5660B

VF1ABL15AUC281153

RENAULT

LATITUDE

22.12.19

AIG

24/12/2014

31 DEC 2019

PART		LIST
1	DOOR PANEL REAR RH	\$ 758.70 ✓
1	DOOR GUIDE REAR RH	\$ 136.40
1	DOOR SEAL REAR RH	\$ 119.80
1	DOOR WHEATHERSTRIP REAR RH	\$ 311.60
1	DOOR HANDLE OUTER REAR RH L70Y	\$ 42.10
1	DOOR HANDLE CAP REAR RH L70Y	\$ 57.90
1	DOOR HANDLE MODULE REAR RH L70Y	\$ 111.00
1	DOOR LOCK REAR RH L70Y	\$ 467.30
1	DOOR REGULATOR REAR RH L70Y	\$ 758.10
1	DOOR REGULATOR MOTOR REAR RH L70Y	\$ 450.60
1	DOOR GLASS RUNNER SEAL REAR RH L70Y	\$ 116.10
1	DOOR WAIST SEAL OUTER REAR RH L70Y	\$ 99.40
1	DOOR BLIND REAR RH	\$ 506.90
1	DOOR HARNESS WIRE RH	\$ 2,670.00
1	ROCKER PANEL INNER GARNISH RH	\$ 466.51
1	ROCKER PANEL INNER RH	\$ 1,024.79
1	ROCKER PANEL OUTER RH	\$ 1,184.99
1	ROCKER PANEL CENTER RH	\$ 990.25
1	FENDER PANEL REAR RH	\$ 1,933.20
1	FENDER PANEL INNER TRIM REAR RH	\$ 671.45
1	WHEELARCH REAR RH	\$ 275.40
1	BUMPER COVER REAR	\$ 561.70
1	BUMPER LOWER REAR	\$ 411.90
1	BUMPER BRACKET SIDE RH REAR	\$ 82.10
1	BUMPER RETAINER RH REAR	\$ 59.80
1	BUMPER REFLECTOR RH	\$ 16.60
1	TAILLAMP RH	\$ 313.10
1	TAILLAMP PANEL RH	\$ 401.40
1	BOOT REFLECTOR LAMP RH	\$ 277.70
1	EXHAUST CAP REAR	\$ 125.40
1	KNUCKLE ARM REAR RH	\$ 472.10

Trans-cab Auto Services Pte Ltd**AAD1912-158**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5660B

1	BRAKE DISC REAR	\$	266.50
1	KNUCKLE HUB+ BEARING RH	\$	272.30
1	ABSORBER REAR	\$	217.30
1	LOWER ARM REAR RH	\$	543.50
1	AXLE SPRING ARM RH	\$	220.60
1	SUBFRAME ARM REAR	\$	198.33
1	RODE- LONG REAR	\$	120.16
1	WHEEL HUB NUT	\$	41.80
1	WHEEL HUB CAP	\$	30.50
1	REAR AXLE	\$	3,469.00
1	ABS SENSOR REAR RH	\$	190.50
1	STABILIZER BAR REAR	\$	427.90
1	STABILIZER LINK REAR	\$	55.20
1	BRAKE CALIPER REAR RH	\$	659.10

*Surx***TOTAL \$ 22,586.98****10% \$ 2,258.70****\$ 20,328.28****Special Nett**

1	DOOR CHECK BOLT	\$	22.69
1	DOOR GUIDE SCREW	\$	10.85
1	DOOR HINGE BOLT	\$	10.85
1	DOOR HINGE NUT RH	\$	14.60
1	DOOR CHECK BOLT	\$	22.69
1	DOOR CHECK NUT	\$	3.75
1	DOOR LOCK SCREW L70Y	\$	6.12
1	REAR RIGHT TYRE	\$	300.00
1	REAR RIGHT TYRE RIM	\$	380.00
1	REAR DOOR STICKER "6555-3333"	\$	100.00
2	REAR WINDSCREEN SEALANT	\$	80.00
1	WINDSCREEN MOULDING	\$	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00
1	FENDER INNER TRIM CLIP RH	\$	28.00
1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00
1SET	PARKING AID	\$	700.00
1SET	REAR BUMPER CLIP	\$	66.00
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00
1SET	BUMPER RETAINER CLIP RH RR	\$	20.00
1SET	BUMPER LOWER REAR RIVET	\$	22.00
1SET	BUMPER LOWER REAR CLIP	\$	66.00

*X**X**✓**both**X*

Trans-cab Auto Services Pte Ltd**AAD1912-158**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5660B

1	TAILLAMP CLIP RH	\$	nn	5.00	X
1	EXHAUST MOUNTING REAR	\$	nn	16.00	X
1	Rear Bumper Protector	\$	nn	100.00	X
TOTAL		\$		2,219.57	

TOTAL PARTS \$ 22,547.85**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 7,500.00 500

Putty and spray painting of the affected portion.

\$ 7,500.00 660

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 80

To check steering geometry and computer wheel alignment

\$ 220.00 60

To transfer of tire, rim and on wheel balancing.

\$ 170.00 20

To Check Electrical Lighting Concerned.

\$ 170.00 20

To transfer of Rear Fender fittings, attachment and perform water seepage test.

\$ 170.00 X

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ 170.00 60

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ nn 380.00 X

To rust-proofing of the affected areas.

\$ 170.00 30

To reinstall rear bumper parking sensor.

\$ nn 170.00 X

To transfer of Rear Bumper fittings, attachment and perform water seepage test.

\$ nn 170.00 X

rans-cab Auto Services Pte Ltd**AAD1912-158**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5660B

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	h 380.00	X
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	h 380.00	X
To repair and realign rear exhaust pipe.	\$	h 170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	h 380.00	X
TOTAL	\$	18,650.00	
Over All Total	\$	41,197.85	

LUMP SUM (REPAIR DAY)**25 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: