

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 637L**AAD1912-195***Not Authored
L/Sing & 7150h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

31 DEC 2019

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF 637L

VF1ABL15AUC278290

RENAULT

LATITUDE

27.12.19

CHINA TAIPING

27-06-14

PART	
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER BRACKET FRT RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	FRONT BRACE PANEL
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	BONNET INSULATOR
1	BONNET STRUT RH
1	BONNET HINGE RH
1	BONNET LOCK

LIST	
\$	Buclaw 747.20 —
\$	SL 344.70 X
\$	SL 394.68 X
\$	Dis 101.40 —
\$	SL 10.70
\$	SL 292.50
\$	SL 147.00
\$	SL 207.21
\$	N 663.70 X
\$	SL 743.60
\$	N 128.30
\$	N 437.10
\$	SL 191.40 —
\$	SL 11.80
\$	N 106.40
\$	SL 66.30
\$	SL 60.90
\$	N 177.22
\$	SL 969.90
\$	SL 225.36 X
\$	SL 686.00
\$	SL 592.70
\$	N 41.60
\$	N 1,312.70
\$	SL 294.30
\$	SL 53.30
\$	SL 237.40
\$	N 152.80

Trans-cab Auto Services Pte Ltd**AAD1912-195**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 637L

1	BONNET CABLE	\$	55.20
1	BONNET CABLE COVER	\$	80.60
1	BONNET SEAL OUTER	\$	83.20
1	BONNET SEAL INNER	\$	70.10
1	LOWER ARM RH L70Y	\$	192.70
1	KNUCKLE ARM RH L70Y	\$	481.50
1	ABSORBER FRT RH L70Y	\$	203.50
1	DRIVESHAFT RH	\$	1,355.70
1	STABILIZER BAR FRT	\$	427.90
1	WIPER RESERVOIR MOTOR	\$	82.60
1	WIPER RESERVOIR	\$	179.60
1	WIPER RESERVOIR NECK	\$	29.30

TOTAL \$ 12,640.07
10% \$ 1,264.01
\$ 11,376.06

Special Nett

1	BUMPER CLIP FRT	\$	66.00
1	BUMPER BRACKET CLIP FRT RH	\$	12.00
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50
1	BUMPER GRILLE LOWER CLIP	\$	69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00
1	WHEELARCH CLIP FRT RH	\$	30.50
1	FRONT RIGHT TYRE	\$	300.00
1	FRONT RIGHT TYRE RIM	\$	380.00
1SET	Front licence plate with holder	\$	80.00
1SET	RADIATOR GRILLE SCREW	\$	16.00
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00
6	BONNET INSULATOR CLIP L70Y	\$	7.30
2	BONNET CABLE COVER SCREW L70Y	\$	10.85
2	BONNET CABLE CLIP L70Y	\$	6.31

TOTAL \$ 1,160.47

TOTAL PARTS \$ 12,536.53

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 637L**AAD1912-195****LABOUR**

Putty and spray painting of the affected portion.	\$	6,000.00	2201
To Check Electrical Lighting Concerned.	\$	170.00	101
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	2001
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na 170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	4 170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	4 380.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	4 380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 637L**AAD1912-195**

To rust-proofing of the affected areas.

	\$	<i>nn</i>	170.00	X
TOTAL	\$		14,760.00	

Over All Total	\$	27,296.53
-----------------------	----	------------------

LUMP SUM (REPAIR DAY)~~20~~ **DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: