

ASSIGNMENT

Surveyor:

MARCUS

DOI: 06/01/2020

Date / Time: 02.01.2020

Registered in Merimen: 02.01.2020

Pre-assign / CCU / FTE



Insured Vehicle No.: SKN 7335J

Claim No.: 1202000000116

Name of Insured: NG SIK SUAN

Policy No.: PNPV2019-00011857

Insured Tel No.: HP: +65-90018361

Make / Model: CITROEN C4 PICASSO 1.6i EHD ETG6 5 SEATER

Excess Sec II: S\$ D.O.A: 30/12/2019 15:15

Place of Accident: ALONG NORTH BRIDGE ROAD

Is driver the owner? (YES / NO) Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final ? Yes / No

SJS 2082G

INSRS:
WSP: Nineteen
Tel: Autowerks
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
SJS 2082G	Non-Reporting ltr (1st):	
SKN 7335J NA/INC19022968/z4; DOA: 30.12.19	Non-Reporting ltr (2nd):	
- NA/CTI17006422/h4; DOA: 01.04.2017	Non-Reporting ltr (Final):	
- CC6/CTI16024349/Kza3n2; DOA: 14.12.2016	Notification ltr (if non-pickup):	
	Call OI	
	After call ltr to OI	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	
Repair Cost: 867	SS 400.40 (2 days) Reduction: 400.45 = 14	Confirm by: MARCUS
FINAL SETTLEMENT Date/Time: 18/3/2020	Confirm with: JENNY	
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 21	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Repair Cost: S\$ 400.00	If NO or B 28, Ass. Lia:	
Loss of Rental (LOR): S\$ 200.00 (2 days) x \$100	COPY SENT 18/3/2020	
Loss of Use (LOU): S\$ - (\$ x days)		
Loss of Income (LOI): S\$ - (\$ x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> (Tick only one)		
GIA/LTA Search: S\$ 2.45	1) Claim status: Normal/Reject/Private Settle	
Medical: S\$ -	2) Report Format: TP	
Disbursement: S\$ - (e.g. Tow/ Independent)	3) Survey fee: \$500/-	
Legal Cost: S\$ -		
Total: S\$ 607.45	Global Sum S\$:	
FINAL PAYMENT Date/Time:	Confirm with:	
Payee 1: S\$ 607.45	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Payee 2: (Strike if N.A.) S\$	Name 1: Nineteen Autowerks Pte Ltd	
Payee 3: (Strike if N.A.) S\$	Name 2:	
	Name 3:	

M forgoe charges
w/ offeners amount
- LOR issue.

REP: FWD

ASSIGNMENT

From: _____ Date: 06/01/2020
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SJS 2082G
 at Workshop n/s Nineteen Autoworks
 of 15 Kaki Bukit Road 4 # 01-53
 Insured: _____
 Policy No. 12pm.
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 26k.
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res: Yes or No
 Lim Sum: 1.5-1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1up 279x
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJS 2082G Vn Regs: 3/8 09
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Toyota Corolla A1415 cc 1598
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 232090 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRO537EE106151244
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / R/Rim / STD A/Rim or
 Tyre Size: F: 185/55-15 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: R/Bal: 6 mm L/Bal: 6 mm
 Rear: R/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 6/1/20

Survey held at: _____
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
 Rec
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
02 2-8-2024	LTA 13410
	P/P #400. (Red: #6547.95 / 941.)

Date/Time, File Pass to: ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

5+PS: 31

Phone: _____

Office: _____

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Insp (\$) ☐ : Wheel track (\$)

Report Format: _____

Lump Sum / A/E/C: _____




NINETEEN
AUTOWERKS

FWD 9
no collect.

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com



not Allowed
dhr

6 January 2020

P/P 400?
2 Jy.

REG NO.: SJS 2082 G
MAKE/MODEL: TOYOTA COROLLA ALTIS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Rear boot lid	\$ 17 778.20 X
2	Rear boot hinges	\$ 17 173.80 X
1	Rear boot inner lock	\$ 17 166.80 X
1	Rear boot weatherstrip	\$ 17 165.60 X
1	Rear boot "COROLLA" emblem	\$ 17 45.30 X
1	Rear boot "ALTIS" emblem	\$ 17 42.50 X
1	Rear boot "1.6" emblem	\$ 17 38.40 X
2	Rear taillamps	\$ 17 781.90 X
1	Rear end panel	\$ 17 762.60 X
1	Rear end panel inner garnish	\$ 17 192.50 X
1	Rear bumper	\$ 17 560.60 X
2	Rear bumper side brackets	\$ 17 97.00 X
2	Rear bumper reflectors	\$ 17 151.00 X
2	Rear bumper side retainers	\$ 17 131.00 X
1	Rear floor board	\$ 17 363.40 X
		\$ 4,450.60
	Less 25%	\$ 1,112.65
		\$ 3,337.95
SPECIAL NETT ITEMS		
1	Rear bumper clip (1 set)	\$ 17 50.00 X
1	Rear reverse sensor (1 set)	\$ 17 350.00 X
		\$ 400.00
LABOUR CHARGES		
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 17 80.00 X
2	To remove and refit inner garnishes.	\$ 17 150.00 X
3	To remove and refit rear reverse sensor.	\$ 17 150.00 X
4	To transfer boot lid mechanism and wiring assembly.	\$ 17 80.00 X
5	To apply undercoating.	\$ 17 150.00 X
6	Panel beating.	\$ 1,400.00 200
7	To re-spray painting on the affected areas.	\$ 1,200.00 200
		\$ 3,210.00
GRAND TOTAL :		\$ 6,947.95

FWD S
no collect.

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

6 January 2020

REG NO.: SJS 2082 G
MAKE/MODEL: TOYOTA COROLLA ALTIS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Rear boot lid	\$ 778.20 X
2	Rear boot hinges	\$ 173.80 X
1	Rear boot inner lock	\$ 166.80 X
1	Rear boot weatherstrip	\$ 165.60 X
1	Rear boot "COROLLA" emblem	\$ 45.30 X
1	Rear boot "ALTIS" emblem	\$ 42.50 X
1	Rear boot "1.6" emblem	\$ 38.40 X
2	Rear taillamps	\$ 781.90 X
1	Rear end panel	\$ 762.60 X
1	Rear end panel inner garnish	\$ 192.50 X
1	Rear bumper	\$ 560.80 X
2	Rear bumper side brackets	\$ 97.00 X
2	Rear bumper reflectors	\$ 151.00 X
2	Rear bumper side retainers	\$ 131.00 X
1	Rear floor board	\$ 363.40 X
		\$ 4,450.60
	Less 25%	\$ 1,112.65
		\$ 3,337.95

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	\$ 50.00 X
1	Rear reverse sensor (1 set)	\$ 350.00 X
		\$ 400.00

LABOUR CHARGES

S/N	DESCRIPTION	AMT(\$)
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 X
2	To remove and refit inner garnishes.	\$ 150.00 X
3	To remove and refit rear reverse sensor.	\$ 150.00 X
4	To transfer boot lid mechanism and wiring assembly.	\$ 80.00 X
5	To apply undercoating.	\$ 150.00 X
6	Panel beating.	\$ 1,400.00
7	To re-spray painting on the affected areas.	\$ 1,200.00
		\$ 3,210.00

GRAND TOTAL:

2 days

\$ 6,947.95

PAGE 1 OF 1

08/11/2019 12:11

208244802

NINETEEN AUTO PTE LTD



NINETEEN
AUTOWERKS

FWD S
no collect.

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

6 January 2020

REG NO.: SJS 2082 G
MAKE/MODEL: TOYOTA COROLLA ALTIS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
LIST ITEMS		
1	Rear boot lid	\$ 778.20 X
2	Rear boot hinges	\$ 173.80 X
1	Rear boot inner lock	\$ 166.80 X
1	Rear boot weatherstrip	\$ 165.60 X
1	Rear boot "COROLLA" emblem	\$ 45.30 X
1	Rear boot "ALTIS" emblem	\$ 42.50 X
1	Rear boot "1.6" emblem	\$ 38.40 X
2	Rear taillamps	\$ 781.90 X
1	Rear end panel	\$ 762.60 X
1	Rear end panel inner garnish	\$ 192.50 X
1	Rear bumper	\$ 560.60 X
2	Rear bumper side brackets	\$ 97.00 X
2	Rear bumper reflectors	\$ 151.00 X
2	Rear bumper side retainers	\$ 131.00 X
1	Rear floor board	\$ 363.40 X
		\$ 4,450.60
Less 25%		\$ 1,112.65
		\$ 3,337.95

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	\$ 50.00 X
1	Rear reverse sensor (1 set)	\$ 350.00 X
		\$ 400.00

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 X
2	To remove and refit inner garnishes.	\$ 150.00 X
3	To remove and refit rear reverse sensor.	\$ 150.00 X
4	To transfer boot lid mechanism and wiring assembly.	\$ 80.00 X
5	To apply undercoating.	\$ 150.00 X
6	Panel beating.	\$ 1,400.00
7	To re-spray painting on the affected areas.	\$ 1,200.00
		\$ 3,210.00

GRAND TOTAL :

2 days.

\$ 6,947.95

PAGE 1 OF 1

08/11/2019 12:10

1086444802

From JAB AUTO PTE LTD

[Advanced Search](#)

Home > Used Cars > 1axis > Toyota Corolla Altis 1.6A (COE till 08/2024)

Toyota Corolla Altis 1.6A (COE till 08/2024)

- [Overview](#) [Financial](#) [Insurance](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)



Price	\$29,800		
Depreciation	\$6,410 /yr	Reg Date	31-Aug-2009 (4yrs 7mths 24days COE left)
Mileage	102,000 km (9.8k /yr)	Manufactured	2009
Road Tax	\$816 /yr	Transmission	Auto
Dereg Value	\$13,644 as of today (change)	OMV	\$17,853
COE	\$14,664	ARF	\$17,853
Engine Cap	1,598 cc	Power	80.0 kW (107 bhp)
Curb Weight	1,195 kg	No. of Owners	3

Type of Vehicle Mid-Sized Sedan

Features

Fuel Efficient And Powerful 1.6L 16 Valve DOHC VVT-I Engine, Smooth Auto Transmission With ECT, Dual SRS Airbags, ABS, Digital Climate Control Aircon. View specs of the Toyota Corolla Altis (2008-2013)

Accessories

Leather Seats, Factory Fitted Audio, Solar Film, Remote Alarm, Reverse Sensors, Knockdown Rear Seats, Fog Lamps, Retractable Side Mirrors.

Description

100% Loan Available. With Our Flexible In House Loan! Free Elegant Silver With Classical Beige Leather Seats. Well Maintained By Previous Owner. Excellent Condition! Call Our Friendly Salesperson Now Or Walk In For Viewing With No Obligations!

Category

COE Car, Low Mileage Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

[Compare](#)



Price Chart

Summary

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

1axis

47 vehicles for sale. 81 sold in past 3 mths.

5 Yishun Industrial Street 1 #01-18
North Spring Bizhub
[Search cars nearby](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	279X
Vehicle Details	
Vehicle No.:	SJS2082G
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4918361
Chassis No.:	MR053ZEE106151244
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	03 Aug 2009
First Registration Date:	03 Aug 2009
Transfer Count:	4
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Aug 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,664.00
COE Rebate Amount:	\$13,410.00
Total Rebate Amount:	\$13,410.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Jan 2020

0049/963
Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Thursday, 2 January 2020 10:53 AM
To: 'admin-d@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: eileen.bay@fwd.com; motorclaims.sg@fwd.com
Subject: Pre-Repair Inspection for SJS 2082 G // Accident on 30/12/2019 @ 15:20HR at along North Bridge Road, involving Vehicle Number SJS 2082 G and SKN 7335 J

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen .

Kindly upload all correspondence emails/documents sent to you into Merimen.


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Nineteen Autowerks [mailto:nineteenautowerks@gmail.com]
Sent: Thursday, January 2, 2020 9:39 AM
To: Venessa Chan - SGUser
Cc: Eileen Bay - SGUser; Motor Claims SG - SG Common
Subject: Re: Pre-Repair Inspection for SJS 2082 G // Accident on 30/12/2019 @ 15:20HR at along North Bridge Road, involving Vehicle Number SJS 2082 G and SKN 7335 J

Dear All,

Kindly appoint surveyor from LKK Auto Consultants.
Thank you.

On Thu, 2 Jan 2020 at 9:27 AM, <venessa.chan@fwd.com> wrote:
| WITHOUT PREJUDICE

12.09pm @ 21/1/2020
A. Jeremy
v. Not In

Dear Jeremy,

Refer to your email dated on 31.12.2019 of the PRI Notice of your client's vehicle SJS2082G;

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.**

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Nineteen Autowerks [mailto:nineteenautowerks@gmail.com]

Sent: Tuesday, December 31, 2019 1:26 PM

To: Motor Claims SG - SG Common

Subject: Pre-Repair Inspection for SJS 2082 G // Accident on 30/12/2019 @ 15:20HR at along North Bridge Road, involving Vehicle Number SJS 2082 G and SKN 7335 J

Dear Sir/Madam,

We are instructed by TZR KARX RENTAL to notify you of a road traffic accident on 30/12/2019 at about 15:20HR at along North Bridge Road involving our client's vehicle registration number SJS 2082 G and vehicle registration number SKN 7335 J driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9270 5882, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 417808.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Cecilia Chong (LKK Auto)

From: Nineteen Autowerks <nineteenautowerks@gmail.com>
Sent: Wednesday, 26 February 2020 2:39 PM
To: Cecilia Chong (LKK Auto)
Subject: Re: YOUR REF: SJS 2082G (OUR REF: CC4/FWD20000099/Uga3) *** ACCIDENT INVOLVING SKN 7335J & SJS 2082G ON 30/12/2019 ***

Dear Cecilia,

The attached rental form is the invoice.

Best Regards,

Jeremy Tan
+65 9270 5882

On Wed, 26 Feb 2020 at 2:27 PM, Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Jeremy,

Kindly let us have a copy of Rental invoice to justify the LOR.

Thanks

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Print Received Message

This mail is associated with :

*SJS2082G (1202000000116)
[SKN7335J]
TP
TZR KARX RENTAL
Dec 30 2019 3:00PM
[Ng Sik Suan]
Nineteen Autowerks Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 06/03/2020 10:15 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$607.45) - SJS2082G - Claim Handler: Clara Li Zi Rong

Approved:607.45.

You are returning to a previous page. This page may be outdated.
Please click 'Refresh' to refresh the page.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2020 Edit Reg		02 Jan 2020 00:00 Edit Adj Rpt	S\$400.00 Edit Estimates	S\$400.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

Ng Sik Suan, ID: S1484542I

Main Claimant:

TZR KARX RENTAL, Co. Reg. No.: 53376279X

Vehicle Reg. No.:

SJS2082G

Date of Loss:

30/12/2019 15:00 - :59
[124 Months and 27 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 1202000000116

Policy/Cover Note No.:

PNPV2019-00011857 (Comprehensive)
Coverage: 15/07/2019 - 14/07/2020

Vehicle Reg. No. (Insured):

SKN7335J

Policy No. (Claimant):

S102405135-01

Excess:

Repairer:

Nineteen Autowerks Pte Ltd (HQ) BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE, 417808 Kaki Bukit - Tel: 94507920

Handling Insurer:

FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]

Claimant's Insurer:

NTUC Income Insurance Co-operative Ltd (HQ) - Tel:

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 13/01/2020]

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- FWD_SG (06/03/2020): Alert - Adj Mandate Approved (S\$607.45) - SJS2082G - Claim Handler: Clara Li Zi ...
- FWD_SG (06/03/2020): Alert - Adj Mandate Revoked - SJS2082G - Claim Handler: Clara Li Zi Rong
- FWD_SG (13/01/2020): Alert - Adj Mandate Maintained - SJS2082G - Claim Handler: Eileen Bay
- FWD_SG (10/01/2020): expedite adjuster report

ALL ASSOCIATED TASKS

















[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS2082G (1202000000116)
[SKN7335J]
TP
TZR KARX RENTAL
Dec 30 2019 3:00PM
[Ng Sik Suan]
Nineteen Autowerks Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Letters/Correspondences									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown										Edit		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	15/01/20 10:10	Adjuster Immediate Advice										Load HTM		
2	15/01/20 10:47	Adjuster Immediate Advice										Load HTM		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
2	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
3	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
4	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
5	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
6	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
7	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
8	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
9	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
10	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
11	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
12	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
13	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
14	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
15	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
16	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
17	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
18	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
19	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
20	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
21	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
22	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
23	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
24	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
25	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
26	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
27	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
28	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
29	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
30	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
31	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
32	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
33	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
34	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		
35	14/01/20 18:30	General View										Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	14/01/20 18:30	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/01/20 18:30	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/01/20 18:30	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/01/20 18:30	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/01/20 18:30	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/01/20 18:30	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/01/20 18:30	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/01/20 18:30	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/01/20 18:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/01/20 18:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/01/20 18:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/01/20 18:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/01/20 18:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/01/20 18:31	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/20 19:02	ACKNOWLEDGEMENT EMAIL TO FWD DD 02.01.2020	 Load PDF	
2	02/01/20 19:02	EMAIL - FWD TO OI DD 02.01.2020	 Load PDF	
3	02/01/20 19:02	EMAIL - WKSP TO FWD DD 02.01.2020	 Load PDF	
4	15/01/20 10:09	TP ESTIMATE - MARKED	 Load PDF	
5	26/02/20 14:27	LOA	 Load PDF	
6	26/02/20 14:27	LOD	 Load PDF	
7	26/02/20 14:27	LTA SEARCH INVOICE	 Load PDF	
8	26/02/20 14:27	RENTAL AGREEMENT	 Load PDF	
9	26/02/20 14:27	TAX INVOICE	 Load PDF	
10	26/02/20 15:01	EMAIL FROM TP ON RENTAL INVOICE	 Load PDF	
11	28/02/20 11:06	WORKSHOP INVOICE	 Load PDF	
12	19/03/20 09:52	Release Voucher	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	03/01/20 09:56	SKN7335J OI GIA	 Load PDF	
2	03/01/20 09:56	SJS2082G TP GIA	 Load PDF	
3	13/01/20 17:39	Accident Scene Photos 1	 Load JPG	<input checked="" type="checkbox"/>
4	13/01/20 17:39	Accident Scene Photos 2	 Load JPG	<input checked="" type="checkbox"/>
5	13/01/20 17:39	Accident Scene Photos 3	 Load JPG	<input checked="" type="checkbox"/>
6	13/01/20 17:39	Accident Scene Photos 4	 Load JPG	<input checked="" type="checkbox"/>
7	13/01/20 17:39	Accident Scene Photos 5	 Load JPG	<input checked="" type="checkbox"/>
8	13/01/20 17:39	Accident Scene Photos 6	 Load JPG	<input checked="" type="checkbox"/>
9	13/01/20 17:39	Accident Scene Photos 7	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKN7335J (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SJS2082G (TP veh)		1.6 (A)
Date of Accident:	30/12/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	8,947.95
Final Repair Cost	:	\$	400.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	200.00 2 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	607.45
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability <u>100</u> (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No:	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Nineteen Autowerks Pte Ltd	:	\$ 607.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

19 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20000099/UGA3Q2

Date: 19/03/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00011857

Claimant Vehicle No : SJS2082G Insured Vehicle No : SKN7335J

Date of Loss: 30/12/2019 Nature of Claim: TP Claim No: 1202000000116

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS2082G
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4918361
 Reg. Date: 03/08/2009 (Man. Year: 2009) Chassis No: MR053ZEE106151244
 Colour: Grey Odometer: 232090 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,737.95	0.00	3,737.95	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	400.00	2,810.00	87.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,947.95	400.00	6,547.95	94.24
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		607.45		

INSPECTION

Date of Assignment: 02/01/2020

Date Inspected: 06/01/2020 Inspected At:

Nineteen Autowerks Pte Ltd (HQ)
 BLK 15 KAKI BUKIT ROAD 4 #01-53
 BARTLEY BIZ CENTRE
 Singapore 417808

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g...> 19/3/2020

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS2082G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	778.20 FL	*- FL
2	2		*REAR BOOT HINGES	Not Necessary	173.80 FL	*- FL
3	1		*REAR BOOT INNER LOCK	Not Necessary	166.80 FL	*- FL
4	1		*REAR BOOT WEATHERSTRIP	Not Necessary	165.60 FL	*- FL
5	1		*REAR BOOT COROLLA EMBLEM	Not Necessary	45.30 FL	*- FL
6	1		*REAR BOOT ALTIS EMBLEM	Not Necessary	42.50 FL	*- FL
7	1		*REAR BOOT 1.6 EMBLEM	Not Necessary	38.40 FL	*- FL
8	2		*REAR TAILLAMPS	Not Necessary	781.90 FL	*- FL
9	1		*REAR END PANEL	Not Necessary	762.60 FL	*- FL
10	1		*REAR END PANEL INNER GARNISH	Not Necessary	192.50 FL	*- FL
11	1		*REAR BUMPER	Repair	560.60 FL	*- FL
12	2		*REAR BUMPER SIDE BRACKETS	Not Necessary	97.00 FL	*- FL
13	2		*REAR BUMPER REFLECTORS	Not Necessary	151.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	131.00 FL	*- FL
15	1		*REAR FLOOR BOARD	Not Necessary	363.40 FL	*- FL
16	1		*SET REAR BUMPER CLIP	Not Necessary	50.00 FS	*- FS
17	1		*SET REAR REVERSE SENSOR	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	4,850.60	0.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,112.65	0.00
Total Parts (\$\$)	3,737.95	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	0.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	0.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	0.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	80.00	0.00
5	TO APPLY UNDERCOATING	New	150.00	0.00
6	PANEL BEATING	New	1,400.00	200.00
7	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	200.00
Gross Labour Cost (S\$)			3,210.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >