



**NINETEEN**  
AUTOWERKS

FWD S  
no collect.

## NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05  
Bartley Biz Centre, Singapore 417807  
Tel: (65) 9270 5882  
nineteenautowerks@gmail.com

6 January 2020

REG NO.: SJS 2082 G  
MAKE/MODEL: TOYOTA COROLLA ALTIS

### ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY | DESCRIPTION                  | AMT(S\$)    |
|-----|------------------------------|-------------|
|     | <b>LIST ITEMS</b>            |             |
| 1   | Rear boot lid                | \$ 778.20 X |
| 2   | Rear boot hinges             | \$ 173.80 X |
| 1   | Rear boot inner lock         | \$ 166.80 X |
| 1   | Rear boot weatherstrip       | \$ 165.60 X |
| 1   | Rear boot "COROLLA" emblem   | \$ 45.30 X  |
| 1   | Rear boot "ALTIS" emblem     | \$ 42.50 X  |
| 1   | Rear boot "1.6" emblem       | \$ 38.40 X  |
| 2   | Rear taillamps               | \$ 781.90 X |
| 1   | Rear end panel               | \$ 762.60 X |
| 1   | Rear end panel inner garnish | \$ 192.50 X |
| 1   | Rear bumper                  | \$ 560.60 X |
| 2   | Rear bumper side brackets    | \$ 97.00 X  |
| 2   | Rear bumper reflectors       | \$ 151.00 X |
| 2   | Rear bumper side retainers   | \$ 131.00 X |
| 1   | Rear floor board             | \$ 363.40 X |
|     |                              | \$ 4,450.60 |
|     | Less 25%                     | \$ 1,112.65 |
|     |                              | \$ 3,337.95 |

### SPECIAL NETT ITEMS

|   |                             |             |
|---|-----------------------------|-------------|
| 1 | Rear bumper clip (1 set)    | \$ 50.00 X  |
| 1 | Rear reverse sensor (1 set) | \$ 350.00 X |
|   |                             | \$ 400.00   |

### LABOUR CHARGES

|   |                                                             |             |
|---|-------------------------------------------------------------|-------------|
| 1 | To remove, replaced damaged lamps and check up rear wiring. | \$ 80.00 X  |
| 2 | To remove and refit inner garnishes.                        | \$ 150.00 X |
| 3 | To remove and refit rear reverse sensor.                    | \$ 150.00 X |
| 4 | To transfer boot lid mechanism and wiring assembly.         | \$ 80.00 X  |
| 5 | To apply undercoating.                                      | \$ 150.00 X |
| 6 | Panel beating.                                              | \$ 1,400.00 |
| 7 | To re-spray painting on the affected areas.                 | \$ 1,200.00 |
|   |                                                             | \$ 3,210.00 |

GRAND TOTAL:

2 days.

\$ 6,947.95

PAGE 1 OF 1

06/11/2018 12:15

10:68444802

FROM JAE AUTO PTE LTD