

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SMQ1707U

TP/FC

M/S: MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848
 ATTN: Motor Claim Department

FAX: 65073849

Estimate No: ES1992427/YISHUN

Date: 30 Dec 2019

Policy No: 5113604251

Veh Reg No: SMQ1707U

Make/Model: HONDA FIT 1.3GF
 PACKAGE

Chassis No: GK33419753

Engine No: L13B3934245

Reg. Date: 31/10/2019

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 26/12/2019

TP Veh Reg No: SHC7151R

Not with hold

Repairing 134 paint

\$5204.48 6 days

Estimate Repair Cost to Vehicle No :SMQ1707U

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	710.30	1 PC	710.30	✓
2 REAR BUMPER SIDE RETAINERS	17.60	2 PCS	35.20	✓
3 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
4 REAR TAILGATE	850.60	1 PC	850.60	✓
5 TAILGATE EMBLEM (FIT)	35.00	1 PC	35.00	✓
6 TAILGATE INNER LOCK	131.80	1 PC	131.80	✓
7 TAILGATE INNER RUBBER	92.30	1 PC	92.30	✓
8 TAILLAMPS	422.70	2 PCS	845.40	✓
9 REAR END PANEL	378.40	1 PC	378.40	✓
10 REAR END PANEL INNER TOP GARNISH	120.80	1 PC	120.80	✓
			3,223.20	
	Less 20%		644.64	2,578.56
Special Net				
11 REVERSE SENSOR	200.00	1 SET	200.00	✓
12 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
			240.00	240.00
Labour				
13 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
14 PANEL BEATING INCLUDE KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT	900.00	1 LA	900.00	700 800
15 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDER, TAILGATE, REAR BUMPER	900.00	1 LA	900.00	750 800
16 RUSTPROOFING	30.00	1 LA	30.00	✓
17 REMOVE & REFIX REVERSE CAMERA	50.00	1 LA	50.00	✓
			1,980.00	1,980.00

b4p 1m rear spare tyre part top coat 80/sml

Supp

1m rear wls moulding 24131 ✓

1m rear bumper centre lower garnish \$130.60 ✓

1m rear RH fender inner garnish \$260.30 ✓

1pc rear smart key sensor \$85.50 ✓

Total SS \$4,798.56
 Add GST @ 7% 335.90
 Total Amount Payable SS \$5,134.46

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

less 20%

Parts \$3223.20

Add supp \$607.40

\$3830.60

766.12

\$3064.48

SN 240.00

supp SN 80.00

lab 1780.00

supp lab 60.00

5224.48

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Supp 1

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES1992427/YISHUN

Date: 31 Dec 2019

Policy No: 5113604251

Veh Reg No: SMQ1707U

Make/Model: HONDA FIT 1.3GF
PACKAGE

Chassis No: GK33419753

Engine No: L13B3934245

Reg. Date: 31/10/2019

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 26/12/2019

TP Veh Reg No: SHC7151R

Estimate Repair Cost to Vehicle No :SMQ1707U

Description	U/Price	Quantity	List Price S\$	Amount S\$
Supplementary 1				
List Price				
1 REAR WINDSCREEN GLASS MOULDING	131.00	1 PC	131.00	✓
2 REAR BUMPER CENTRE LOWER GARNISH	130.60	1 PC	130.60	✓
3 REAR RH FENDER INNER GARNISH	260.30	1 PC	260.30	✓
4 REAR SMART KEY SENSOR	85.50	1 PC	85.50	✓
			607.40	
		Less 20%	121.48	485.92
Special Net				
5 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PC	80.00	6 of 80.00
			80.00	
Labour				
6 REMOVE & REFIX REAR EXHAUST PIPE, REPAIR AND REALIGN.	60.00	1 LA	60.00	✓
			60.00	60.00
		Total		S\$ 625.92
		GST Amount		S\$ 43.81
		Total Amount Payable		S\$ 669.73

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE