

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

WIP :24098

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1491/2019/RT
Date : 19-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured Veh No : **SHA 1749 S**

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. LEE BUI ONN
Address : BLK 221 BOON LAY PLACE
#11-106
Singapore 640221
Telephone : Hp+ 65 84199979
Type of Claim : Third Party Claims
Policy No. : 5091326149-01
Vehicle No : **SGT 8141 K**
Model Code : Honda Stream 1.8 RSZ A
Model / Year : Apr-07
Engine No : R18A1725222
Chassis No : RN61022253
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Dec-19
Place of Accident : Jurong West Ave 2

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGT 8141 K

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To renew rear parking aid.	S/N \$ 280.00	/
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper Assy.	\$ 150.00	/ 100
3	To renew rear windscreen	S/N \$ 400.00	X
4	To install rear windscreen solar film	S/N \$ 400.00	X
5	To dismantle and renew rear bumper and rear lid. Re-organise crash management components. Reinstall all parts removed.	\$ 1,500.00	/ 875
6	To respray rear bumper, rear lid, lhs rear fender and lhs tail lamp panel.	\$ 1,600.00	/ 1225
7	To carry out diagnostic check.	S/N \$ 100.00	/
TOTAL LABOUR CHARGES		: \$ 4,430.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGT 8141 K

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER <i>de</i>	\$ 1,050.00	
2	REAR BUMPER SIDE BRACKET-LH/RH <i>ne</i>	1pc 2 \$ 78.00	
3	REAR BUMPER TOW EYE COVER <i>X</i>	1 \$ 30.00	
4	REAR LID <i>repar</i>	1 \$ 1,560.00	
5	"STREAM" EMBLEM FOR REAR BOOT LID <i>ne</i>	1 \$ 90.00	
6	"RSZ" INSCRIPTION FOR REAR BOOT LID <i>ne</i>	1 \$ 105.00	
7	REAR LID LOGO <i>X</i>	1 \$ 45.00	
8	REAR WINDSCREEN <i>X</i>	1 \$ 2,040.00	
9	REAR WINDSCREEN MOULDING <i>X</i>	1 \$ 90.00	
10	TAILLIGHT - LH <i>CA</i>	1 \$ 630.00	
11	SUNDRIES <i>/ ne</i>	\$ 200.00 <i>50</i>	
TOTAL SPARE PARTS		: \$ 5,918.00	
TOTAL LABOUR CHARGES		: \$ 4,430.00	
GRAND TOTAL		: \$ 10,348.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Rasul - Hp 90010078

Surveyed Date

: 30/12/19 @ 1520

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

5 days
Repair before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant