

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 3234S

MAKE :

MODEL : HYUNDAI IONIQ

DATE : 20.12.2019

TEL : 6542 5119

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>new</i>		\$ 118.70	\$ 2,253.80
	Bonnet Hinge (LH/RH) <i>1st</i>			\$ 237.40
	Bonnet Lock <i>1st</i>			\$ 127.30
	Bonnet Insulator <i>crumpled</i>			\$ 230.10
	Bonnet Insulator Clips <i>new</i>			\$ 8.40
	Radiator Grille <i>broken</i>			\$ 1,409.10
	Unit Assy-SMART CRU (Radar Sensor) <i>broken</i>			\$ 2,910.90
	Front Bumper Cover <i>turn</i>			\$ 418.30
	Front Bumper Sponge <i>turn</i>			\$ 86.90
	Front Bumper Reinforcement <i>Detached</i>			\$ 1,075.10
	Front Bumper Absorber <i>Detached</i>			\$ 86.90
	Front Bumper Grille (LH/RH) <i>new</i>	\$	186.90	\$ 373.80
	Front Bumper Centre Moulding <i>broken</i>			\$ 188.00
	Front Bumper Moulding (LH/RH) <i>new</i>	\$	93.60	\$ 187.20
	Front Bumper Lower Stiffener <i>new</i>			\$ 85.10
	Front Bumper Lip <i>new</i>			\$ 35.10
	Front Bumper Bracket Top (LH/RH) <i>new</i>	\$	35.00	\$ 70.00
	Front Bumper Bracket (LH/RH) <i>new</i>	\$	28.00	\$ 56.00
	Front Bumper Clips 10 pcs <i>new</i>			\$ 22.00
	Headlamp Support Top Cover <i>1st broken</i>			\$ 398.00
	Headlamp Support Panel Assy <i>broken</i>			\$ 949.30
	Headlamp (LH/RH) <i>broken / mended broken</i>	\$	1,198.80	\$ 2,397.60
	Day Light, LH <i>new</i>			\$ 642.50
	Day Light, RH <i>new</i>			\$ 642.50
	Radiator Inverter <i>1st / punctured</i>			\$ 884.80
	Radiator <i>1st / punctured</i>			\$ 510.50
	Radiator Blower Motor <i>broken / Dem</i>			\$ 576.00
	Radiator Fan <i>Dem</i>			\$ 375.10
	Radiator Shroud <i>broken</i>			\$ 275.50
	Radiator Air Guard (LH/RH) <i>new</i>	\$	26.40	\$ 52.80
	Radiator Air Guard, Upr(LH/RH) <i>new</i>	\$	27.50	\$ 55.00
	Hose & Tube Assy <i>new</i>			\$ 245.70
	Horn Unit (LH/RH) <i>new</i>	\$	72.80	\$ 145.60
	Horn Wire <i>new</i>			\$ 156.50
	Front Fender (RH) <i>Damage</i>			\$ 490.70
	Front Fender Shield (RH) <i>new</i>			\$ 114.70
	Emblem-Blue Drive (RH) <i>new</i>			\$ 26.60
	Air Cleaner Assy <i>1st broken</i>			\$ 282.70
	Air Duct <i>new</i>			\$ 96.80
	Air Duct B <i>new</i>			\$ 68.70
	Aircon Condenser <i>1st / punctured</i>			\$ 663.60
	Aircon Suction & Liquid Hose <i>2nd</i>			\$ 679.60
	Aircon Discharge Hose <i>2nd</i>			\$ 148.50
	Frt Safety Belt (Assy) (LH/RH) <i>active</i>	\$	448.90	\$ 897.80
	Wiper Panel Top Garnish <i>new</i>			\$ 181.20
	Wiper Container <i>new</i>			\$ 210.00
	Wiper Container Motor <i>new</i>			\$ 75.00

SHB 3234S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Engine Under Cover <i>HH</i>			\$ 469.40
	Dashboard Complete <i>Down</i>			
	Airbag Control Module <i>actuated</i>			\$ 1,243.70
	Curtain Airbag Module, LH <i>HH</i>			\$ 1,344.50
	Curtain Airbag Module, RH <i>HH</i>			\$ 1,344.50
	Steering Wheel Air Bag <i>actuated</i>			\$ 1,090.90
	Module Assy -Knee Air Bag <i>actuated</i>			\$ 578.60
	Air Bag Assy - Passenger <i>actuated</i>			\$ 1,951.20
	Air Bag Sensor (LH/RH) <i>actuated</i>		\$ 330.00	\$ 660.00
</				

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 3234S (Supplementary)

DATE : 26.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Speaker Assy- VESS <i>Dented</i>			\$ 354.40	✓
	Radiator Spare Tank <i>crack</i>			\$ 258.00	✓
	Radiator Bottom Hose <i>turn</i>			\$ 168.00	✓
	Flap Assy Active Air Upper, (LH/RH) <i>broken / Dam</i>	\$	712.00	\$ 1,424.00	✓
	A/C Tube -Liquid "A" <i>vrt</i>			\$ 165.00	✓
	A/C Tube -Liquid "B" <i>vt</i>			\$ 275.00	✓
	Air Duct "B" Assy <i>broken</i>			\$ 152.00	✓
	Electric Clutch Pump <i>crack</i>			\$ 4,130.20	✓
	Intake Manifold <i>Dam</i>			\$ 1,382.00	✓
	Generator HSG Assy <i>broken</i>			\$ 2,420.10	✓
	Rear Seat Side Garnish Cover (LH/RH) <i>broken / mostly</i>	\$	438.00	\$ 876.00	✓
	Front Windscreen Moulding <i>New</i>			\$ 57.30	✓
	Engine Mounting <i>broken</i>			\$ 483.00	✓

