



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FRANCE PTE. LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M  
GST Reg No. MR-8500111-X**ESTIMATE**

Invoice Name & Address		Owner Name & Vehicle Info	
Ang Ching Sze		Cust No/Name	/ANG CHING SZE
BLK 476 SEMBAWANG DR		Reg No/Reg Date	SLQ2487J / 30/06/2017
#13-301		Date In/Mileage	/ 56583
SINGAPORE 750476		Chassis No	VF7NXBHZTGY541058
Contact No Mobile: 98246045		Engine No	10JBHX3006928
		Make/Model	CIT/DS4 1.6 BLUEHDI 120 EAT6 CROSSBACK S
		Colour/Trim	VLM GRIS PLATINIUM / 3PF BLACK LEATHER

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	27/12/2019/ 18:48	QUD	247 / DonBong	15045

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S SPECIALISTJOB				180.00
WO: 1228696 ACCIDENT TOWED BY KINGDOLLEY FROM FLYOVER LENTOR TO CNC PG				
E PNT88000				<del>3600.00</del>
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, REAR TAILGATE, CUT/WELD REAR FLOOR-PANEL, REAR END PANEL, REPAIR BOTH REAR FENDER				2100
E PNT88000				300.00
REMOVE AND REPLACE REAR WINDSCREEN GLASS				80
M SUNDRY				100.00
SUPPLY REAR WINDSCREEN SEALANT				80
E PNT88000				100.00
REMOVE AND INSTALL PARKING ASSIST				300
E PNT88000				600.00
REMOVE AND TRANSFER REAR TAILGATE TRIM, MECHANISM TO NEW PANEL				1260
E PNT98000				2940.00
PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR TAILGATE, REAR BUMPER, RH REAR FENDER, LH REAR FENDER AND AFFECTED PORTION				80
M SUNDRY				320.00
SUPPLY BODY SEALANT				50
A 54900099				80.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				300.00
A 10028901				
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				80
M SUNDRY				180.00
PERFORM RUST PREVENTION				300
A 30000001				600.00
RENEW FRONT BOTH SEALT BELT AND BUCKLE AND OTHERS ATTACHMENT				300?
A 30000001				600.00
REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK				

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FRANCE PTE. LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M  
GST Reg No. MR-8500111-X

## ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Ang Ching Sze		Cust No/Name	/ANG CHING SZE
BLK 476 SEMBAWANG DR		Reg No/Reg Date	SLQ2487J / 30/06/2017
#13-301		Date In/Mileage	/ 56583
SINGAPORE 750476		Chassis No	VF7NXBHZTGY541058
Contact No Mobile: 98246045		Engine No	10JBHX3006928
		Make/Model	CIT/DS4 1.6 BLUEHDI 120 EAT6 CROSSBACK S
		Colour/Trim	VLM GRIS PLATINIUM / 3PF BLACK LEATHER

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073	Cash	27/12/2019/ 18:48	QUD	247 / DonBong	15045			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A 30000001								300 600.00
REMOVE AND REPLACE REAR EXHASUT SYSTEM								X 50.00
M SUNDRY								50.00
SUPPLY REAR NUMBER PLATE WITH FRAME								20 50.00
M SUNDRY								
SUPPLY C&C LOGO								
M SUNDRY								
SUNDRIES								
M	REAR BUMPER	de -			1.00	843.00	0.00	843.00
M	RECESS DOOR	de -			1.00	59.00	0.00	59.00
M	RR SKIRT PANEL	de -			1.00	562.00	0.00	562.00
M	BUMPER MOULDING	de -			1.00	305.00	0.00	305.00
M	SET REINFORFORC	de -			1.00	64.00	0.00	64.00
M	BRACKET SET	nee -			1.00	120.00	0.00	120.00
M	BUMPER BRACKET	nee -			1.00	131.00	0.00	131.00
M	STIFFENER	nee -			1.00	24.00	0.00	24.00
M	RIVET 4,8X20	nee -			10.00	8.00	0.00	80.00
M	LOW RR PAN FIX	nee -			1.00	80.00	0.00	80.00
M	LOAD FLOOR ASS	?			1.00	687.00	0.00	687.00
M	BULKHEAD	?			1.00	467.00	0.00	467.00
M	REAR PANEL ASS	? repair			1.00	559.00	0.00	559.00
M	BADGE AV	de -			1.00	52.00	0.00	52.00
M	BADGE	ce -			1.00	65.00	0.00	65.00
M	BADGE DS4	nee -			1.00	61.00	0.00	61.00
M	BADGE CROSSBACK	nee -			1.00	126.00	0.00	126.00
M	TAILGATE ASS	de -			1.00	1240.00	0.00	1240.00
M	TLGT EXT PANEL	?			1.00	641.00	0.00	641.00
M	TAILGATE HINGE	?			2.00	87.00	0.00	174.00
M	WEATHERSTRIP	?			1.00	147.00	0.00	147.00
M	TAILGATE GLASS	?			1.00	523.00	0.00	523.00
M	TAILGATE PROP LH	X			1.00	104.00	0.00	104.00
M	TAILGATE PROP RH	X			1.00	104.00	0.00	104.00
M	MOULDING	de -			1.00	345.00	0.00	345.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FRANCE PTE. LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M  
GST Reg No. MR-8500111-X**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
Ang Ching Sze	Cust No/Name /ANG CHING SZE
BLK 476 SEMBAWANG DR	Reg No/Reg Date SLQ2487J / 30/06/2017
#13-301	Date In/Mileage / 56583
SINGAPORE 750476	Chassis No VF7NXBHZTGY541058
Contact No Mobile: 98246045	Engine No 10JBHX3006928
	Make/Model CIT/DS4 1.6 BLUEHDI 120 EAT6 CROSSBACK S
	Colour/Trim VLM GRIS PLATINIUM / 3PF BLACK LEATHER

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	27/12/2019/ 18:48	QUD	247 / DonBong	15045

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SPOILER FLAP X	1.00	816.00	0.00	816.00
M SPOILER SEAL X	1.00	38.00	0.00	38.00
M TAILGATE FIX	1.00	85.00	0.00	85.00
M WING REAR LIGHT RH	1.00	354.00	0.00	354.00
M WING REAR LIGHT LH	1.00	354.00	0.00	354.00
M TAILGATE LIGHT RH	1.00	165.00	0.00	165.00
M TAILGATE LIGHT LH	1.00	165.00	0.00	165.00
M REAR FOG LIGHT RH	1.00	124.00	0.00	124.00
M REAR FOG LIGHT LH	1.00	117.00	0.00	117.00
M WDW WIPER MOTOR	1.00	256.00	0.00	256.00
M MOTOR SPACER	1.00	10.00	0.00	10.00
M SENSOR	1.00	231.00	0.00	231.00
M SENSOR	1.00	231.00	0.00	231.00
M SENSOR	1.00	231.00	0.00	231.00
M SENSOR	1.00	231.00	0.00	231.00
M SENSOR SUPPORT	4.00	137.00	0.00	548.00
M ASSIST. CAMERA ASS	1.00	473.00	0.00	473.00
M ASSIST. CAMERA	1.00	384.00	0.00	384.00
M EXHAUST PIPE	1.00	323.00	0.00	323.00
M REAR SILENCER PSA 3382	1.00	356.00	0.00	356.00
M FIXING CLAMP DIAM 61	1.00	13.00	0.00	13.00
M FRT PIPE SLEEVE DIAM 50	1.00	139.00	0.00	139.00
M FR RETRACK STAL LH	1.00	502.00	0.00	502.00
M FR RETRACK STAL RH	1.00	502.00	0.00	502.00
M BELT BUCKLE	2.00	143.00	0.00	286.00
M ADJUSTMENT	2.00	130.00	0.00	260.00
M TRUNK MAT	1.00	290.00	0.00	290.00
M LINING	1.00	322.00	0.00	322.00
M ELECTRO UNIT	1.00	392.00	0.00	392.00

Estimate

SURVEYOR NAME: Rasul - Hp 90010068SURVEYOR SIGNATURE: [Signature]DATE: 02/01/19 @ 1640REMARKS: 9 days

Confirm &amp; accepted by

Authorized signatory and company stamp

Parts	15,761.00
Labour	9,720.00
Standard Menu	0.00
Specialist Job	180.00
Diagnostics Job	0.00
Sundry/Others	750.00
Total (w/o GST)	26,411.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.