

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20000115/R1GS3Q2

Date: 08/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLL4173C	Insured Vehicle No :	SHA7723B
Date of Loss: 22/12/2019	Nature of Claim: TP	Claim No: MCT19120546

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL4173C		
Make & Model:	AUDI A1 SPORTBACK, 1.0 TFSI S-tronic (A)	Engine No:	CHZ107060
Reg. Date:	24/02/2017 (Man. Year: 2016)	Chassis No:	WAUZZZ8X5GB118107
Colour:	White	Odometer:	32882 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,462.81	2,273.34	1,189.47	34.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	840.00	470.00	35.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,772.81	3,113.34	1,659.47	34.77
Approved Total (Overridden) (\$\$)		2,450.00		
(\$\$)	4,772.81	2,450.00	2,322.81	48.67
+ GST 7.00/7.00% (\$\$)	334.10	171.50	162.60	48.67
Nett Amount (\$\$)	5,106.91	2,621.50	2,485.41	48.67
+ Loss of Use (4.0 x S\$50.00/day) (\$\$)		200.00		
(\$\$)		2,821.50		
Liabe Amount (50.00%) (\$\$)		1,410.75		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,418.20		

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 08/01/2020 Inspected At:

Sng Ah Tee Motor & Panel Service
Pte Ltd (Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2021)
Parts:	144	AUDI A1 SPORTBACK 1.0 TFSI S-tronic (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL4173C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER	Scratched	1,106.73 FL	*1,106.73 FL
2	10	*FRT BUMPER CLIP	Necessary	70.00 FL	*70.00 FL
3	1	*FRT FOGLAMP GARNISH RH	Missing	357.88 FL	*357.88 FL
4	1	*FRT FENDER RH	Bent	671.93 FL	*671.93 FL
5	1	*FRT FENDER INNERSHIELD RH	Deformed	130.45 FL	*130.45 FL
6	8	*FRT FENDER INNERSHIELD CLIPS	Necessary	56.00 FL	*56.00 FL
7	1	*FRT TYRE RIM (CUT)	Not Consistent With The Impact	936.28 FL	*- FL
8	1	*FRT TYRE 185/60 R15	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,629.27	2,392.99
- List Item Discount on L Items 5.00/5.00% (\$\$)	166.46	119.65
Total Parts (\$\$)	3,462.81	2,273.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK ,WELD ,REMOVE & FIX ON ABOVE PARTS	New	500.00	400.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	600.00	400.00
3	TO APPLY ANTI RUST COATING	New	80.00	40.00
4	TO REPAIR & REPLACE UNDERCARRIAGE	New	50.00	0.00
5	TO DO WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			1,310.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >