



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PERFORMA INVOICE

AIG INSURANCE

Vehicle number	SFB923E
Make / Model	SUBARU FORESTOR
Chassis number	JF1SJGK85EG035446
Accident date	27/12/19
Reference	1912-46

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	794 ✓ 890.00 de ✓
2	REAR BUMPER SIDE RETAINER	43.70 87.40 LH RH - new
2	REAR BUMPER REFLECTOR	57.20 114.40 LH-x RH. new
1	REAR BUMPER REINFORCEMENT	✓ 331.20 ? bt ✓
1	TAILGATE	1370.80 RY
1	TAILGATE EMBLEM - LOGO	✓ 91.08 new ✓
1	TAILGATE EMBLEM - FORESTER	✓ 74.52 new ✓
1	TAILGATE EMBLEM - XT	✓ 74.52 new ✓
1	TAILGATE EMBLEM - SUBARU	✓ 74.52 new ✓
1	TAILGATE WEATHERSTRIP	✓ 124.20 ? new ✓
1	TAILGATE INNER TRIM BOARD	x 415.05 x nn
1	TAILGATE WINDSCREEN MOULDING	x 224.00 x nn
1	TAILLAMP RH	✓ 518.40 ? cm ✓
1	TAILLAMP PANEL RH	x 345.60 x nn
1	REAR EXHAUST SILENCER	668.20 722.16 ? bt ✓
2	REAR EXHAUST MOUNTING	88.40 ? x nn
1	REAR EXHAUST HEATSHIELD	105.30 x nn
1	REAR END PANEL - photo.	589.63 R x
1	REAR END PANEL TOP GARNISH	260.50 x nn
		6501.68
	Less 20 %	1300.34
	Subtotal	5201.34
	Balance C/F	5201.34
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	REAR BUMPER CLIP	50.00 30 new ✓
1 SET	END PANEL TOP GARNISH CLIP	40.00 x nn
1	REAR NUMBER PLATE	80.00 x nn
1 SET	REVERSE SENSOR	600.00 200 new ✓
1	JONT SEALANT	150.00 x nn
1	WINDSCREEN SEALANT	150.00 x nn.
	Subtotal	1070.00
	Balance C/F	6271.34
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	6271.34
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30.
2	REMOVE, REFIT LINING, TRIM AND GARNISH	200.00 50.
3	REMOVE AND RENEW REAR REVER SENSOR	120.00 30
4	REMOVE AND NEW REAR EXHAUST ASSY	120.00 60 photo.
5	REMOVE, REFIT AND RENEW NEW TAILGATE	150.00 x nn.
6	PANEL BEATING ON AFFECTED AREAS	1200.00 500
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00 500
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	3200.00
	Grand total	9471.34

3679 53
- 2000
2943 63

230

1200

2851.54
2281.23

Sun P.n (CLdc)
03/01/2020

230.

Tan Jiah 974 75744
- WP

02/01/20 @ 4 50 pm

Lumpsum

Recovery after repair

Tan Jiah C/LH auto new

04 days

1200.

3711.23

4/5 of 3000

04 days