

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 5392E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,745.60	1,218.40
1	FRONT BUMPER RETAINER	DEFORMED	129.90	129.90
1	FRONT BUMPER REINFORCEMENT	BENT	471.90	381.70
1	FRONT BUMPER SPONGE	CRACKED	163.80	163.80
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	295.00	-
1	FRONT LH HEADLAMP	CRACKED	2,287.53	1,712.40
1	FRONT LH HEADLAMP BRACKET	NOT NECESSARY	198.60	-
1	FRONT LH FOG LAMP	NOT NECESSARY	269.90	-
1	FRONT LH FOG LAMP COVER	CRACKED	194.00	194.00
1	FRONT LH FOG LAMP CHROME GARNISH	CRACKED	141.50	141.50
1	FRONT BUMPER TOW COVER	CUT	81.91	81.91
1	FRONT BUMPER OUTER GARNISH	NOT NECESSARY	311.50	-
1	FRONT GRILLE	NOT NECESSARY	364.00	-
	LESS 25% DISCOUNT		-1,663.79	-1,005.90
			4,991.35	3,017.71
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NOT NECESSARY	60.00	-
			110.00	30.00
	LABOUR			
	CHECK WIRING AND LIGHTING SYSTEM.		60.00	30.00
	PANEL BEATING ON AFFECTED AREAS.		800.00	250.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	350.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			_	-
			_	_
			_	-
			1,810.00	630.00
	GRAND TOTAL		6,911.35	3,677.71

Report Ref No. CC4/FCI20000119/T1ha3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,900.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/FCI20000119/T1ha3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

**Automotive Assessor** 

Amonto

**HO LEONG CHUAN** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.