



Insurance Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

AIG INSURANCE Their survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

Vehicle number	SME5392E
Make / Model	TOYOTA ESTIMA
Chassis number	ACR507119430
Accident date	25/12/19
Reference	1912-43

Qty Date: **Particulars** Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS

1	FRONT BUMPER	1745.60	de
1	FRONT BUMPER RETAINER	129.90	de
1	FRONT BUMPER REINFORCEMENT	471.90	7bt
1	FRONT BUMPER SPONGE	163.80	?cm
1	FRONT BUMPER LOWER GRILLE	295.00	X
1	FRONT LH HEADLAMP	2287.53	?cm
1	FRONT LH HEADLAMP BRACKET	198.60	?X
1	FRONT LH FOG LAMP	269.90	X
1	FRONT LH FOG LAMP COVER	194.00	X?cm
1	FRONT LH FOG LAMP CHROME GARNISH	141.50	X?cm
1	FRONT BUMPER TOW COVER	81.91	cutie
1	FRONT BONNET OUTER GARNISH	311.50	X
1	FRONT GRILLE	364.00	X

Less 25%

6655.14
1663.78
4991.36

PARTS REPLACEMENT - SPECIAL NETT ITEMS

1 SET	FRONT BUMPER CLIP	50.00	30 ne
1 SET	FRONT GRILLE CLIP	60.00	X

Subtotal

110.00

Balance C/F

5101.36

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

5101.36

1	CHECK WIRING AND LIGHTNING SYSTEM	60.00	30
2	PANEL BEATING ON AFFECTED AREAS	800.00	250
3	SPRAY PAINTING ON AFFECTED AREAS	800.00	350
4	APPLY ANTI RUST ON AFFECTED AREAS	150.00	X

Subtotal

1810.00

Grand total

6911.36

Tanflin 97495749

7/1/20 @ 1230pm

Lumpsum

Resurvey after repair

Tanflin@lkhant.com

02 days