

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SH 6383M

DATE : 30.12.2019

MAKE :

TEL : 6542 5119

MODEL : MERCEDES

FAX : 6542 6039

India

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Door Shell, Frt/LH <i>Dent</i>			\$ 2,970.00
	Door Shell, Rear/LH <i>Dent</i>			\$ 2,870.00
	Mirror Glass, Frt/LH <i>HH</i>			\$ 380.00
	Mirror Cover Frt/LH <i>HH</i>			\$ 350.00
	Mirror Housing W/Signal Lamp, Frt/LH <i>HH</i>			\$ 890.00
	Mirror Motor Assy, Frt/LH <i>HH</i>			\$ 920.00
	Door Window Regulator, Frt/LH <i>HH</i>			\$ 620.00
	Door Window Motor, Frt/LH <i>HH</i>			\$ 860.00
	Door Centre Pillar Outer (LH) <i>Dent</i>			\$ 3,980.10
	Side Panel Outer/LH <i>reg</i>			\$ 730.90
				SUB TOTAL
				\$ 14,571.00
				LESS 10%
				\$ 1,457.10
				DISCOUNTED TOTAL
				\$ 13,113.90
	Labour Charge			
	Panel Beating			\$ 1,600.00
	Spray Painting Charge			\$ 900.00
	Wiring Charge			\$ 50.00
	Towing Charges			\$ 50.00
	Tuff Kote			\$ 50.00
	Transfer Of Door	\$	120.00	\$ 240.00
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00
	Re-set and Diagnosis			\$ 550.00
				TOTAL LABOUR
				\$ 3,840.00
				ESTIMATE TOTAL
				\$ 16,953.90

03/01/2020 @ 0930hrs
 NA Antenna
 4/5mm 4 days.

R
 Jan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.