

ASSIGNMENT

REC BY:

REF: *msk/*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD/TP/WS/TP RES/QD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s *Cheng Hoe*
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *842k*

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *10* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

8/4 / 11 Rmp @ 16050L Confirm

Veh No: *YP495A* Yr Regn: *12, 15*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Mit Center* c.c. *2998*

Colour: *White* A/C: Insured / Std / NI / NA

Sp. Reading: *284608* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *1-2321E A 20115*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modl: *Nil* / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: *195/85R15 (0)*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. *7* mm

L/Bal. *7* mm

D.O.A. *23/12/19*

Survey held at

Des. of Damages: Frt / *Rear* / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. *8 8* mm

L/Bal. *8 8* mm

D.O.I. *14/1/2020*

Date/Time, File Pass to?

☐ : Prel. Report

Date/Time, File Return to?

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

☐ S - RS. ☐ SI

☐ Fixt's

☐ Others

TOTAL

Report Format :

Sum / I.B.I: (\$ _____)

Cheng Hoe Motor Pte Ltd

Sik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chengmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/MSIG/WL
Claim Type: Third Party
Accident Date: 23/12/2019
TP Veh Reg No: GX2196X

Estimate No: ES2090041/WL
Date: 14 Jan 2020
Policy No: 18-MV010784-R02
Veh Reg No: YP495A
Make/Model: MITSUBISHI CANTER
FEB21ER4SDEB (CBU)

Chassis No: FEB21EA20115
Engine No: 4P10B98425
Reg. Date: 11/12/2015

Estimate Repair Cost to Vehicle No : YP495A

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	1,010.33	1 PC	R ₁ 1,010.33	✓
2 FRONT BUMPER LH BRACKET	196.24	1 PC	R ₁ 196.24	✓
3 FRONT BUMPER LH STAY	163.55	1 PC	DJS 163.56	✓
4 FRONT BUMPER SIDE PADS	417.72	2 PCS	CM 835.44	✓
5 FRONT GRILLE	1,053.14	1 PC	CM 1,053.14	✓
6 FRONT GRILLE CLIPS	6.90	6 PCS	CM 41.40	✓
7 SIGNAL LAMPS	266.36	2 PCS	R ₂ 532.72	✓
8 SIDE LAMPS	455.06	2 PCS	R ₁ 910.12	✓
9 FRONT PANEL	2,521.83	1 PC	R ₁ 2,521.83	✓
10 FRONT PANEL EMBLEM (FUSO)	154.69	1 PC	CM 154.69	✓
11 FRONT LH CORNAL PANEL	506.76	1 PC	mgcm 506.76	✓
12 FRONT WINDSCREEN GLASS	1,312.96	1 PC	CM 1,312.96	✓
13 FRONT WINDSCREEN GLASS RUBBER	492.05	1 PC	CM 492.05	502.50
14 AIR-CON GAS DISCHARGE HOSE	444.43	1 PC	CM 444.43	✓
15 HEATER PIPES	175.86	1 SET	CM 175.86	✓
16 HORN	145.41	1 PC	CM 145.41	✓
17 FRONT LH WIPER ARM COVER	29.10	1 PC	CM 29.10	✓
18 CABIN FRONT MOUNTINGS	230.41	2 PCS	CM 460.82	✓
19 CABIN FRONT MOUNTING BRACKETS	953.24	2 PCS	CM 1,906.48	✓
20 CABIN FRONT MOUNTING CROSS BAR	898.76	1 PC	R ₁ 898.76	✓
21 AIR-CON EVAPORATOR UNIT	2,303.12	1 PC	CM 2,303.12	✓
22 FRONT LH DOOR INNER LOCK	402.84	1 PC	CM 402.84	✓
23 DASHBOARD	2,208.05	1 PC	R ₁ 2,208.05	✓
24 DASHBOARD LH SIDE GARNISH	116.42	1 PC	CM 116.42	✓
25 DASHBOARD CENTRE LOWER GARNISH	501.64	1 PC	mgcm 501.64	✓
26 DASHBOARD LH LOWER GARNISH	673.71	1 PC	CM 673.71	✓
27 TAILLAMPS	194.22	2 PCS	CM 388.44	✓
28 REAR TAILGATE	2,402.15	1 PC	R ₁ 2,402.15	✓
29 TAILGATE STICKER (MITSUBISHI)	101.55	1 PC	CM 101.55	✓
30 REAR NUMBER PLATE LAMP	79.82	1 PC	CM 79.82	✓
			22,969.84	
			Less 25%	5,742.46
				17,227.38
Special Net				
31 REAR NUMBER PLATE	18.00	1 PC	R ₁ 18.00	15.50
32 STICKER - 60KM/H	10.00	1 PC	CM 10.00	✓

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581
 TEL: 68277660 FAX: 62257402
 ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/MSIG/WL
 Claim Type: Third Party
 Accident Date: 23/12/2019
 TP Veh Reg No: GX2196X

Estimate No: ES2090041/WL
 Date: 14 Jan 2020
 Policy No: 18-MV010784-R02
 Veh Reg No: YP495A
 Make/Model: MITSUBISHI CANTER
 FEB21EA4SDEB (CBU)
 Chassis No: FEB21EA20115
 Engine No: 4P10B98425
 Reg. Date: 11/12/2015

Estimate Repair Cost to Vehicle No :YP495A

Description	U/Price	Quantity	List Price	Amount
33 STICKER - 21 PAX			S\$	S\$
34 REAR STEP PANEL ASSY	10.00	1 PC	10.00	✓
35 ERP BRACKET	480.00	1 PC	480.00	✓
36 FRONT BODY STCKER	25.00	1 PC	25.00	X
	150.00	1 SET	150.00	120.00
Labour			693.00	693.00
37 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	80.00
38 PUTTY & RESPRAY DASHBOARD,METER ASSY,REPAIR DASHBOARD REINFORCEMENT & REALIGN THE SAME	280.00	1 LA	280.00	25.00
39 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
40 PUTTY & RESPRAY FRT BUMPER ASSY,GRILLE,HEADLAMPS,SIDE LAMPS,FRT WIPER ASSY,CUT,WELD & RENEW FRT PANEL,KNOCK & REPAIR FRT INNER PANEL,FRT RH DOOR & REALIGN THE SAME	1,200.00	1 LA	1,200.00	100.00
41 REMOVE & REFIX FRT CABIN,REPLACE MOUNTINGS,FRT CROSS BAR & REALIGN POSITION	800.00	1 LA	800.00	60.00
42 REMOVE & REFIX TAILGATE ASSY,TAILLAMPS,REAR STEP BAR,KNOCK & REPAIR TAILGATE LOWER MEMBER,REAR BOTH MAIN CHASSISS,LH SIDE GATE & REALIGN THE SAME	1,000.00	1 LA	1,000.00	70.00
43 PUTTY & RESPRAY ON FRT BUMPER,CORNAL PANEL,FRT GRILLE,FRT PANEL,WIPER GARNISHS,FRT RH DOOR,TAILGATE,TAILGATE LOWER PANEL	1,600.00	1 LA	1,600.00	140.00
			5,080.00	5,080.00
Total			S\$ 23,000.38	
Add GST @ 7%			1,610.03	
Total Amount Payable			S\$ 24,610.41	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

338H

Vehicle Details

Vehicle No.:

YP495A

Vehicle to be Exported:

Yes

Intended Deregistration Date:

24 Dec 2019

Vehicle Make:

MITSUBISHI

Vehicle Model:

CANTER FEB21ER4SDEB (CBU)

Primary Colour:

White

Manufacturing Year:

2015

Engine No.:

4P10B98425

Chassis No.:

FEB21EA20115

Maximum Power Output:

-

Open Market Value:

\$30,223.00

Original Registration Date:

11 Dec 2015

Latest Registration Date:

11 Dec 2015

Transfer Count:

0

Total ARF Paid:

\$1,512.00

Extended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Extended COE Rebate Details

Expiry Date:

10 Dec 2025

Category:

C - Goods Vehicle & Bus

Period(Years):

10

Aid:

\$23,137.00

Rebate Amount:

\$13,790.00

Rebate Amount:

\$13,790.00

Information contained herein is correct as at 24 Dec 2019

OK