

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX1517D
POH SOON KUAN
BLK 653B JURONG WEST STREET 61
03-442
SINGAPORE 642653
TEL : FAX :
PH : 82882763 9328 2299
ATTN :

ESTIMATE BILL

Number : EB00005372
Date : 30/12/2019
Case No : AD00010884
Vehicle No : SJB8875K
Chassis : KNAFE227385528201
Year of Mfr : 2007
Policy No :
Model : KIA CERATO

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER	1.0	416.00	10	374.40
2	FRONT BUMPER RETAINER LH	1.0	17.00	10	15.30
3	FRONT FENDER LH	1.0	257.00	10	231.30
4	HEADLAMP LH	1.0	404.00	10	363.60
5	FRONT BUMPER FOG LAMP LH	1.0	155.00	10	139.50
List Price - Parts Sub Total					1,124.10
Parts Total					1,124.10
6	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	400.00	0	400.00
7	SPRAY PAINT ON THE AFFECTED AREAS	1.0	400.00	0	400.00
8	ANTI-RUST COATING	1.0	50.00	0	50.00
9	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					890.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					7-820 17 738 1308
SINGAPORE DOLLARS : TWO THOUSAND ONE HUNDRED FIFTY-FIVE AND CENTS NINE ONLY			Less Excess	0.00	
			SUBTOTAL	2,014.10	
			GST 7.00%	140.99	
			TOTAL	2,155.09	

Date of accident : 02/10/2019 01:45 AM. Place : BEDOK SOUTH AVENUE 1, BLK2A MSCP DECK 1B

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE