



Accident Photo



Accident Photo






SLX 55 Z, Porsche Panamera

S/NO.	Parts Description	QTY	SGD \$
40-1	Bumper Front / 0.75	✓ 1800.00 ✓ 1	\$ 3,570.00 ✓
13-2	Sponge / CEA	✓ 31.20 1	\$ 60.00 ✓
14-3	Left Bumpbr Bracket / BT	✓ 31.20 1	\$ 60.00 ✓
25-4	Disc Upper / ✓	✓ 60.00 ✓ 1	\$ 140.00 ✓
30-5	Disc Lower / ✓	✓ 60.00 ✓ 1	\$ 140.00 ✓
11-6	Left Lower Retainer / 2 X CEA NN	✓ 57.60 1	\$ 104.00 ✓
X 7 X	Additional Headlamp / 2 X CEA	✓ 162.00 1	\$ 700.00 X
22-8	Headlamp Bracket / ✓	✓ 2850.00 1	\$ 340.00 ✓
1-9	Headlamp / CEA	✓ 2940.00 1	\$ 4,300.00 ✓
5-10	Bonnet / BUC	✓ 192.00 1	\$ 4,200.00 ✓
37-11	Left Side Bonnet Actuator / ✓	✓ 192.00 1	\$ 320.00 ✓
28-12	Right Side Bonnet Actuator / ✓	✓ 192.00 1	\$ 320.00 ✓
X 17 X	Bonnet Lock / X BT NN	1	\$ 150.00 X
3-14	Fender Left No Eta / BUC	✓ 750.00 1	\$ 2,500.00 ✓
27-15	Support Panel / BT 2 X NN	✓ 684.00 1	\$ 1,200.00 ✓
X 16 X	Bracket Centre Bumper / 2 X CEA	1	\$ 540.00 X
16-17	Centre Inner Air Duct / BT	✓ 240.00 1	\$ 490.00 ✓
27-18	Radiator OEM, Nissens / 2 X NN	✓ 540.00 1	\$ 800.00 ✓
X 19 X	Fan Cowling And Fan / 2 X NN	1	\$ 2,100.00 ✓
X 20 X	Radiator Frame / 2 X CEA	1	\$ 180.00 X
40-21	Return Tube Left / 2 X	✓ 114.00 1	\$ 180.00 ✓
22-22	Return Tube Right / 2 X BR	✓ 90.00 1	\$ 140.00 ✓
23-23	Radiator Upper Bracket / 2 X	✓ 16.80 1	\$ 44.00 ✓
8-24	Radiator Upper Bracket Rubber Isolator / 2 X See	✓ 22.80 1	\$ 40.00 ✓
44-25	Radiator Lower Bracket Rubber Isolator / 2 X NN	✓ 31.20 1	\$ 56.00 ✓
X 26 X	Radiator Lower Bracket / 2 X	1	\$ 44.00 X
X 27 X	Top Hose / 2 X NN	1	\$ 90.00 X
X 28 X	Bottom Hose / 2 X	1	\$ 90.00 X
24-29	Intake air Duct Left / 2 X See	✓ 120.00 1	\$ 170.00 ✓
25-30	Intake air Duct Right / 2 X	✓ 120.00 1	\$ 170.00 ✓
43-31	Air Filter Housing / 2 X See	✓ 450.00 1	\$ 700.00 ✓
17-32	Air Duct Left / 2 X See	✓ 72.00 1	\$ 90.00 ✓
18-33	Air Duct Right / 2 X	✓ 72.00 1	\$ 110.00 ✓
X 34 X	Hose / 2 X NN	1	\$ 36.00 X
X 35 X	Lock Cable Right Upper / 2 X NN	1	\$ 54.00 X
X 36 X	Lock Cable Right Lower / 2 X NN	1	\$ 32.00 X
15-37	Bonnet Gasket / 2 X NN	✓ 162.00 1	\$ 270.00 ✓
12-38	Wheel Housing Left Front / 2 X NN	✓ 234.00 1	\$ 330.00 ✓
X 39 X	Wheel Housing Left Rear / 2 X NN	1	\$ 430.00 X
X 40 X	A/C Suction Suction Pipe / 2 X NN	1	\$ 660.00 X
X 41 X	A/C Pressure Pipe / 2 X NN	1	\$ 960.00 X
X 42 X	A/C Pressure Pipe / 2 X NN	1	\$ 720.00 X
41-43	Radiator Bracket / 2 X BR	✓ 84.00 1	\$ 180.00 ✓

16549.8
+15% = 19032.27

Parts Total: \$ 27,810.00

Take note of 2 unidentified parts, will re-submit again after remove and confirm



Vehicle No :SLX 55 Z

Car Model : Porsche Panamera

S/NO.	Labour Description	Repairer's Estimate (S\$)
1	Towing from accident scene to workshop — Invoice	\$ 150.00 120
2	To straighten, repair, realign on affected area and replace damaged parts for front bumper	\$ 3,200.00 1000
3	To spary painting , blending on affected and adjacent area including right hand fender	\$ 4,000.00 800
4	To check electrical system and repair wire hardness for front bumper	\$ 750.00 7100
5	To remove , replace and/or transfer parking sensor and control unit	\$ 300.00 40
6	To conduct chasiss alignment NN	\$ 850.00 X
Labour Total : 1940		\$ 9,250.00
		39820

7 Days .

Excess \$ 2000

Not Authorised.

Guo Qi any — 82880282

03/01/2020.

Unsump Repair.

After repair photos.

Total = 21324.17
+ 120 = 21,444.17
41737

41231.50

47138.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLX 55 Z, PORSCHE PANAMERA

S/N	Parts Description	QTY	SGD \$
9-1	Head lamp	1 \$	3,049.50
14-2	Head lamp (A) - CRA 2850 ✓	1 \$	3,049.50 SUPP(A)
3-3	Used Wing Prime Coated 750	1 \$	802.50
4-4	Hook (A) - BT ✓ 60 2940	1 \$	64.20 SUPP(A)
10-5	Lid Prime Coated	1 \$	3,145.80
6-6	Support (A) - Mis 12 ✓	1 \$	12.84 SUPP(A)
24-7	Wing Prime Coated	1 \$	1,412.40
24-8	Fixing Device 22.8 Blue ✓	1 \$	24.40
9-9	Retainer Plate (A) - BT 72 ✓	1 \$	77.04 SUPP(A)
10-10	Cover Black (A) - Mis 12 ✓	1 \$	12.84 SUPP(A)
6-11	Mounting Prime Coated	1 \$	250.38
28-12	Wheel-housing liner 23457.6	1 \$	33.38
2-13	Foam part 31.2	1 \$	33.38
3-14	Retaining strip 31.2	1 \$	173.34
37-15	Gasket 162	1 \$	256.80
17-16	Air guide 240	1 \$	77.04
32-17	Air duct 72	1 \$	77.04
33-18	Air duct 72	1 \$	385.20 SUPP(A)
19-19	Bracket Prime Coated (A) - BT 360 ✓	1 \$	12.84 SUPP(A)
20-20	Cover Black (A) - Mis 12 ✓	1 \$	57.78 SUPP(A)
21-21	Rubber sleeve (A) - Re 54 ✓	1 \$	173.34
8-22	Mounting 162	1 \$	17.98
22-23	Support 16.8	1 \$	128.40
23-24	Intake manifold 120	1 \$	128.40
24-25	Intake manifold 120	1 \$	77.04 SUPP(A)
26-26	Retainer Plate (A) - BT 72 ✓	1 \$	731.88
15-27	Assembly frame 684	1 \$	96.30
22-28	Distributor tube 90	1 \$	57.78 SUPP(A)
29-29	Funnel (A) - Re 54 ✓	1 \$	712.62 SUPP(A)
30-30	Condenser (A) - BT 666	1 \$	70.62 SUPP(A)
31-31	Licence plate holder black (A) - Re 66 ✓	1 \$	288.90
32-32	Acceleration sensor (A) - NW 270	1 \$	38.52
33-33	Support (A) = CRA 18	1 \$	38.52
4-35	Corner panel 60	1 \$	64.20
5-36	Corner panel 60	1 \$	64.20
11-37	Actuator 192	1 \$	205.44
12-38	Actuator 192	1 \$	205.44
18-39	Radiator, Nissens 63779 540	1 \$	577.80
21-40	Distributor tube 84 114	1 \$	121.98
43-41	Bracket 84 114	1 \$	89.88
42-42	Cover black (A) - Re 66 ✓	1 \$	70.62 SUPP(A)
31-43	Air cleaner 450	1 \$	481.50
25-44	Retaining strip 31.2	1 \$	33.38
45-45	Car plate (A) - Dis ✓ 15	1 \$	110.00 SUPP(A)
1-46	Front bumper 1800	1 \$	1,800.00

before GST

Parts Total : \$ 19,454.58

16549.8 16855.8

+15% : 19232.27 19384.17



AUTOW Recovery Services
18 Kaki Bukit Road 3 #03-15 Singapore 415978
ROC: 53347242C

Hotline: +65 9392 4545
Email: info.autow@gmail.com

CASH ORDER / WORK ORDER


No. A07497

Service Date: 18-12-19 Time Received: _____
Member Name: Etalia Time Arrived: _____
NRIC No.: Joson Time Completed: _____
Contact No.: _____ From: Airangan
Car Reg No.: SL455Z To: 51 paya ubi
Car Make/Model: Porsche Tow Truck No.: YLS8148
Remarks: _____ Amount: \$120
Cash / Credit

ADDITIONAL CHARGES:

- ☐ Dolly Wheels / Flat Bed
- ☐ Basement / Multi Storey
- ☐ Crane up / Bogged
- ☐ Causeway / Second Link
- ☐ Low Body Kit
- ☐ Collection of Key
- ☐ ERP / Carpark _____

BODY & PAINT CONDITION:



Soon
Tow Diver's Name & Signature

Member's Name & Signature

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misdemeanour to your vehicle / asset whilst being towed.

ALPHA

 Tel: 6509 8258

ROC No. 2017I7633Z

Invoice No.: *A 1749*

Date: 25-Feb-2020

Bill To: *Etalia Autoworkz Pte Ltd*
Address: *51 Ubi Ave 1*
#01-16 Paya Ubi Industrial Park
Singapore 408934.
Contact No.: *6727 5477*
Vehicle No: *SLX 55Z*
Make & Model: *Posche Panamera*

Total due:	\$480.00
-------------------	-----------------

**** All payment should be make within 30 days from invoice date.**

*** Interest at the rate of 2% per month shall be charged for all overdue payment(s).

Alpha C.2



Good received in good order

Customer signature

Customer's Signature _____

SATISFACTION VOUCHER

Name & Address of Insured: TEEM YOK CHAI, 14 SELETAR GREEN VIEW

Name & Address of Repairers: ETALIA AUTOWORKZ PTE LTD, 51 UBI AVE 1 #01-04 Paya Ubi Industrial Park

Date & Place of Accident: 18 DECEMBER 2019, ORCHARD LINK TWDS CAIRNHILL CIRCLE

Policy No: DMPCSN30123419011 Claim No: SNM19D206070C01/5 (6t)

Vehicle No: SLX 552 Cost of Repairs: \$20805.26

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., settling the repair costs stated above with the said repairers I/We hereby release and discharge the said Insurers from all further obligations and liabilities under the aforesaid policy in respect of an accident involving my/our said motor vehicle on the above-mentioned date and place.

I/We agree that by virtue of such payment the said Insurers are subrogated to all my/our rights and remedies in respect of the damage to the said Motor Vehicle in accordance with the laws governing the Contract of Insurance.

I/We hereby grant the said Insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefor. I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their part they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:-

Company's Chop & Signature



WITNESS:-

Lee Xiao Wei
Name & Signature

51 Ubi Avenue 1 #01-04 paya ubi industrial Park
Address

28/3/2020
Date

INSURED:-

Company's Chop & Signature

WITNESS:-

LIXIAO (W)
Name & Signature

51 Ubi Ave 1 #01-04 paya ubi industrial Park
Address

28/3/2020
Date

No. 51 Ubi Avenue 1 #01-04
Paya Ubi Industrial Park
Singapore 408933
Tel : 6747 5277 Fax : 6444 0200
Co.Reg.No. : 201707802C

Proforma Invoice : 300320
Work Order No. : 1498
Date : 30/3/2020
No. of Pages : 1
Terms of Payment : CASH/CREDIT CARD/CHEQUE
Account Code :

To :
Name : CHINA TAIPING INSURANCE
Address : 3 Anson Road #15-00 Springleaf
Tower Singapore 079909
Contact No. : 6389 6183

Vehicle No. : SLX 55 Z
Make / Model : PORSCHE PANAMERA
Mileage : 196953KM
Vin : WP0ZZZ97ZBL003084

No.	Qty	Description	List Price	Amount
1	1	REPAIR COST AS PER RECOMMENDATION	\$ 21,444.17	\$ 21,444.17
2	1	EXCESS FEE	\$ (2,000.00)	\$ (2,000.00)
Remarks : For Cheque Payment Please make cheque payable to Etalia Autoworkz Pte Ltd OCBC Account : 588 132 993 001			TOTAL : \$ 19,444.17 GST (7%) : \$ 1,361.09 DEPOSIT : \$ - TOTAL DUE (SGD) : \$ 20,805.26	

Authorized Signatory
For Etalia Autoworkz Pte Ltd