


SLX 55 Z, Porsche Panamera

S/NO.	Parts Description	QTY	SGD \$
40-1	Bumper Front / 0.75	✓ 1800.00 ✓ 1	\$ 3,570.00 ✓
13-2	Sponge / CEA	✓ 31.20 1	\$ 60.00 ✓
14-3	Left Bumpbr Bracket / BT	✓ 31.20 1	\$ 60.00 ✓
25-4	Disc Upper / 2	✓ 60.00 ✓ 1	\$ 140.00 ✓
36-5	Disc Lower / 2	✓ 60.00 ✓ 1	\$ 140.00 ✓
11-6	Left Lower Retainer / 2	✓ 60.00 ✓ 1	\$ 104.00 ✓
X 7 X	Additional Headlamp / 2 X CEA NN	✓ 57.60 1	\$ 700.00 X
22-8	Headlamp Bracket / 2 CEA	✓ 162.00 1	\$ 340.00 ✓
1-9	Headlamp / CEA	✓ 2850.00 1	\$ 4,300.00 ✓
5-10	Bonnet / BUC	✓ 2940.00 1	\$ 4,200.00 ✓
37-11	Left Side Bonnet Actuator / 2	✓ 192.00 1	\$ 320.00 ✓
28-12	Right Side Bonnet Actuator / 2	✓ 192.00 1	\$ 320.00 ✓
X 17 X	Bonnet Lock / X BT NN	1	\$ 150.00 X
3-14	Fender Left No Eta / BUC	✓ 750.00 1	\$ 2,500.00 ✓
27-15	Support Panel / BT	✓ 684.00 1	\$ 1,200.00 ✓
X 16 X	Bracket Centre Bumper / 2 X NN	1	\$ 540.00 X
17-17	Centre Inner Air Duct / CEA	✓ 240.00 1	\$ 490.00 ✓
29-18	Radiator OEM, Nissens / 2 BT NN	✓ 540.00 1	\$ 800.00 ✓
X 19	Fan Cowling And Fan / 2 X NN	1	\$ 2,100.00 ✓
X 20 X	Radiator Frame / 2 X CEA	1	\$ 180.00 X
40-21	Return Tube Left / 2	✓ 114.00 1	\$ 180.00 ✓
22-22	Return Tube Right / 2	✓ 90.00 1	\$ 140.00 ✓
23-23	Radiator Upper Bracket / 2	✓ 16.80 1	\$ 44.00 ✓
8-24	Radiator Upper Bracket Rubber Isolator / 2	✓ 22.80 1	\$ 40.00 ✓
44-25	Radiator Lower Bracket Rubber Isolator / 2	✓ 31.20 1	\$ 56.00 ✓
X 26 X	Radiator Lower Bracket / 2 X NN	1	\$ 44.00 X
X 27 X	Top Hose / 2 X NN	1	\$ 90.00 X
X 28 X	Bottom Hose / 2 X NN	1	\$ 90.00 X
24-29	Intake air Duct Left / 2	✓ 120.00 1	\$ 170.00 ✓
25-30	Intake air Duct Right / 2	✓ 120.00 1	\$ 170.00 ✓
43-31	Air Filter Housing / 2	✓ 450.00 1	\$ 700.00 ✓
17-32	Air Duct Left / 2	✓ 72.00 1	\$ 90.00 ✓
18-33	Air Duct Right / 2	✓ 72.00 1	\$ 110.00 ✓
X 34 X	Hose / 2 X NN	1	\$ 36.00 X
X 35 X	Lock Cable Right Upper / 2 X NN	1	\$ 54.00 X
X 36 X	Lock Cable Right Lower / 2 X NN	1	\$ 32.00 X
15-37	Bonnet Gasket / 2	✓ 162.00 1	\$ 270.00 ✓
12-38	Wheel Housing Left Front / 2 X NN	✓ 234.00 1	\$ 330.00 ✓
X 39 X	Wheel Housing Left Rear / 2 X NN	1	\$ 430.00 X
X 40 X	A/C Suction Suction Pipe / 2 X NN	1	\$ 660.00 X
X 41 X	A/C Pressure Pipe / 2 X NN	1	\$ 960.00 X
X 42 X	A/C Pressure Pipe / 2 X NN	1	\$ 720.00 X
41-43	Radiator Bracket / 2	✓ 84.00 1	\$ 180.00 ✓

16549.8
+15% = 19032.27

Parts Total: \$ 27,810.00

Take note of 2 unidentified parts, will re-submit again after remove and confirm



Vehicle No :SLX 55 Z

Car Model : Porsche Panamera

S/NO.	Labour Description	Repairer's Estimate (S\$)
1	Towing from accident scene to workshop - <i>Invoice</i>	\$ 150.00 <i>1120</i>
2	To straighten, repair, realign on affected area and replace damaged parts for front bumper	\$ 3,200.00 <i>1000</i>
3	To spary painting , blending on affected and adjacent area including right hand fender	\$ 4,000.00 <i>800</i>
4	To check electrical system and repair wire hardness for front bumper	\$ 750.00 <i>7100</i>
5	To remove , replace and/or transfer parking sensor and control unit	\$ 300.00 <i>40</i>
6	To conduct chasiss alignment <i>NN</i>	\$ 850.00 <i>X</i>
Labour Total : <i>1940</i>		\$ 9,250.00
		<i>39820</i>

7 Days

Excess \$ 2000

Not Authorised.

Guo Qi ang - 82880282

03/01/2020

Unsump Repair.

After repair photos.

Total = 21324.17
+120 = 21,444.17
41737
41231.50
47138.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: