

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

To: Khanchana Pothuraj

27-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6576 E

1 pc	Bonnet grille X (R)	\$	385.00
1 pc	Front bumper X (R)	\$	531.00
1 pc	Front bumper emblem rec X (reuse)	\$	44.00
1 pc	Front bumper centre grille Xnr	\$	174.00
1 pc	Front bumper lower stiffer Xnr	\$	134.00
1 pc	Front bumper tow hook cover Xnr	\$	14.00
1 pc	Front bumper inner sponge Xnr	\$	110.00
1 pc	Front bumper reinforcement Xnr	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 Xnr	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 Xnr	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 Xnr	\$	32.00
		\$	1,816.00
		\$	181.60
		\$	1,634.40

S/NETT

1 pc	Front no. plate with casing	\$	50.00
1 pc	Front bumper clips Xnr	\$	48.00
Sundry		\$	50.00 \$30
To check for wiring and to focus head lamps		\$	80.00 Xnr
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 Xnr
To labour charge for dismantle and renew the accident damaged parts. knock-out, straighten, repair, reshape and adjust of the support panel etc		\$	750.00 \$300
To putty and spray painting on front bumper, bonnet grille,		\$	400.00 \$360
To apply rustproofing on the repaired and replaced panels.		\$	120.00 \$50
		\$	3,312.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

R/P: \$790 /
2 repair days

Ram (LKK)

06/01/2020 1645hrs
Para Surana@LKKauto-co
aft repair photo
2 repair days