

Sun Pin

NTUC NSI INC 20000139 / 21/1302

ASSIGNMENT

From: Date: 21/1/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 1651J

at Workshop no: SMRT

of Woodlands Depot

Insured: SFJ 282D

Policy No: 5048449243-01 (06/03/2019-09/01/2020)

Claims No: MT/1077694-003

Sum Insured: Excess:

(Claim's Record)

Make of Vch:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up?

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHB 1651J Regn: 10/12/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry (Tax) / Prime Mover /

Truck / Trailer or

Make: Toyota Prius s.c 1748

Colour: Maroon AC: Insured / Std / NI / NA

Sp Reading: 584667 T/Radio: Insured / Std / NI / NA

EngNo: -

C/No: JTPKN364405753538

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 29/12/2019. D.O.I: 02/01/2020

Survey held at SMRT

Des. of Damages: Frt / Rear / (O/S) N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHB 1651J - X

TP.

SFJ 282D - (C3) A24 1602421 / 6002421

Tax-3/10/12/19/2126

SFJ 282D

RECEIVED 27 FEB 2020

Confirm with Poh Suan

Finalize \$ 4,350 @ 5 days (L/S) (Red: 10656.74 !71%)

Date/Time, File Path to?

☐: Prel. Report

Days Of Repair: 5

21/2 Typist

☑: Final Report

Resurvey No. of Trip:

Date/Time, File Path to?

Survey Fee:

160

Transportation:

L + RS: \$

Phone:

Other:

Total:

160

Add Fee: ☐ Site Insp: \$

☐ Interview: \$

☐ Tech. Insp: \$

☐ Wood Insp: \$

Request Form:

Lum Sum / 21/1/20 4350

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5098499243-01		LEW FAI KAH DAVID	S6903911A	GPC	drive PREMIUM	SFJ282D	SFJ282D	06/03/2019	05/03/2020

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Thursday, 27 February, 2020 8:58 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: RE: SHB1651J

Hi Poh Suan,

Confirm the finalize amount \$4,350. Repair day 5 days under lump sum repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]
Sent: Tuesday, 25 February, 2020 2:16 PM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: FW: SHB1651J

Hi Sun Pin,

FYA.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Sent: Friday, 31 January 2020 2:51 PM
To: 'Oi Sun Pin (LKK Auto)'
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'
Subject: SHB1651J

Hi Sun Pin,

Attached herewith the repair estimate of SHB 1651J having Case No: TAX/12/19/2126.

There is no change to the approved amount of \$4,350 @ 5 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Ms Lee,

Denise Tay (LKKAUTO)

From: MTCL@income.com.sg
Sent: Thursday, 27 February 2020 4:20 PM
To: Denise Tay (LKKAUTO)
Subject: RE: REQUEST CLAIM NUMBER

Dear Sir/Mdm,

We have registered the claim.

Please refer below

Please allow the claim officer 2-3 working days to respond to your case.

We appreciate if you do not respond to this email. Thank you

Best regards,

Diana Tay
Senior Admin Assistant
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in wi
yc

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 27 February 2020 11:59 AM
To: MTCL@income.com.sg
Subject: REQUEST CLAIM NUMBER

Dear Sir/Mdm,

Request claim number

S/No		Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1083840-002	Comfort Transportation PTE LTD	SHC 3512J	SJV 358J	10/02/2020	18:40	7910.88	4900
2	MT/1077694-003	SMRT TAXIS	SHB 1651J	SFJ 282D	29/12/2019	22:25	10,452.68	4350

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB1651J
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1462230
Chassis No.:	JTDKN36U405753538
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	10 Dec 2014
First Registration Date:	10 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Dec 2022
PARF Rebate Amount:	\$5,661.00
Intended COE Rebate Details	
COE Expiry Date:	09 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$18,941.00
Total Rebate Amount:	\$24,602.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/12/2019 08:23
Date Of Accident	29/12/2019 22:25
Exact Location Of Accident	JUNCTION OF PUNGGOL FIELD TOWARDS PUNGGOL PLAZA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1651J
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	THAM YOW LEONG
NRIC No	SXXXX024G
Date Of Birth	09/09/1956
Occupation	OUTDOOR
Date Of Driving Pass	07/06/1976
Driving Experience	43 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 621A
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 2 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING ,
 POSTCODE: 319194 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2519999 - FAX NO: 63548749
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT T/20191230/2036 ON 29/12/2019 AT ABOUT 2225 HRS, I WAS DRIVING MY VEHICLE BEARING REGISTRATION OF SHB1651J ALONG PUNGGOL FIELD TOWARDS PUNGGOL PLAZA, WHILE APPROACHING THE TRAFFIC JUNCTION, ONE VEHICLE BEARING REGISTRATION OF SFJ282D FROM MY RIGHT SIDE HIT ONTO MY RIGHT SIDE OF MY SAID VEHICLE. I THEN MAKE A HECK ON THE SAID VEHICLE AND THERE IS A DENTED OF MY RIGHT SIDE OF MY SAID VEHICLE. NEITHER TRAFFIC POLICE NOR - AMBULANCE AT SCENE. I HAVE 2 PASSENGERS AND THEY ARE NOT INJURED AT ALL. WE DID EXCHANGE PARTICULARS. I PROCEED TO CLINIC TO MAKE A CHECK AND I WAS GIVEN 3 DAYS OF MC WHICH DATED FROM 30.12.2019 TO 01.01.2020.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFJ282D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



PUNGGAL FIELD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191230/2038

1 of 3

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20191230/2038

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/12/2019 11:58	Vide Report No.:	Station Diary No.: 79
--	------------------	--------------------------

Informant's Particulars

Name of Informant: THAM YOW LEONG	Address: APT 3LK 621A EDGEFIELD WALK #06-15 SINGAPORE 821611		
ID Type / ID No.: NRIC NO / S1182024G	Contact No.:	Mobile: 92717598	
Nationality: SINGAPORE CITIZEN	Home/Office:	Email:	
Sex: Male	Age: 63	Date of Birth: 09/09/1956	Type of Informant: Driver
Race: Chinese	Language:	Institution / School Name:	
Occupation: Taxi driver	Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 29/12/2019 22:25	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 PUNGGOL FIELD				
ALONG PUNGGOL FIELD GOING TOWARD S. PUNGGOL PLAZA				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFJ282D	Car				Slightly Damaged	2
SHB1651J	Car				Seriously Damaged	4

Details of Person Involved

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	



SINGAPORE
POLICE FORCE



T/20191230/2035

2 of 3

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20191230/2035

CONTINUATION OF REPORT

Driver Name	THAM YOW LEONG	ID No.	S1182024G
Related Vehicle	SHB1651J (Car)	Contact No.	92717598
Hospital/Clinic	HORIZON MEDICAL PTE LTD	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

On 29.12.2019 at about 2225hrs, I was driving my vehicle bearing registration of SHB1651J along Punggol Field going towards Punggol Plaza.

While I approaching the traffic junction, one vehicle bearing registration of SFJ282D from my right side hit onto my right side of my said vehicle.

I then make a check on the said vehicle and there is a dent on my right side of my said vehicle. Neither traffic police nor ambulance at scene. I have 2 passengers and they are not injured at all. We did exchange our particulars. I proceed to clinic to make a check and I was given 3 days of MC which dated from 30.12.2019 to 01.01.2020.

SINGAPORE
POLICE FORCE

T/20191230/2038

3 of 3

Report No. T/20191230/2038

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Staff Sgt NUR FHADILAH BINTE MOHD
KHALID

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Signature Of Informant:

Date/ Time:

30/12/2019 11:58

Classification Of Case:

SN 168

Authentication Stamp

NP168

SINGAPORE
POLICE FORCE
INVESTIGATION UNIT

SIGNATURE

Case Details

Case Reference Number :

TAX/12/19/2126

Type of Repair : Accident Repair

Vehicle Registration Number : SHB1651J

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-9940-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 29/12/2019 02:25 PM

Vehicle Age(In Months) : 60

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give • X Svc
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give • X Svc
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	0.00 \$670.8	Replace • / PD
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace • / NA
One Time Key In	Main			HINGE LOWER RH, DOOR	1	80.10	80.10	25.00	60.07	Replace	0	0	Check • X Svc
One Time Key In	Main			HINGE UPPER RH, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Check • X Svc
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check • X Svc
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give • X Svc
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give • X Svc
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give • X Svc

Total Spare Part Cost 8,883.35

Surveyor Total 1,975.58

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 7,106.68

Final Sur Total 1,580.46

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	715.88	Replace	* / PD
One Time Key In	Main			DOOR REGULATOR MOTOR REAR RH	1	947.80	947.80	10.00	853.02	Replace	0	0	Check	* X SVC
One Time Key In	Main			DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1	224.80	224.80	25.00	168.60	Replace	0	0	Check	* X SVC
One Time Key In	Main			WIRE RHR, DOOR	1	280.20	280.20	10.00	252.18	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			HINGE UPPER LHR, DOOR	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			HINGE LOWER RHR, DOOR	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	* / CR4
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	* / NEC
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	* / NEC
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	505.20	Replace	* / CRA
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	* X R
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			WHEEL HUB REAR	1	489.40	489.40	25.00	367.05	Replace	0	0	Not Give	* X SVC

Total Spare Part Cost 8,883.35

Surveyor Total 1,975.58

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 7,106.68

Final Sur Total 1,580.46

SMRT Recommendation											Surveyor Approval		
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1	224.00	224.00	25.00	168.00	Replace	0	0	Not Give • X SVC
One Time Key In	Main			DOOR REGULATOR MOTOR FRONT RH	1	947.00	947.00	10.00	853.02	Replace	0	0	Not Give • X SVC
One Time Key In	Main			BUMPER REAR	1	458.00	458.00	25.00	343.95	Replace	1	0	Repair • X R
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	0	0	Not Give • X SVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	25.00	90.00	Replace	2	90.00 \$120	Replace • / Nec.
Total Spare Part Cost									8,883.35	Surveyor Total 1,975.59			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20			
Final Spare Part Cost									7,106.58	Final Sur Total 1,580.46			

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	675.00	400	/
Total:			675.00 1326	400.00 700	

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
2	Main	TO RESPRAY FRONT DOOR RH	378.00	200	/
3	Main	TO RESPRAY REAR DOOR RH	378.00	200	/
4	Main	TO RESPRAY REAR FENDER RH	378.00	200	/
5	Main	TO RESPRAY ROCKER PANEL Moulding	180.00	80	/
6	Main	TO RESPRAY REAR BUMPER	378.00	200	/
Total:			2,070.00	880.00	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TRANSFER DOOR MECHANISM	120.00	80	✓ 2 days
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓
3	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	✓
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			600.00 245	140.00 325	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary bond(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,106.68	1,580.46
Total Labour Cost	676.00	400.00
Total Spray Painting	2,070.00	880.00
Other	600.00	140.00
Overall Total	10,452.68	3,000.46
Lump Sum Repair Option		✓
Lump Sum Total	10,450.00	3,000.00
Surveyor Approved Amount	15006.74	3,000.00
No of Repair Days*	5	4 days
Remarks	-	Lump Sum repair, after paint photo
Surveyor Name		Sun Pin (LKK)
Signature		 3/1/2020
Survey Date	02/01/2020	

Save Clear

17624.74

Section A - Accident Details

Registration Number	SHB1651J
Case Reference Number	TAX/12/19/2126
Registration Date	10/12/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	THAM YOW LEONG
Type of Accident	Head To Side
Accident Date and Time	29/12/2019 10:25 PM
Accident Reported Date and Time	30/12/2019 4:20 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105083
Special Instruction to ARC, if any	RIGHT HAND PORTION DAMAGE
Prepared Date and Time	31/12/2019 1:25 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,326.00	\$700.00
Total Spray Cost	\$2,070.00	\$880.00
Total Spare Part Cost	\$10,606.85	\$3,516.86
Total Other Cost	\$845.00	(\$746.86)
TOTAL COST	\$14,847.85	\$4,350.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	Fong Soon Loh	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	08/01/2020 10:23 AM	07/01/2020 4:37 PM
Signature		
Remarks	Total number of repair days = 5 days. SUP = + 1 day.	Lump Sum repair, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2001-0354	Invoice Number	
Quotation Date	23.01.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPLACE REAR FENDER	\$650.00	\$300.00
TO REPAIR FRONT RH PORTION	\$676.00	\$400.00
Total Labour	\$1,326.00	\$700.00

supp

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$80.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,070.00	\$880.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$1,071.86)
TO TRANSFER DOOR MECHANISM	\$120.00	\$80.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$845.00	(\$746.86)

supp
NPL
supp

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53801-47050	FENDER FRT/RH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given
		75374-47051	NAME PLATE (HYBRID)	0.00	\$51.80	0.00	\$0.00	Replace	Not Given
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
		68730-12120	HINGE LOWER RH, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Check
		68710-12151	HINGE UPPER RH, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Check

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park S4, Singapore 737708
FAX Number: 63640882
Estimate Telephone Number: 68626223
Accident Reporting Number: 68626272

Date Generated: 24/01/2020

User ID: Ponguen

68610-47021	CHECK ASSY, FR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Check	X
52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	Y
52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	Y
76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X
67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	✓
85710-47120	DOOR REGULATOR MOTOR REAR RH	0.00	\$947.80	0.00	\$0.00	Replace	Check	X
69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check	X
82153-47300	WIRE RHR, DOOR	0.00	\$280.20	0.00	\$0.00	Replace	Not Given	X
68760-20122	HINGE UPPER LHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X
68770-52031	HINGE LOWER RHR, DOOR	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
61804-47090	FENDER RR/RH	1.00	\$766.80	25.00	\$575.10	Replace	Replace	✓
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
	STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given	X
75851-47900	MOULDING BODY, RH	1.00	\$673.60	25.00	\$505.20	Replace	Replace	✓
42811-47140	WHEEL DISC	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given	X
69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Not Given	Y
85710-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Not Given	X
52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair	R
90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given	X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
Total			\$11,258.34		\$2,676.38			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		85710-47120	DOOR REGULATOR MOTOR REAR RH	0.00	\$947.80	0.00	\$0.00	Replace	Not Given
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1.00	\$224.80	25.00	\$168.60	Replace	Replace
		62710-47130	QUARTER GLASS RR/RH	1.00	\$846.50	25.00	\$634.88	Replace	Replace
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace
Total					2,056.10		840.48		

X Svc
BT
Nec
30 + Nec

3516.86
+ 700.00
+ 1205.00
5421.86
- 202
4337.49

4/5 \$4350/
5 days

REQUEST FOR SUPPLEMENTARY PARTS

Contractor:			
Accident Case Number	TAX 12/19/2126	Date of Collection	1 1
Vehicle No	SHB 1651-J	Date of Request	04/01/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	4 1

S/N	Part Number	Part Description	Quantity	Unit Price	
		REAR DOOR REGULATOR RH	1 PL	/ BT	
		REAR DOOR REGULATOR MOTOR RH	1 PL	X SVC	
		QUARTER GLASS REAR RH	1 PL	/ NAC	
	LABOR	TO CUT & REPAIR REAR FENDER RH		\$ 650	300
		REAR QUARTER GLASS SEALANT	1 PL	30	
	LABOR	TO PROVIDE SOLAR FILM FOR REAR QUARTER GLASS			/ Nec

<<Please submit photographs for damaged parts>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Pg 1/2

REQUEST FOR SUPPLEMENT PARTS

Contractor:			
Accident Case Number	TAX 12/19/2126	Date of Collection	1 / 1
Vehicle No	SHB 1651 J	Date of Request	04/10/2020
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	4.1

S/N	Part Number	Part Description	Quantity	Unit Price
	LABOR	TO W/ 8 REPAIR REAR BUMPER GLASS RH		60
	TO	Request ADDITIONAL REPAIR DAYS		

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff _____

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Hunter
Photo Submitted	YES / NO	Date of submission

Pg 2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20000139/Qtf3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

Date: 04-03-2020



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFJ 282D	Veh. Inspected	SHB 1651J
Policy No.	5098499243-01	Coverage (\$)	0.00
Claim No.	MT/1077694-003	Excess (\$)	0.00
Assign From		Assign Date	02/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U405753538	Colour	MAROON
Odometer	584667	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	ACHILLES	5 mm
L/H Front Tyre	195/65 R15	ACHILLES	5 mm
R/H Rear Tyre	195/65 R15	ACHILLES	5 mm
L/H Rear Tyre	195/65 R15	ACHILLES	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/12/2019	Inspection Date	02/01/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 80 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1651J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DOOR FRT/RH (DISC 25%)	DENTED	894.40	670.80
1	DOOR RR/RH (DISC 25%)	DENTED	954.50	715.88
1	FENDER RR/RH (DISC 25%)	CRUMPLED	766.80	575.10
1	MOULDING BODY, RH (DISC 25%)	CRACKED	673.60	505.20
1	DOOR REGULATOR SUB-ASSY, FRT/REAR RH (DISC 25%)	BENT	224.80	168.60
1	QUARTER GLASS RR/RH (DISC 25%)	NECESSARY	846.50	634.88
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	30.00
1	FENDER FRT/RH	SERVICEABLE	723.40	-
1	NAME PLATE (HYBRID)	SERVICEABLE	51.90	-
1	HINGE LOWER RHF, DOOR	SERVICEABLE	90.10	-
1	HINGE UPPER RHF, DOOR	SERVICEABLE	80.50	-
1	CHECK ASSY, FR DOOR,	SERVICEABLE	150.30	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	947.80	-
1	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	SERVICEABLE	224.80	-
1	WIRE RHR, DOOR	SERVICEABLE	280.20	-
1	HINGE UPPER LHR, DOOR	SERVICEABLE	81.70	-
1	HINGE LOWER RHR, DOOR	SERVICEABLE	72.20	-
1	QUARTER GLASS RR/RH	SERVICEABLE	846.50	-
1	TYRE	SERVICEABLE	126.74	-
1	WHEEL HUB REAR	SERVICEABLE	489.40	-
1	DOOR REGULATOR SUB-ASSY, FRT / REAR RH	SERVICEABLE	224.80	-

Report Ref No. NS/INC20000139/Qtf3e2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR REGULATOR MOTOR FRONT RH	SERVICEABLE	947.80	-
10	BUMPER CLIPS @\$2.10	SERVICEABLE	21.00	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	947.80	-
1	WHEEL DISC	TO REPAIR SEE LABOUR	1,484.20	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
1	SOLAR FILM (SN)	NECESSARY	125.00	125.00
			13,518.34	3,634.86
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF WHEEL DISC AND BUMPER REAR.		1,326.00	700.00
	SPRAY PAINT.		2,070.00	880.00
	TO TRANSFER DOOR MECHANISM.		120.00	80.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS RH.		120.00	60.00
			4,116.00	1,780.00
GRAND TOTAL			17,634.34	5,414.86

**RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)****4,350.00**

Report Ref No. NS/INC20000139/Qtf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.