

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST & Reg No. 201629438M

LKK  
06/01/20  
Monday

24/12/2019

Owner: HYMS CAR LEASING PTE LTD

## ESTIMATE TO REPAIR HONDA SHUTTLE - SLZ4399U

|       |                                    |
|-------|------------------------------------|
| 1pc   | rear tailgate                      |
| 1pc   | rear tailgate "H" logo             |
| 1pc   | rear tailgate "SHUTTLE" emblem     |
| 1pc   | rear tailgate chrome               |
| 1pc   | rear tailgate windscreen moulding  |
| 1pc   | rear tailgate inner lock           |
| 1pc   | rear tailgate inner rubber         |
| 1pc   | rear tailgate inner garnish        |
| 1pc   | rear bumper                        |
| 2pcs  | rear bumper side retainer @\$38.50 |
| 10pcs | rear bumper clip @\$5.00           |

|    |             |   |
|----|-------------|---|
| R  | \$ 1,193.70 | X |
| nr | \$ 58.00    | — |
| nr | \$ 55.00    | — |
| sn | \$ 383.10   | X |
| nr | \$ 195.00   | X |
| R  | \$ 289.40   | X |
| sn | \$ 188.50   | X |
| sn | \$ 358.50   | X |
|    | \$ 1,150.60 | ? |
| sn | \$ 77.00    | X |
|    | \$ 50.00    | ? |

less 20%

|             |
|-------------|
| \$ 3,998.80 |
| \$ 799.76   |
| \$ 3,199.04 |

|      |                            |
|------|----------------------------|
| 1set | rear parking sensor        |
| 1set | rear number plate & casing |

|           |           |      |
|-----------|-----------|------|
| nr s.nett | \$ 280.00 | 2000 |
| sn s.nett | \$ 50.00  | X    |

|                                      |
|--------------------------------------|
| remove & refit rear windscreen glass |
| sealant                              |
| wiring                               |
| tuffkote                             |
| spray painting                       |
| labour charges                       |
| Total                                |

|    |             |      |
|----|-------------|------|
| nr | \$ 120.00   | X    |
| nr | \$ 80.00    | X    |
|    | \$ 100.00   | 15%  |
| nr | \$ 100.00   | X    |
|    | \$ 800.00   | 4000 |
|    | \$ 800.00   | 4000 |
|    | \$ 5,529.04 |      |



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: