

ASS. REC. BY:

REF: CS/MSG-0000153/ Agf312

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Crystal Lee of MSIG Date/Time: 3.1.2020 11:30 AM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 3686m Insured: SLQ 6241A

at Workshop m/s Modern Auto Motive Tel: 67484422

of BIK 3023-A via road 1 70161

Policy No: 28795104 Claim No: 616513

Sum Insured: Excess:

Make of Veh: D.O.A. 2-1-2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 3-1-19 12:30 PM Person Contacted: Grace

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SLD 3686m-X

SLQ 6241A-X

06/01/20 @ 11.20am Informed Jowyn Tay, we are pending estimate from repairer.

30/01/20 @ 4.41pm revised to Jowyn Tay via messenger.

LS \$4500, 7 days (Red \$4268, 49%)

SIGNATURE

SLD3686M

2016 June

Policy No. _____
 To Insured Vehicle No. _____
 At Workshop No. _____
 Insured: _____
 Policy No. _____
 Claim No. _____
 Sum Insured: _____
 (Client's Record)
 Make of Veh: _____

Type: ☒ Car / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Private Motor /
 Truck / Trailer or
 Make: Mit Attrage 1193
 Colour: Blue, Insured / Std / Nil / NA
 Sp. Reading: 119420 T/Ratio: Insured / Std / Nil / NA
 Engine: _____
 C/Nr: MMBSTA13A1H000374.
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Mod: Nil / ☒ STD A/Rim or
 Tyre Size F: 185/55R15
 R: 185/55R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / ☒ YOKO or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

INS	O/S

Bal. or Market Value _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 7 days Res: Yes or No
 Lim Sum _____ % 3 Val: Yes or No
 CA / REV / REP. / 24HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front: _____ Rear: _____
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A: _____ D.O.I: 03/01/20
 Survey held at: Modern.
 Des. of Damages: Fnt / ☒ R / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: TP MSIG.
 MV: A3K
 PV: 34.31c
 Nett: 8.7K
 RECEIVED 31 JAN 2020
 30/1/2020

Date/Time File Filed for: ☐ Prel. Report
 31/1/2020 ☐ Final Report
 Days Of Repair: 7
 Resurvey No. of Trip: 1
 A/W/F Fee: ☐ Site Insp. 1K
☐ Interview 1K
☐ Test 1K
☐ Report 1K
 150
 11
 161
 4500

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 30 Jan 2020

Preliminary Advice

Insured Vehicle No	: SLQ6241A	Accident Date	: 02/01/2020
TP Vehicle No	: SLD3686M	Assignment Date	: 03/01/2020
Make	: MITSUBISHI ATTRAGE	Est. Duration of Repair	: 7.00
Date of Inspection	: 03/01/2020		
Inspection At	: MODERN AUTOMOTIVE PTE LTD (HQ) BLK 3023A UBI ROAD 1, #01-61 & #01-58 SINGAPORE 408717		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,768.00
Revised Amount	:S\$	5,650.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,650.10

Lump Sum Repair	:S\$	4,500.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Friday, 3 January 2020 11:13 AM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: SLD3686M_02012020.pdf

TP Claim SLD3686M & SLQ6241A (MSIG) DOA: 02/01/20

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua

Sent: Friday, 3 January, 2020 10:23 AM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: TP Claim SLD3686M & SLQ6241A (MSIG) DOA: 02/01/20

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Friday, 3 January 2020 10:23 AM
To: 'Chin' <chin@modernautomotive.com.sg>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: TP Claim SLD3686M & SLQ6241A (MSIG) DOA: 02/01/20

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG



A Member of **MS&AD** INSURANCE GROUP

From: Chin <chin@modernautomotive.com.sg>
Sent: Friday, 3 January 2020 9:51 AM
To: Helene Phua <helene_phua@sg.msig-asia.com>
Subject: RE: TP Claim SLD3686M & SLQ6241A (MSIG) DOA: 02/01/20

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Helene

We choose Lkk Auto Consultant Pte Ltd to survey our client vehicle.

Thank you

Regards,
Grace Chin

Modern Automotive Pte Ltd
Blk 3023-A, Ubi Road 1 #01-61
Singapore 408717

Tel: 6748 4422
Fax: 6747 6720

From: Helene Phua [mailto:helene_phua@sg.msig-asia.com]
Sent: Thursday, January 2, 2020 6:28 PM
To: chin@modernautomotive.com.sg
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: TP Claim SLD3686M & SLQ6241A (MSIG) DOA: 02/01/20

Hi,

We refer to your email dated 02/01/2020.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Xing Guo Qiang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Chin [<mailto:chin@modernautomotive.com.sg>]

Sent: Thursday, January 02, 2020 4:39 PM

To: Claims <claims@sg.msig-asia.com>

Subject: Re: TP Claim SLD3686M & SLQ6241A

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir

We refer to the above matter.

Kindly arrange survey our client 's vehicle as follow:

Your Insured: SLQ6241A

Our Insured: SLD3686M

DOA: 02.01.2020

We enclosed herewith our client report for your perusal and please revert.

Thank you

Regards,

Grace Chin

Modern Automotive Pte Ltd

Blk 3023-A, Ubi Road 1 #01-61

Singapore 408717

Tel: 6748 4422

Fax: 6747 6720

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Monday, 6 January 2020 11:20 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SLD 3686M (YOUR INSURED VEHICLE: SLQ 6241A)

This mail is associated with :

***SLD3686M**

[SLQ6241A]

TP

QUAH WEI LING

Jan 2 2020 12:00AM

[SKYWAY MOTOR PTE LTD]

Modern Automotive Pte Ltd

Dear Jowyn,

Please be informed that we have inspected the vehicle SLD 3686M on 03/01/2020.

We are pending for estimate from repairer.

Wishing you a Happiness and Prosperity New Year

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



Best Car Repair Workshops in Singapore

Browse more than 3,000 car workshops in Singapore.
You can read customers' reviews & ratings on their services too.

► **SEARCH** Price Range Depreciation Year Reg Vehicle Type

► Used Car Comparison

--- Comparing 4 Vehicles ---

Mitsubishi Atrage 1.2A



 Clear All

[Back to search result](#)

Mitsubishi Atrage 1.2A



Mitsubishi Atrage 1.2A



Mitsubishi Atrage 1.2



CAR DETAILS

	Mitsubishi Atrage 1.2A	Mitsubishi Atrage 1.2A	Mitsubishi Atrage 1.2A	Mitsubishi Atrage 1.2
Price	\$55,800	\$49,888	\$53,800	\$52,800
Instalment	\$591	\$502	\$542	\$532
Registration Date	19-Aug-2016	29-May-2017	17-Aug-2017	22-Jan-2018
Manufactured	2016	2017	2016	2017
Mileage	68,000 km	33,650 km	23,000 km	16,388 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,193 cc	1,193 cc	1,193 cc	1,193 cc
Road Tax	\$506 /yr	\$506 /yr	\$506 /yr	\$506 /yr
Power	57.0 kW (76 bhp)	57.0 kW (76 bhp)	57.0 kW (76 bhp)	59.0 kW (79 bhp)
Curb Weight	940 kg	940 kg	940 kg	940 kg
Features	Fuel Efficient 1.2L DOHC 12 Valves MIVEC Engine, INVECS-III CVT Auto Transmission, ABS, EPS, Airbags, Keyless Entry/Start/Stop, Knockdown Rear Seats.	Fuel Efficient 1.2L DOHC 12 Valves MIVEC Engine, INVECS-III CVT Auto Transmission, ABS, EPS, Airbags, Keyless Entry/Start/Stop, Knockdown Rear Seats.	Fuel Efficient 1.2L DOHC MIVEC Engine, Smooth INVECS III CVT Auto Transmission, Airbags, ABS, Traction Control, Keyless Start/Stop.	Fuel Efficient 1.2L Smooth INVECS III CVT Auto Transmission, Airbags, Keyless Start/Stop.
Accessories	Keyless Entry, Leather Seats, Reverse Camera, Audio System With BT, Multi Function Steering. 10 Years Engine Warranty And 5 Years Gearbox Warranty.	Keyless Entry, Leather Seats, Reverse Camera, Audio System With BT, Multi Function Steering. 10 Years Engine Warranty And 5 Years Gearbox Warranty.	Sports Rims, Leather Seats, Digital Climate Control Aircon, Retractable Side Mirror, Fog Lamps.	Sports Rims, Leather Climate Control Air Mirror, Fog Lamps.
Description	Selling With Old 3 Digits Registration Number. Only 1 Owner. Low Mileage Done. Accident Free. Original Paintwork. Warranty 10 Years On Engine And 5 Years On Gearbox. Buy With Peace Of Mind. Fully Maintained By Agent Since Day 1. Low Fuel Consumption. Excellent Power For Such A Small CC Car. Trade In Available. 100% Loan Possible. Call For Viewing Now. Honest Deal Assured. No Hidden Cost.	Only 1 Owner With Agent Warranty, Nice Car Plate Number, Low Mileage, Accident Free Condition, Original Paintwork Since Day 1, View To Believe, Low Upfront Will Be Arrange By Professionals. Call To View The Car Now.	Non Private Hire Unit! AA Trust Certified Pre-Owned Vehicle! Best Value For Your Money! Low Fuel Consumption, Low Maintenance! Original Paintwork Condition And Well Taken Care By Owner! Flexible Bank And In House Loan Available! Trade In Welcome! Hurry Call To Make An Appointment Now!	100% Loan Availat Transfer Of Owner: 1 Owner. Non PHV Mileage Done. Full Since Day 1. Under Please Call For View
COE	\$53,000	\$51,600	\$49,430	\$42,339
OMV	\$14,128	\$11,287	\$13,450	\$13,474
ARF	\$5,000	\$5,000	\$5,000	\$5,000
Depreciation	\$8,040 /yr	\$6,400 /yr	\$6,730 /yr	\$6,240 /yr
No. of Owners	1	1	2	1
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	PARF Car	PARF Car, Direct Owner Sale	PARF Car, Low Mileage Car	PARF Car, Premium Car
Availability	Available	Available	Available	Available

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	2751
Vehicle Details	
Vehicle No.:	SLD3686M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jan 2020
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	3A92UDB9241
Chassis No.:	MMB5TA13AHH000374
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,744.00
Original Registration Date:	15 Jun 2016
First Registration Date:	15 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Amount	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jun 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Amount	
COE Expiry Date:	14 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$30,495.00
Total Rebate Amount:	\$34,245.00

The information contained herein is correct as at 03 Jan 2020

OK

Attn: Adrian

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MSIG INSURANCE (S) PTE LTD

4 Shenton Way # 21 - 01

SGX Centre 2

Singapore 068807

Hot line : 6827 - 7660

Fax : 6225- 7402 (CLAIM)

Xiao Chan.

Quotation
DATE : 03.01.2020
VEH NO : SLD3686M
MODEL : Mitsubishi Attrage
D O A : 02.01.2020
YR REF : SLQ6241A

Attn: Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SLD3686M (MITSUBISHI ATTRAGE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Am't</u>
NO	LIST ITEMS		
1	Rear Bumper <i>scratched</i>	1	708.00 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	110.00 ✓
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	84.00 ✓
5	Rear End Panel <i>scratched</i>	1	452.00 ✓
6	Rear End Panel Top Garnish <i>scratched</i>	1	178.00 ✓
7	Rear End Panel Air Vent <i>new</i>	1	75.00 ✓
8	Rear End Panel Side Garnish <i>scratched</i>	2	58.00 ✓
9	Tail Lamp - RH <i>scratched</i>	1	295.00 ✓
10	Tail Lamp Panel - RH <i>scratched</i>	1	95.00 ✓
11	Bootlid <i>scratched</i>	1	828.00 ✓
12	Bootlid Lock <i>new</i>	1	206.00 ✓
13	Bootlid Weatherstripe <i>at</i>	1	177.00 ✓
14	Mitsubishi Logo	1	42.00 ✓
15	Attrage Emblem <i>new</i>	1	45.00 ✓
16	Mivec Emblem	1	65.00 ✓
17	cylce and carriage Logo <i>new</i>	1	54.00 ✓
18	Rear Fender - RH <i>Regis</i>	1	923.00 ✓
19	Rear Fender Inner Trim - RH <i>new</i>	1	308.00 ✓
20	Rear Fender Inner Trim Clips - RH <i>new</i>	1 set	30.00 ✓
21	Rear Windscreen Moulding <i>new</i>	1	105.00 ✓
22	Spare Tyre Panel Top Board <i>torn</i>	1	222.00 ✓
23	Rear Exhaust Pipe <i>new</i>	1	597.00 ✓
24	Rear Exhaust Mounting	1	48.00 ✓
			\$ 5,735.00
Less 20%			(1,147.00)
			\$ 4,588.00

RE : ESTIMATE FOR ACCIDENT REPAIR SLD3686M (MITSUBISHI ATTRAGE)

S/NET ITEMS

1	Reverse Sensor <i>Don't</i>	1	\$	280.00 <i>200</i>
2	Rear End Panel Sealant <i>per</i>	1	\$	60.00 ✓
3	Rear Windscreen Sealant <i>per</i>	1	\$	60.00 X

\$ 400.00

Total parts

\$ 4,988.00

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,600.00 <i>1100</i>
2	To putty and spray up paint works	\$	1,400.00 <i>1100</i>
3	To check wiring system	\$	50.00 <i>30</i>
4	To remove reverse sensor	\$	100.00 <i>50</i>
5	To remove upholstery	\$	150.00 <i>60</i>
6	To remove exhaust pipe	\$	150.00 X
7	To remove rear windscreen	\$	180.00 X
8	To remove fuel tank	\$	150.00 X
			\$ 3,780.00

GRAND TOTAL

\$ 8,768.00 *9341.50*

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5648.30

L/S: 4.51C

OT Days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20000153/AQF3N2
Date: 03/02/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28795104
Claimant Vehicle No : SLD3686M **Insured Vehicle No :** SLQ6241A
Date of Loss: 02/01/2020 Nature of Claim: TP Claim No: 616513

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD3686M**
Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UDB9241
Reg. Date: 15/06/2016 (Man. Year: 2016) Chassis No: MMBSTA13AHH000374
Colour: Blue Odometer: 119420 km
Engine Capacity: 1193 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,561.50	3,310.10	2,251.40	40.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	2,340.00	1,440.00	38.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,341.50	5,650.10	3,691.40	39.52
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	9,341.50	4,500.00	4,841.50	51.83
+ GST 7.00/7.00% (S\$)	653.91	315.00	338.91	51.83
Nett Amount (S\$)	9,995.41	4,815.00	5,180.41	51.83

INSPECTION

Date of Assignment: 03/01/2020
Date Inspected: 03/01/2020 Inspected At: Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Feb 2020)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD3686M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	708.00 FL	*708.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	110.00 FL	*110.00 FL
4	2		*REAR BUMPER REFLECTOR-LH & RH	Not Necessary	84.00 FL	*- FL
5	1		*REAR END PANEL	Dented	452.00 FL	*452.00 FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	178.00 FL	*178.00 FL
7	1		*REAR END PANEL AIR VENT	Not Necessary	75.00 FL	*- FL
8	2		*REAR END PANEL SIDE GARNISH	Deformed	58.00 FL	*58.00 FL
9	1		*TAIL LAMP-RH	Cracked	295.00 FL	*295.00 FL
10	1		*TAIL LAMP PANEL-RH	Dented	95.00 FL	*95.00 FL
11	1		*BOOTLID	Buckled	828.00 FL	*828.00 FL
12	1		*BOOTLID LOCK	Not Necessary	206.00 FL	*- FL
13	1		*BOOTLID WEATHERSTRIPE	Cut	177.00 FL	*177.00 FL
14	1		*MITSUBISHI LOGO	Necessary	42.00 FL	*42.00 FL
15	1		*ATTRAGE EMBLEM	Necessary	45.00 FL	*45.00 FL
16	1		*MIVEC EMBLEM	Necessary	65.00 FL	*65.00 FL
17	1		*CYCLE AND CARRIAGE LOGO	Necessary	54.00 FL	*54.00 FL
18	1		*REAR FENDER-RH	Repair	923.00 FL	*- FL
19	1		*REAR FENDER INNER TRIM-RH	Not Necessary	308.00 FL	*- FL
20	1		*SET REAR FENDER INNER TRIM CLIPS-RH	Necessary	30.00 FL	*30.00 FL
21	1		*REAR WINDSCREEN MOULDING	Not Necessary	105.00 FL	*- FL
22	1		*SPARE TYRE PANEL TOP BOARD	Torn	222.00 FL	*222.00 FL
23	1		*REAR EXHAUST PIPE	Not Necessary	597.00 FL	*- FL
24	1		*REAR EXHAUST MOUNTING	Not Necessary	48.00 FL	*- FL
25	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
26	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,135.00	3,649.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	573.50	338.90
Total Parts (\$\$)	5,561.50	3,310.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,600.00	1,100.00
2	TO PUTTY AND SPRAY UP PAINT WORKS	New	1,400.00	1,100.00
3	TO CHECK WIRING SYSTEM	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO REMOVE EXHAUST PIPE	New	150.00	0.00
7	TO REMOVE REAR WINDSCREEN	New	180.00	0.00
8	TO REMOVE FUEL TANK	New	150.00	0.00
Gross Labour Cost (S\$)			3,780.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >