



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2004561  
INV Date 25/06/2020  
Reference CC6/FCI20000154/Uda3q2  
Code FCI2



### PROFESSIONAL SERVICE FEE

Vehicle No. FBF 3207X  
Insured Veh. SHC 7337Y  
Claim No. D19007922MFSH/1  
Policy No. D-18088937MFSH  
Accident Date 12/12/2019  
Inspection Date 03/01/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC6/FCI20000154/Uda3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-06-2020		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 7337Y	Veh. Inspected	FBF 3207X	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D19007922MFSH/1	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	03/01/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA FZ 16	c.c	153	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	ME121C05YA2020959	Colour	BLACK	
Odometer	82959	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	110-70-17	METZELER	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140-70-17	METZELER	6 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/12/2019	Inspection Date	03/01/2020	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 3207X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	HANDLE BAR	SERVICEABLE	180.00	-
1	BRAKE LEVER	SCRATCHED	48.00	48.00
1	FUEL TANK COVER RH	TO REPAIR SEE LABOUR	105.00	-
1	SIDE COVER RH	TO REPAIR SEE LABOUR	88.00	-
1	BRAKE PEDAL	BENT	58.00	58.00
2	FOOTREST FRONT @\$35.00	O/S CUT	70.00	35.00
2	FOOTREST REAR @\$30.00	O/S TORN	60.00	30.00
1	REAR TAILBOARD RH	CRACKED	80.00	80.00
1	RIGHT FOOTREST BRACKET	BENT	102.00	102.00
	LESS 10% DISCOUNT		-79.10	-35.30
			711.90	317.70
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET BAR END (SN)	TWISTED	110.00	110.00
1	SET YOSHUMURA PIPE TITANIUM BLUE (SN)	DENTED	1,500.00	1,200.00
1	SET BOX AND RACK (SN)	CUT	900.00	480.00
			2,510.00	1,790.00
<b><u>LABOUR</u></b>				
	TO KNOCK ,REPAIR ,JACK BODY FRAME AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF FUEL TANK COVER RH AND SIDE COVER RH .		1,300.00	300.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		600.00	200.00
	TO CHECK WIRING .	NOT NECESSARY	30.00	-
	TO PRESS AND ALIGHTMENT FRONT FORK .	NOT NECESSARY	280.00	-
			-	-
			-	-
			-	-
			2,210.00	500.00
<b>GRAND TOTAL</b>			<b>5,431.90</b>	<b>2,607.70</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	----------

Report Ref No. CC6/FCI20000154/Uda3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 3207X

INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 3207X

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 3207X

RE-INSPECTION

