



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005477
INV Date 11/08/2020
Reference CC4/FCI20000163/Uda3n2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMD 7107E
Insured Veh. SHD 7217E
Claim No. D19008065MFSH
Policy No. D-19092580MFSH
Accident Date 20/12/2019
Inspection Date 06/01/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20000163/Uda3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 11-08-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 7217E	Veh. Inspected	SMD 7107E
Policy No.	D-19092580MFSH	Coverage (\$)	0.00
Claim No.	D19008065MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	30/12/2019

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN SCIROCCO (A)	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WVWZZZ13ZBV002178	Colour	WHITE
Odometer	103155	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40Z R18	MICHELIN	6 mm
L/H Front Tyre	225/40Z R18	MICHELIN	6 mm
R/H Rear Tyre	225/40Z R18	MICHELIN	6 mm
L/H Rear Tyre	225/40Z R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/12/2019	Inspection Date	06/01/2020
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 7107E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,144.50	1,144.50
1	REAR BUMPER RETAINER RH	NOT NECESSARY	45.60	-
1	REAR BUMPER RETAINER LH	NOT NECESSARY	45.60	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	465.00	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	47.85	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	47.85	-
1	END PANEL TOP GARNISH	NOT NECESSARY	1,125.75	-
1	REAR NUMBER LAMP RH	NOT NECESSARY	36.55	-
1	REAR NUMBER LAMP LH	NOT NECESSARY	36.55	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,256.00	-
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	35.25	-
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	35.25	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	412.00	-
1	HEADLAMP RH	NOT NECESSARY	634.00	-
1	HEADLAMP LH	NOT NECESSARY	634.00	-
1	SUPPORT PANEL	NOT NECESSARY	1,056.75	-
1	FRONT SPONGE	DAMAGED	225.75	225.75
	LESS 5% DISCOUNT		-	-68.51
			7,284.25	1,301.74
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE HOLDER (SN)	SCRATCHED	30.00	20.00
1	REAR NUMBER PLATE (SN)	SCRATCHED	30.00	20.00
1	REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	END PANEL (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	FRONT NUMBER PLATE (SN)	SCRATCHED	30.00	20.00
1	FRONT NUMBER PLATE HOLDER (SN)	SCRATCHED	30.00	20.00
			400.00	80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS (REAR).INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		400.00	300.00
	SPRAY PAINT ON THE AFFECTED AREAS (REAR).		500.00	400.00
	ANTI-RUST COATING (REAR).	NOT NECESSARY	60.00	-
	TO REMOVE & REFIT REVERSE SENSOR .		150.00	50.00
	LABOUR TO REMOVE & REFIT NECESSARY PARTS (FRONT).INCLUSIVE OF THE REPAIR OF FRONT BUMPER,FRONT BUMPER REINFORCEMENT AND END PANEL.		500.00	280.00
	SPRAY PAINT ON THE AFFECTED AREAS (FRONT).		500.00	200.00
	ANTI-RUST COATING (FRONT).	NOT NECESSARY	60.00	-
	WIRING (FRONT).		80.00	20.00
			2,250.00	1,250.00
GRAND TOTAL			9,934.25	2,631.74

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	-----------------

Report Ref No. CC4/FCI20000163/Uda3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMD 7107E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMD 7107E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMD 7107E

RE-INSPECTION

