55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 23937

Telefax

Estimate : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference: PA/OD/1518/2019/NS

Date : 26-Dec-19

Vehicle NOT IN Workshop. Kindly Arrange For Survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Liu Leming

Address : Blk 28 Duchess Road

#02-09

Singapore 269030

Telephone : HP +65 98635418

Type of Claim : Own Damage Claims

Policy No. : 1900142169

Vehicle No : SKD 1988 S

Model Code : Audi A3 Sedan 1.0 TFSI 8V

Model / Year : Jul-19

Engine No : CHZ C31258

Chassis No : WAUZZZ8V3KA096069

Mileage : -

Date In : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 22-Dec-19

Place of Accident : 28 Duchess Road The Tresor

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 1988 S

S/N	Nature of Jobs	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function.	S/N	\$	280.00	✓·
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N	\$	600.00	/
3	To install rear windscreen solar film.	S/N	\$	400.00	/
4	To remove and transfer rhs rear door's multi-lock system and power window devices. Check function and renew if necessary.	S/N	\$	280.00	/
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$	1,400.00	/
	SUB TOTAL LABOUR CHARGES	:	\$	2,960.00	- =

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 1988 S

S/N	Nature of Jobs		 Estimated Charges	Surveyor's Recommendations
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	
7	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender. To renew rhs rear door and rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 6,300.00	3000
8	To respray rear bumper, rhs rear door, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	_	\$ 2 85 5 5,600.0 0	5 x 550 = 2750 Hundle : 100
9	To renew rhs rear rim and carry out wheel alignmen	S/N	\$ 280.00	/
10	To carry out diagnostic check.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 16,732.00	-

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 1988 S

S/N	Parts Description			<u>Damage Parts & Prices</u> S/NETT REMARKS		
3/14	raits bescription	-	-	3/NETT REMARKS		
1	REAR BUMPER Repris		\$	1,793.00 🗶		
2	REAR BUMPER STICKY PAD 7	4	\$	د 21.00		
3	REAR BUMPER FIXING PARTS		\$	175.00 ~		
4	WHEEL HOUSING LINER ADAPTER - RH 2		\$	34.00 +		
5	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	30.00 *		
6	REAR BUMPER LOCKING MECHANISM	2	\$	53.00+		
7	DEAD DUMABED COCKIED III	Not Nec	\$	216.00 *		
8	REAR LIGHT REFLECTOR - RH		\$	38.00 *		
9	REAR BUMPER GUIDE SECTION - RH		\$	60.00 *		
10	SIDE PANEL - RH Dended.		\$	2,110.00		
11	REAR WINDSCREEN 2		\$	742.00 ~		
12	PRIMER NCC		\$	19.00 —		
13	SIDE WINDOW - RH		\$	520.00		
14	REAR WHEEL HOUSING LINER - RH	ec	\$	223.00 🐣		
15	REAR WHEEL HOUSING LINER ATTACHMENT	PARTS NEL	\$	81.00 🛂		
16	REAR DOOR - RH Devted		\$	2,279.00		
17	REAR DOOR OUTER SEAL New	NEC	\$	146.00 🗸		
18	BONDING AGENT	NEC	\$	45.00		
19	CLEANING SOLUTION	NEC	\$	65.00 ?		
20	REAR DOOR ATTACHMENT PARTS ?		\$	117.00		
	SUB TOTAL SPARE PARTS		\$	8,767.00		
	JUD TOTAL STAIL LAILIS	•, :	~	0,707.00		

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 1988 S

			Damage Parts & Prices		
S/N	Parts Description_		S/NETT	REMARKS	
21	REAR DOOR CATCH ME N		\$ 85.00 <i>'</i>	+	
22	C-PILLAR REINFORCEMENT - RH LOWER ?		\$ 176.00	? .	
23	REAR ALUMINIUM RIM - RH LA		\$ 666.00		
24	ALUMINIUM RIM RUBBER VALVE N N	4	\$ ر 13.00	<	
25	ACRYLIC SEALANT	S/N	\$ 180.00	✓	
26	CAVITY WAX	S/N	\$ 140.00		
27	STONE CHIP	S/N	\$ 180.00		
28	METAL FILLER POWDER	S/N	\$ 280.00		
29	REAR WINDSCREEN SEALANT / /	S/N	\$ 200.00	V	
30	1/4 GLASS SEALANT	S/N	\$ 100.00		
31	SUNDRIES ?		\$ 400.00	?	
	TOTAL SPARE PARTS	:	\$ 11,187.00		
	TOTAL LABOUR CHARGES	:	\$ 16,732.00		
	GRAND TOTAL	:	\$ 27,919.00		

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Authorised Date

Surveyed Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

He Authorsed, # 13 Days.

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant