

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-174

Date : 26/12/2019

Vehicle Num. : SLM6565L

Make/Model : BMW X6-2012

Chassis/Eng# : WBAFG22050L596572/09448036N551

Accident Date : 21/12/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 pc	LIST ITEMS :		
2.	1 pc	Rear Door LH <i>Dented</i>		2,527.20 ✓
3.	1 pc	Rear Door Mechanism Lock LH <i>new</i>	2785.20	798.00 *
4.	1 pc	Rear Door Weatherstrip LH <i>new</i>		258.00 ✓
4.	1 pc	Rear Fender Guard LH <i>Repair</i>	2645.94	980.50 +
List Total S\$:				4,563.70
5.00% Discount S\$:				228.19
				4,335.51

1.	1 pc	SPECIAL NETT ITEMS :		
2.	1 pc	Rear Door Guard LH <i>Repair</i>		1,018.00 *
		Side Rocker Skirt LH <i>Repair</i>		785.00 *
Special Nett Total S\$:				1,803.00
LABOUR :				
To remove, rearrange electrical wirings, check lighting				120.00 30
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				1,200.00 400
To putty and respray painting on affected area.				1,200.00 600
Labour Total S\$:				2,520.00

Total S\$: 8,658.51

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim
H/S 03/01/20
03 Rep.
Total: 3675.94
H/S: 28/1/20