

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24775

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1546/2019/NS
Date	:	2-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Sng Yu Lin Melissa
Address	:	63A Still Road Singapore 424009
Telephone	:	(HP) +65 98336446
Type of Claim	:	Own Damage Claims
Policy No.	:	1900106948
Vehicle No	:	SJB 20 M
Model Code	:	Audi A5 SB 2.0 TFS
Model / Year	:	20/6/2019
Engine No	:	CVK 082484
Chassis No	:	WAUZZZF52KA052826
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Alian Wu
Accident Date	:	31-Dec-19
Place of Accident	:	Parkway East Hospital

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJB 20 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 1250 ✓	
3	To respray front bumper and rhs front fender.	\$ 2,500.00 1100 ✓	
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 *	
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u><u>6,252.00</u></u>	

premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 20 M

S/N	Parts Description		S/Nett	Damaged Parts & Prices	
				S/Nett	Remarks
1	FRONT BUMPER <i>Delud</i>	\$	2,073.00	✓	1658.40
2	FRONT BUMPER FIXING PARTS	\$	368.00	+	
3	FRONT BUMPER SECURING STRIP	2 \$	64.00	✓	
4	FRONT BUMPER GRILLE - CENTRE	\$	178.00	✓	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	207.00	+	
6	FRONT BUMPER SPOILER <i>new</i>	\$	489.00	+	
7	FRONT BUMPER AIR GUIDE - RH <i>new</i>	\$	56.00	+	
8	RADIATOR GRILLE COVER - UPPER	\$	2,131.00	+	
9	FRONT BUMPER AIR GUIDE GRILLE - RH <i>3 new</i>	\$	431.00	+	
10	FRONT BUMPER CARRIER <i>new</i>	\$	733.00	+	
11	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$	113.00	+	
12	FRONT BUMPER COVER <i>new</i>	\$	116.00	+	
13	FRONT BUMPER GUIDE SECTION - RH <i>2H new</i>	\$	33.00	?	+
14	CAUTION SIGN STICKER	NEC \$	13.00	+	
15	AIRCON STICKER	NEC \$	7.00	+	
16	LOCK CARRIER BRACKET	\$	125.00	+	
17	FRONT BUMPER SUPPORT - LH / RH	2 \$	52.00	+	
18	FRONT PARKING AID SENSOR - OUTER / INNER	2 \$	462.00	+	
19	FRONT PARKING AID SEAL RING	4 \$	12.00	+	
20	HORN - RH LOW TONE <i>Not new</i>	\$	262.00	?	+
SUB TOTAL SPARE PARTS			:	\$	7,925.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 20 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	SPRING SHACKLE - RH <i>Ne m</i>	\$ 26.00	+
22	FRONT FENDER - RH <i>Dented</i>	\$ 968.00	✓ 774.40
23	FRONT FENDER ATTACHMENT PARTS <i>?</i>	\$ 48.00	+
24	FRONT FENDER CLOSING ELEMENT - RH <i>Ne m</i>	\$ 68.00	+
25	FRONT FENDER BRACKET - RH <i>3</i>	\$ 32.00	x
26	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>Ne m</i>	\$ 45.00	+
27	FRONT FENDER TRIM - RH <i>Ne m</i>	\$ 145.00	✓ 116
28	FRONT WHEEL HOUSING LINER - RH <i>?</i>	\$ 256.00	+
29	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Ne m</i>	\$ 82.00	+
30	WHEEL SPOILER - RH <i>cracked</i>	\$ 66.00	✓ 55.04
31	WHEEL SPOILER TRIM - RH <i>Not Nec</i>	\$ 33.00	+
32	WHEEL SPOILER TRIM BRACKET - RH <i>Not Nec</i>	\$ 22.00	+
33	STONE CHIP GUARD - RH <i>Ne m</i>	\$ 46.00	✓ 36.80
34	REAR FENDER LEDGE COVER - RH <i>Front</i>	S/N \$ 32.00	? x
35	FRONT FENDER LEDGE COVER - RH <i>Ne m</i>	\$ 14.00	? x
36	LED HEADLIGHT - RH <i>cut</i>	\$ 7,204.00	✓ 5763.20
37	LIFT CYLINDER - RH <i>Ne m</i>	\$ 181.00	? x
38	LIFT CYLINDER BRACKET - RH <i>Ne m</i>	\$ 13.00	+
39	HEADLIGHT CORRUGATED PIPE <i>?</i>	\$ 78.00	+
40	HEADLIGHT SPRING CLIP <i>Ne m</i>	\$ 23.00	+
41	FRONT ALUMINIUM RIM - RH <i>?</i>	\$ 943.00	+
42	ALUMINIUM RIM RUBBER VALVE <i>Ne m</i>	4 \$ 13.00	+
43	FRONT NO PLATE <i>Ne m</i>	S/N \$ 60.00	x 85.60
44	SUNDRIES <i>Ne m</i>	\$ 300.00	? 12.00

TOTAL SPARE PARTS

TOTAL LABOUR CHARGES

GRAND TOTAL

: \$ 18,623.00
: \$ 6,252.00
: \$ 24,875.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 03/01/20.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1546/2019/NS

10-Jan-20

Glory Tan

1 of 1

SJB 20 M

Audi A5 SB 2.0 TFS

Quantity	Description
----------	-------------

Parts

1

Front fender brace RHS

Revt

Unit Price	Amount
------------	--------

\$ 107.00	✓
-----------	---

TOTAL

\$ 107.00

For Premium Automobiles Pte Ltd

Authorised Signature

86/5
Adrian Ling
10/01/20

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24775

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1546/2019/NS
Date : 2-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

5 days - ok - Jy - 30 Mar 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Sng Yu Lin Melissa
Address : 63A Still Road
Singapore 424009
Telephone : (HP) +65 98336446
Type of Claim : Own Damage Claims
Policy No. : 1900106948
Vehicle No : **SJB 20 M**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 20/6/2019
Engine No : CVK 082484
Chassis No : WAUZZZF52KA052826
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 31-Dec-19
Place of Accident : Parkway East Hospital

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJB 20 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's ecommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	2,800.00	\$ 1,250.00
3	To respray front bumper and rhs front fender.	\$	2,500.00	\$ 1,100.00
4	To renew rhs front rim and carry out wheel alignment.	S/N \$	280.00	
5	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 6,252.00	\$ 3,022.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 20 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,073.00	\$ 1,658.40
2	FRONT BUMPER FIXING PARTS	\$ 368.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 64.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 178.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	
6	FRONT BUMPER SPOILER	\$ 489.00	
7	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	
8	RADIATOR GRILLE COVER - UPPER	\$ 2,131.00	
9	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 431.00	
10	FRONT BUMPER CARRIER	\$ 733.00	
11	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	
12	FRONT BUMPER COVER	\$ 116.00	
13	FRONT BUMPER GUIDE SECTION - RH	\$ 33.00	
14	CAUTION SIGN STICKER	NEC \$ 13.00	
15	AIRCON STICKER	NEC \$ 7.00	
16	LOCK CARRIER BRACKET	\$ 125.00	
17	FRONT BUMPER SUPPORT - LH / RH	2 \$ 52.00	
18	FRONT PARKING AID SENSOR - OUTER / INNER	2 \$ 462.00	
19	FRONT PARKING AID SEAL RING	4 \$ 12.00	
20	HORN - RH LOW TONE	\$ 262.00	
SUB TOTAL SPARE PARTS		: \$ 7,925.00	\$ 1,658.40

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 20 M

S/N	Parts Description	c/f	Damaged Parts & Prices		Remarks
			S/Nett	\$	
21	SPRING SHACKLE - RH		\$	26.00	
22	FRONT FENDER - RH		\$	968.00	\$ 774.40
23	FRONT FENDER ATTACHMENT PARTS		\$	48.00	
24	FRONT FENDER CLOSING ELEMENT - RH		\$	68.00	
25	FRONT FENDER BRACKET - RH	3	\$	32.00	
26	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH		\$	45.00	
27	FRONT FENDER TRIM - RH		\$	145.00	\$ 116.00
28	FRONT WHEEL HOUSING LINER - RH		\$	256.00	
29	WHEEL HOUSING LINER ATTACHMENT PARTS		\$	82.00	
30	WHEEL SPOILER - RH		\$	66.00	\$ 55.04
31	WHEEL SPOILER TRIM - RH		\$	33.00	
32	WHEEL SPOILER TRIM BRACKET - RH		\$	22.00	
33	STONE CHIP GUARD - RH		\$	46.00	\$ 36.80
34	REAR FENDER LEDGE COVER - RH	S/N	\$	32.00	
35	FRONT FENDER LEDGE COVER - RH		\$	14.00	
36	LED HEADLIGHT - RH		\$	7,204.00	\$ 5,763.20
37	LIFT CYLINDER - RH		\$	181.00	
38	LIFT CYLINDER BRACKET - RH		\$	13.00	
39	HEADLIGHT CORRUGATED PIPE		\$	78.00	
40	HEADLIGHT SPRING CLIP		\$	23.00	
41	FRONT ALUMINIUM RIM - RH		\$	943.00	
42	ALUMINIUM RIM RUBBER VALVE	4	\$	13.00	
43	FRONT NO PLATE	S/N	\$	60.00	
44	SUPPLEMENTARY		\$	107.00	\$ 85.60
45	SUNDRIES		\$	300.00	\$ 12.00
TOTAL SPARE PARTS			:	\$ 18,730.00	\$ 8,501.44
TOTAL LABOUR CHARGES			:	\$ 6,252.00	\$ 3,022.00
GRAND TOTAL			:	\$ 24,982.00	\$ 11,523.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1546/2019/NS 10-Jan-20 Glory Tan 1 of 1 SJB 20 M Audi A5 SB 2.0 TFS
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Front fender brace RHS	\$ 107.00	\$ 85.60
TOTAL		\$ 107.00	\$ 85.60

For Premium Automobiles Pte Ltd

Authorised Signature